

Douglas County Surveyor's Record of  
Government Corners Renewed

27 T. S. 3 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

James W. Byron, Dep. County Surveyor  
M. Godfrey  
S. Bilow  
Oct., 1957  
C. S. File No. 49/14

James W. Byron, Deputy  
M. Godfrey  
S. Bilow  
May 5, 1958  
C. S. File No. 49/14

46

Section Corner Common to Sections 20, 21, 28, & 29.

Found - Original 12" now 30" R. Fir S.53°E. 22.4 ft. Old bark scribe "BT". Shows old face above. I do not open. All other BTs. gone. I also find old rotted stake at corner, maybe Original.

Set Brass Cap at corner marked County Surveyor's Office  $\frac{S20}{S29} | \frac{S21}{S28} T27S R3W$  1957

New BTs.: 5" Hemlock bears N.66°W., 5.4 ft. scribed S20 CS BT.  
8" R. Fir bears S.45°W., 11.2 ft. scribed S29 T27S R3W CS BT.  
10" Hemlock bears N.20½°E. 18.2 ft. scribed S21 T27S R3W CS BT.  
Oct. 15, 1957

47

Section Corner Common to Sections 7, 8, 18, 17.

Found - The four BTs as Boyer recorded in 1943, except the original 10" now 30" Cedar I find should be N.63°W., 9.2 ft record N.63°W., 5.3 ft. ~~RENEWED~~

Set Brass Cap at Corner marked County Surveyor's Office, 1957.  $\frac{S7}{S18} | \frac{S8}{S17} T27S R3W$  #130

do not scribe or rescribe New BTs. Oct. 14, 1957

Section Corner Common to Sections 21, 22, 28, & 27.

Found-Original 20" now 36" Fir N.10°W. 24.4 ft. Shows real old axe marks and old blaze that shows bark scribing "1" and ½ B thus "D".

I also find base of rotted Fir stump that checks bearing and distance and size for original S.45°W. 4.0 ft. BT. #152

I also find depression in ground at record distance and bearing of original S. E. BT.

I can find no trace of original N. E. BT.

Set Brass cap at corner marked T27S R3W County Surveyor's Office, 1957  $\frac{S21}{S28} | \frac{S22}{S27} T27S R3W$

New BTs.: 10" Cedar bears S.15°E., 59.2 ft. scribed S27 T27S R3W CS BT.  
36" R. Fir bears S.75°W., 5.0 ft. bark scribed S28 T27S R3W CS BT.  
14" Sugar Pine bears N.26°W., 14.2 ft. scribed T27S R3W S21 CS BT.  
12" Cedar bears N.70°E. 60.2 ft. scribed T27S R3W S22 CS BT.  
Oct. 11, 1957

49

½ Section Corner to Sections 20 & 21.

Found - Orig. 12"; now 20" Laurel N.52°W. 50.2 ft., has open face, good scribing "S".

Shell of 5' Cedar bears S.70°W. 7 ft. This may have been Orig. BT., badly burned, no scribing found.

Set Brass Cap at Corner Mkd:  $\frac{S20}{S21} \frac{1}{2}$  County Surveyor's Office, 1958.

New BT's: 16" R. Fir bears S.74°W. 58.0 ft. scribed ½ S20 CS BT.  
16" R. Fir bears S.67°E. 21.4 ft. scribed ½ S21 CS BT.

50

Section Corner common to Sections 16, 17, 20, 21.

Found - Orig. 12" Chinquapin N. 18", has partly open face, good scribing visible, "BT".

Rotted Stumps that checks bearing & distances for Orig. S. E., N. W. & S. W. BT's., no scribing found.

Set Brass Cap at Corner Mkd:  $\frac{S17}{S20} | \frac{S16}{S21} T27S R3W$  County Surveyor's Office, 1958

New BT's: 14" Hemlock bears S.71°E. 25.6 ft. scribed S21 T27S R3W CS BT.  
30" R. Fir bears S.83°W. 27.3 ft. scribed S20 T27S R3W CS BT.  
8" Cedar bears N.30°W. 23.7 ft. scribed S17 T27S R3W CS BT.  
22" Cedar bears N.88°E. 46.8 ft. scribed S16 T27S R3W CS BT.