

Douglas County Surveyor's Record of
Government Corners Renewed

T. 27 S. T. S. R. 3 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

James W. Byron, Deputy County Surveyor
John Powell and Wm. Stoffel
August and September 1962
C. S. File No. 49/28

Renew Corner to S35/S36 T27S R3W T28S 75
Found - Orig. 14", now 17" Laurel, shows good scribing, T27S R3W.
No other Orig. BT's. found.
Also find $\frac{3}{4}$ " Iron Rod at Cor. & a $\frac{3}{4}$ " Iron Rod. 9.2 ft. East
which is record for C.C. S2/S1
New BT's: 8" R.Fir bears N.82°E. 19.7 ft. scribed S36 CS BT.
15" R.Fir bears N.79°W. 55.0 ft. scribed S35 T28S R3W CS BT.
Note - We find 48" R.Fir bears N.61°E. 52.7 ft., shows good bark
scribing, T27S R3W. This BT. may have been scribed for
C. C. S2/S1 T28S, but is not of record.

South $\frac{1}{4}$ Corner of Section 35. 76
Found - Orig. 18" Fir N.65°W. 42.9 ft., shows good bark scribing.
Orig. 72", now 90" Fir S.85°E. 67.0 ft., not 72.6 ft. "Dead".
Also find $\frac{3}{4}$ " Iron bears East 13.6 ft. May have been set for North
 $\frac{1}{4}$ Corner Section 2.
New BT's: Rescribe, now 40" R.Fir N.65°W. 45.9 ft. $\frac{1}{4}$ S35 CS BT.
9" Laurel bears S.85°E. 21.4 ft. scribed $\frac{1}{4}$ S CS BT.

Closing Corner Sections 30 and 31, T27-2W. 77
Found - 30" Fir Stump S.75°E. 19.1 ft., good scribing visible on old face.
36" Fir Stump, uprooted, N.50°E. 18.5 ft., scribing visible.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962 T27S R2W C.S.

S30
S31

A $1\frac{1}{2}$ " Iron Pipe bears N.80°E. 1.1 feet.
Scribed 36" Fir Stump S.18°E. 59.4 ft. Mkd: T27S R2W S31 CS BT.
Note - In Clean Cut Area. No trees available.
Corner lies approx. 50 ft. North of a timber access road.

South $\frac{1}{4}$ Corner to Section 32. 78
Found - Orig. 18", now 22" Laurel S.50°E. 7.9 ft., not 83.2 ft., shows
good scribing $\frac{1}{4}$ ". Orig. 20", now 24" Laurel N.20°E. 13.9 ft.
We open but old face rotted, no scribing found.
Note - We find S.E. BT. dist. should be 12 lks. not 126 lks., as this
area has a great number of old Laurel & Fir trees that would have
been close to corner had the distance been as recorded.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
South $\frac{1}{4}$ S32 T27S R3W.
New BT's: 7" Fir bears N.27°E. 23.4 ft. scribed S $\frac{1}{4}$ S32 CS BT.
28" Laurel bears N.52°W. 24.5 ft. scribed S $\frac{1}{4}$ S32 CS BT.

Renew Corner S33/S34 T27S R3W T28S 79
Found - $\frac{3}{4}$ " Iron Rod at Cor. Orig. 30", now 50" Cedar S.30°W. 13.9 ft.,
shows good old bark scribing.
Orig. 8", now 15" Laurel N.35°E. 58.7 ft. Face rotted.
Also find Stump Hole for N. W. Bearing Tree.
New BT's: 8" Chinquipin bears N.62°E. 13.7 ft. scribed T27S R3W S34 CS BT.
14" Laurel bears N.7°W. 50.0 ft. scribed T27S R3W S33 CS BT.
Note - We also old bark scribing on now 36" R.Fir "T28S R3W S3", bears
S.27°E. 36.0 ft. I believe this tree was scribed 1882 but
not recorded.

O
V
E
R