

Douglas County Surveyor's Record of
Government Corners Renewed

T. 27 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97401

T. E. Shrum, Jr.
For U.S. Fly.
Map File
M 29-29

Center $\frac{1}{4}$ Corner to Section 11.
Found - 1" diam., Iron Pipe - See Ren. #34.
D. Fir 36" diam., S. 52° E. 7.8 ft.
Yew 8" diam., N. 10° E. 15.5 ft.

FAOK By W. ROGERS
5/99 1999-0052

CORNER REPORT
CS 43/34
2/11/86
FAOK BY
BEITZ 3/95
Vol 18 PG 41
98
Dec. 1964

99

$\frac{1}{4}$ Corner to Sec. 6, T27-3 and Sec. 31, T26-3.
Found - 1 $\frac{1}{4}$ " O.D. I. Pipe at Fence Corner as recorded Ren. #12-A, by BBI.
18", now 26", D. Fir N. 31 $\frac{1}{2}$ ° E. 66.0 ft. (face), shows very
good upper & lower scars. We do not open.
Stump Hole to S. E., probably other BT.
New BT: 6" D. Fir S. 58° W. 16.5 ft. Mkd: $\frac{1}{4}$ S6 CS BT.
Note - This corner lies at fence corner with fences S. - E. & W. and
40 feet west of creek, course North.

100

Sec. Cor. to Secs. 4 & 5, T27-3 & Secs. 32 & 33, T26-3.
Found - 1958 Cadastral Brass Cap Mkd. for Sec. Cor. with $\frac{3}{4}$ " I. Rod
alongside & set in Mound of Stone.
All CS BT's., as recorded in Ren. #46, T26-3W, are stumps or snags.
6" Cedar N. 85 $\frac{1}{2}$ ° E. 47.5 ft., now snag, shows scribing.
16" Cedar S. 14° E. 62.0 ft. Alive & health, scribing visible.
17" Cedar S. 13 $\frac{1}{2}$ ° W., 58.1 ft. Alive, scrbing. vis. on partially healed
22" Cedar N. 84° W. 220.4 ft., turned out, scribe visible. / face.
Orig. Laurel to S.E. & Oak to S. W. still alive.

New BT's: 10" W. Oak N. 53° E. 53.9 ft. Mkd: T26S R3W S33 CS BT.
7" Cedar N. 83° W. 159.8 ft. Mkd: T26S R3W S32 CS BT.
Feb. 11, 1966

101

$\frac{1}{4}$ Corner to Sec. 4, T27-3 & Sec. 33, T26-3.
Found - 1958 Cad. Brass Cap mkd. for $\frac{1}{4}$ corner.
60" D. Fir N. 74 $\frac{3}{4}$ ° W. 101.0 ft. Alive, scribe vis., pitched face.
67" Cedar S. 48 $\frac{1}{2}$ ° W. 369.6 ft., now broken snag, 12 ft. high,
shows " $\frac{1}{4}$ S3 BT", should be "S4".
New BT: 5" Laurel S. 87° E. 119.2 ft. Mkd: $\frac{1}{4}$ S4 CS BT.
Note - This corner lies approximately 100 ft. east of bottom of
small draw, course N.

102

West $\frac{1}{16}$ for Sec. 3, T27-3 & Sec. 34, T26-3W.
Found - 1958 Cadastral Brass Cap Mkd: for $\frac{1}{16}$ th corner. (See note)
6" Cedar S. 32° W. 25.1 ft. Slash piled on backside of tree,
scribing visible, but tree appear to be dying.
8" D. Fir S. 25 $\frac{1}{2}$ ° E. 9.9 ft., blaze nearly healed over. Alive, good
New BT: " Cedar N. 24° W. 35.0 ft. Mkd: W $\frac{1}{16}$ S34 CS BT. /condition.
Note - This corner lies on steep, east slope, Brass Cap just
below large root of Fir Tree.

103

Sec. Cor. to Secs. 4 & 3, T27-3 & Secs. 33 & 34, T26-3.
Found - 1958 Cadastral Brass Cap mkd. for section corner.
13" Cedar N. 32 $\frac{3}{4}$ ° E. 31.0 ft. scribed T26S R3W S34 BT.-Alive.
9" D. Fir S. 47 $\frac{1}{2}$ ° E. 9.9 ft. scribe visible on pitched face.
10" D. Fir S. 68° W. 11.2 ft., pitched & almost healed blaze.
11" D. Fir N. 45° W. 11.2 ft., down & dead, scribing visible.
New BT - 9" D. Fir N. 18 $\frac{1}{2}$ ° W. 35.5 ft. Mkd: "T26S R3W S 33 CS BT.
Note - This corner lies approximately 120 ft. East of Logging Road,
course N. E. & S. W. in young Fir, Cedar and Laurel.

Vernon "Ray" Tracy
Mike Stone & Jack Heritage
February 1966
C. S. File No. 54/7