

Douglas County Surveyor's Record of
Government Corners Renewed

T. 27. S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Milo E. Godfrey, Deputy County Surveyor
Wm. Stoffel & Mike Stone
November 1963
C. S. File No. 53/33

101
 $\frac{1}{4}$ Section Corner to Sections 21 and 28.
 Found - $\frac{1}{2}$ " Iron Pipe, extending 32" above ground. (See Ren. Cor. #49)
 15" W. Oak, Orig. BT., S.79°E. 14.5 ft., scribing still visible.
 12" D.Fir N.13 $\frac{1}{2}$ °W. 68.5 ft., blaze pitched over & nearly healed over,
 Alive & in good condition.
 Fir to the S.W. is now sawed stump, cut below scribing.
 Replace I.Pipe with Brass Cap Mkd: County Surveyor's T27S R4W $\frac{1}{4}$ S21
 Office, 1963 S28
 New BT: 18" D.Fir S.61°E. 39.2 ft., Mkd: $\frac{1}{4}$ S28 CS BT.
 Note - Orig. W. Oak to N.E. is still standing.
 Corner lies at E. end of narrow valley.

FD OK
8/87
M101-26
D. BENTZ

102
 West $\frac{1}{4}$ Corner to Section 24 only.
 Found - I.Pipe with Brass Cap set in 1917 survey.
 40" Fir S.73°E. 21.8 ft., shows very plain axe scar. Tree alive
 & in good condition.
 Stump of 40" Fir N.67°E. 36.3 ft., shows good scar. Did not open.
 New BT: 24" D.Fir S.30°E. 40.1 ft. Mkd: $\frac{1}{4}$ S24 CS BT.
 Note - Corner lies on steep N. slope approx. 150 ft. N. of ridge top.

103
 East $\frac{1}{4}$ Corner to Section 23 only.
 Found - 42" Fir S.60°W. 10.6 ft., cut open scar & fd. good scribing "S2".
 Tree alive & in good condition.
 Did not find Rock at Corner, lies on very steep north slope.
 Jagged remnants of Fir Stump, (uprooted tree 100 ft. downhill),
 N. 71° W. 39.6 feet.
 At Corner Drove - $\frac{3}{4}$ " Iron Pipe.
 New BT: 22" Doug. Fir N.62 $\frac{1}{2}$ °W. 52.3 ft. Mkd: $\frac{1}{4}$ S23 CS BT.
 Note - Corner is approximately 70 ft. north of W $\frac{1}{4}$ Corner to Sec. 24.

104
 Section Corner to Secs. 15 - 16 - 21 - 22.
 Found - Brass Cap set in 1958 has been bulldozed out in making
 fire trail & cannot be found, See Ren. Cor. No. 35.
 S. W. BT. marked in 1958 is down and partly burned up.
 Reset Corner from N.E. & N.W. BT's. mkd. in 1958 and from hole
 where brass cap was dragged out.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T27S R4W S16 | S15
 Office, 1963 S21 | S22
 from which:
 12" W.Oak N.80°E. 33.0 ft. (1958 BT), shows good scars.
 19" W.Oak N.56°W. 20.1 ft. (1958 BT.), shows good scars.
 New BT: 5" Madrone S.52°W. 49.5 ft. Mkd: T27S R4W S21 CS BT.
 Note - Corner is 2.5 ft. South of E. & W. fence line.

FD OK
W/83
W. RUPP
M 75-22

105
 $\frac{1}{4}$ Corner to Sections 16 and 15.
 Found - Brass Cap set in 1958. See Cor. Ren. No. 39.
 23" Fir S.76°E. 13.0 ft. is burned & dead, good scribing still visible.
 20" Fir S.76°W. 18.0 ft. is now a stump, partially burned away.
 No face nor scribing left.
 New BT's: 25" Bl.Oak N.23°W. 65.2 ft. Mkd: $\frac{1}{4}$ S16 CS BT. Tree is probably dead.
 19" Bl.Oak N.44°E. 38.5 ft. Mkd: $\frac{1}{4}$ S15 CS BT. Tree alive but hollow.
 No other live trees remain in vicinity of corner. A fire this
 past summer or early fall has killed nearly every tree within sight.

FD OK
W. RUPP
M 75-22

RE-FILED

NO. #143

106
 $\frac{1}{4}$ Corner to Sections 17 and 16.
 Found - 17" Bl.Oak S.28°E. 37.0 ft., shows 2 very plain axe scars,
 Eppstein's BT. 1920, See Cor. Ren. No. 3.
 18" Bl.Oak N.46 $\frac{1}{2}$ °W. 33.3 ft., shows 2 faint axe scar. Reblaze &
 scribe this Tree " $\frac{1}{4}$ S17 CS BT".
 28" Orig. W. Oak N.60°E. 99.0 ft., upper scar previously opened,
 probably 1920, still shows good BT. scar.
 No trace of Eppsteins' Oak Stake at Cor.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
 T27S R4W $\frac{1}{4}$ S17/S 16
 Old Bearing Trees still in good condition.