

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 27 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

107

1/4 Section Corner to Sections 4 and 9.  
Found - Dead & Rotten Bl. Oak, now 18", S.2°W. 6.6 ft., upper scar  
opened many years ago & interior rotted away. I open lower  
scar & find overgrowth of lower face with notch at bottom,  
showing good axe marks & portion of straight scribe mark,  
reverse. Most of overgrowth rotted away, center hollow. #136  
No trace of N. W. Bearing Tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963  
T27S R4W 1/4 S 4  
S 9

New BT's: 8" D. Fir N.17°E. 23.3 ft. Mkd: 1/4 S4 CS BT.

18" D. Fir S.74°E. 47.4 ft. Mkd: 1/4 S9 CSBT.

Note - An E. & W. fence line bears North 1.6 feet from corner.

108

S. W. Corner D.L.C. No. 43.

Found - 35" W.Oak S.85°W. 74.5 ft. Cut open scar & fd. good reverse.

Tree rotting badly inside nearly hollow. REN #3

28" Laurel S.40°W. 8.0 ft., old face rotted away.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963  
T27S R4W SW D.L.C. No. 43

New BT's: 11" W.Oak S.44°E. 15.5 ft. Mkd: SW DLC 43 CS BT.

7" W.Oak N.78°W. 33.8 ft. Mkd: SW DLC 43 CS BT.

Note - Corner is approx. 8' N. of E. & W. fence line in edge of  
cultivated field.

109

Most Satherly S.E. Cor. D.L.C. No. 43.

Found - 1/2" I. Pipe set in 1922, See Ren. Cor. No. 10.

Stump of 20" Fir N.28°E. 7.0 ft., cut open & found good scrng.

8" W.Oak N.57°W. 18.7 ft. (ren. record calls for N.63°W. 21.1 ft.)

Reblaze & Scribe this tree "SE DLC 43 CS BT".

New BT: 9" Maple S.50°W. 20.2 ft. Mkd: SE DLC 43 CS BT.

Note - Corner is in N. & S. Fence Line.

110

S. W. Corner D.L.C. No. 44.

Found - Pipe with Brass Cap set in 1948. See Ren. Cor. No. 24.

Both BT's, marked in 1948 are down, scrng. vis. on N.W. Tree.

New BT's: 12" D. Fir N.69°W. 30.8 ft. Mkd: SW DLC 44 CS BT.

9" D. Fir West 21.7 ft. Mkd: SW DLC 44 CS BT.

111

Most Easterly N.E. Cor. DLC No. 44.

Found - 1/2" Iron Pipe set by Stewart in 1922. See Cor. No. 9 & No. 21.

Stump of 15" W.Oak N.59°E. 36.0 ft., scribing visible "C".

No trace of either of other 2 Bearing Trees.

New BT's: 8" W.Oak S.2°W. 66.8 ft. Mkd: NE. DLC 44 CS BT.

4" B.Oak N.56°E. 29.8 ft. Mkd: DLC 44 CS BT.

112

S. E. Corner D. L. C. No. 45.

Found - Sandstone Rock at Corner - Remnants of old fences N. &

W. from Corner. See Ren. Cor. No. 23.

18" W.Oak S.49°E. 41.6 ft., shows very good axe scars.

Stump of 24" Fir N.55°W. 21.8 ft., bark scribing visible.

New BT: 12" Madrone S.64°W. 10.7 ft. Mkd: SE DLC 45 CS BT.

Note - Corner lies approximate 550 ft. South of Buckhorn Road.

113

1/4 Corner to Sec. 1, T27-4W. & Sec. 6, T27-3W.

Found - 14" White Oak Tree (in clump) N.19°E. 437.6 ft., opened  
& found good scribing "S".

Did not find Rock at Corner - No Trace of S.W. BT.

Note - Corner & Position of S.W. Tree is in cultivated field.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964.

T27S R4W 1/4 S1/S 6 R3W

Set Steel Fence Post alongside of Brass Cap.

Rescribe - 14" W.Oak N.19°E. 437.6 ft. 1/4 S6 CS BT.

New BT: 22" D. Fir N.6°W. 553.3 ft. Mkd: 1/4 S1 CS BT. This BT. is

alongside Old Road - Buckhorn Creek to Fall Creek.

Jan. 8, 1964

Milo E. Godfrey, Deputy County Surveyor  
Wm. Stoffel and Mike Stone  
November 1963  
C. S. File No. 53/33

FD. OK  
M101-26  
D. BEATZ

FD. OK  
M101-26  
D. BEATZ

RE-RENEWED, SEE CORNER NO. #136

RE-RENEWED, SEE CORNER NO. #150