

Douglas County Surveyor's Record of
Government Corners Renewed

27 T. S. 4 R. W. W. M.

N.E. Richardson
Roy Strader
Mar. 22, 1938
C.S. 15/14

CORNER SECTION BETWEEN 4, 5, 8, and 9.
Located from old B.T. and Iron Bar set by Cole. Marked
new trees as follows REN. #2
White Oak 18" dia. bears N.20°E., 28.4 ft. marked
S. 4 C.S. B.T.
Black Oak 10" dia. bears N.59½°E., 48 ft. marked
S. 4 C.S. B.T.
White Oak 8" dia. bears N.81°W., 179.9 ft. marked
S. 5 C.S. B.T.

22

B. B. Irving
Wit.
R.L. Irving
G.A. Lindbloom
June 30, 1939
C.S. 53/59

S.E. CORNER OF THE WM. A. WILLIS D.L.C. # 45
This corner is a 6" x 14" x 6" above the ground Sand-
stone. The original bearing trees have been chopped out
and scribe marks are no longer legible. I blazed and
scribed the following trees
A Fir 24" dia. bears N.55°W., 33 lks. S.E. D.L.C. 45
C.S.B.T.
A White Oak 12" dia. bears S.49°E., 63 lks. S.E.
D.L.C. 45 C.S.B.T.

23

R. M. Darby
Richardson
R.G. Irving
6-2-48
M11-55

SW COR. D.L.C.#44
Set 1" iron pipe with a brass cap, mkd. Co. Surveyors Office S
SW cor. C. 44. Marked B. T's.
7" Fir N 70° 30' W 12.7 ft., mkd. SW C 44 CS BT.
6" Fir, S 41° 30' W 7.3 ft., mkd. SW C 44 CS BT.

24

A S. E. Cor Cl 40 Set post Witness tree
Laurel 14" N 40 E 2.25 lks Old B.T.
Nov. 29, 1883

(NOT FO. FOR GODFREY
1963-C.S. 59/33)

Record Vol. 1. page 27

25

Vol. 1
Pg. 133

Cor. 116 Established New bearing trees.
12 1/2" W Oak 6" N 05° E 41 lks.
W Oak 6" S 25° W 20 lks.
Apr. 2 1889
1889
Briggs

SEE 1958 G.L.O. SURVEY
CORNER NO. # 97
E SIDE OF TOWNSHIP

26

Ext. L Cor. D.L.C. 43 Post Marked Bt.
Black Oak 24" S 83 W lks.
Aug. 9, 1894 Hayden

SEE VOL. 2, PAGE 35

HAYDEN'S RENEWALS

27

Int. L. Cor. D. L. C. 43 post marked B. T.
8" limb of fallen Maple N 13 W 77 lks.

28

James W. Byron, Dep.
County Surveyor
Ray Irving
John Fee
December, 1954.
C. S. File No. 46/122.

1/4 sec. corner to sec. 6 (T 27 S, R 4 W) and sec. 31 (T 26 S, R 4 W).
Found - Both BTs, est. 40 years ago, more or less. Check for bearings
and distances. Also found bottom of squared stake at corner. We
cut out W. O. tree and scribing good - scribed 1/4 S. Ash alive
and in good condition.
Set 3/8 inch Iron Rod at corner 12 inches below surface.
Blazed and Scribed:
15" W. O., S 36° E., 48.0 feet, 1/4 S 31, T 26 S, R 4 W., CS BT.
12" W. O., N. 30° E., 103.6 feet, 1/4 S 6, T 27 S, R 4 W., CS BT.

29

James W. Byron, Deputy
Milo Godfrey
S. A. Bilow
December 1958
C. S. File 49/130

Section Corner to Sections 23 & 26, only.
Found - Stone at Corner & Both BT's. as recorded in 1917.
S.W. BT., now Stump, shows good scribing "T27S R4W"
N.W. BT., now down, shows good scar. I do not open.
Find Brass Cap at Record Dist. & Bearing for Section Corner → 24
I do not renew this corner, No trees near. | 25
New BT's. for Section Corner 23 |
26 |
5" Laurel bears S.73°W. 14.6 ft. scribed S26 CS BT.
15" W. Fir bears N.56°W. 46.0 ft. scribed S23 T27S R4W CS BT.
42" Cedar bears S.71°W. 97.5 ft. scribed S26 T27S R4W CS BT.
Note: - I Set 3/4" Iron Rod alongside Stone At Corner | 23
26

30