

Douglas County Surveyor's Record of
Government Corners Renewed

27 T. S. 4 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

James W. Byron, Deputy
M. Godfrey
S. A. Bilow
Jan. 23, 1959
C.S. File No. 49/130

Section Corner common to Sections 29, 30, 31, & 32
Found - Orig. 7", now 16" W.Oak N.8°W. 202.0 ft., I open & find
good scribing "S30".

No trace of other Orig. BT's.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

S30	S29	T27S R4W	Note: Corner is in old E W Fence Line.
S31	S32		

New BT's: 10" B.Oak bears North 28.3 ft. scribed S30 T27S R4W CS BT.
26" R.Fir bears S.73°W. 38.8 ft. scribed S31 T27S R4W CS BT.
8" W.Oak bears N.83½°E. 48.7 ft. scribed S29 T27S R4W CS BT.
10" W.Oak bears S.12°E. 18.6 ft. scribed S32 T27S R4W CS BT.

48
FD. OK
1970 Resurvey
Mier-24 8/67
D. Deure

James W. Byron, Deputy
Milo Godfrey
S. A. Bilow
Feb. 17, 1959
C.S. File No. 49/130

¼ Section Corner to Sections 21 & 28.

Found - Both Original BT's:

Orig. 6", now 14" W.O. S.79°E. 14.5 ft., I open & find Orig. &
Boyer's rescribing. This BT now dead.

Orig. 7", now 14" dead W. Oak, record N.35°E. 34.3 ft., should be
as recorded by Boyer, N.27°E. 34.3 ft. REN #6

I also find Boyer's rescribing & Orig. Scribing.

Also find 5/8" Iron Pipe N.75°W. 10.0 ft. I move this pipe
to original position.

New BT's:

16" R. Fir bears S.33°W. 20.0 ft. scribed ¼ S28 CS BT. 101
12" R. Fir bears N.13½°W. 68.5 ft. scribed ¼ S21 CS BT.

49

March 23, 1959

¼ Section Corner to Sections 30 & 31.

Found - Orig. 18", now 22" W. Oak N.28°W. 36.3 ft. I open & find
good scribing "½S".

No trace of Orig. S.W. BT.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

½	S30	T27S R4W
	S31	

New BT's: 16" R.Fir bears N.2°W. 6.7 ft. scribed ½ S30 CS BT.
14" W.Oak bears S.48°W. 63.0 ft. " ½ S31 CS BT.

50

James W. Byron, Deputy
Milo Godfrey
S. A. Bilow
April, 1959
C.S. File No. 49/146
M 14-42

Section Corner To Sections 14 & 23.

Found - Stone at Corner as recorded & both BT's., now Stumps, 76
show good scars, do not open.

New BT's: 20" Cedar bears N. 3°W. 43.2 ft., scribed S14 T27S R4W CS BT.
30" R.Fir bears S.86°W. 27.0 ft., scribed S23 T27S R4W CS BT.

51

Section Corner to Sections 13 & 24.

Found - Brass Cap at Corner & 30" Fir Snag, shows scar, do not
open, S.63°E. 22.4 ft.

New BT: 36" Cedar bears N.89°E. 29.2 ft., scribed S13 T27S R4W CS BT.

52
FD. OK
by: B. HOLT
MAR. 1962
M 91-37

¼ Section Corner to Sections 14 & 23.

No Original BT's. found. REN #15

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959 ¼

S14
S23

T27S R4W

New BT's: 4" R. Fir bears N. 1°30'E. 40.6 ft., scribed ¼ S14 CS BT.
12" B. Oak bears S.83°W. 26.0 ft. scribed ¼ S23 CS BT.

See Note in File!!

See Map for way corners were set!!

53

Section Corner to Sections 14, 15, 22, & 23.

No Original BT's found:

Set Brass Cap at Corner Mkd:

S15	S14
S22	S23

 T27S R4W County Surveyor's
Office, 1959

New BT's: 32" Cedar N.9°E. 76.5 ft. scribed S14 T27S R4W CS BT.
40" Cedar N.43°E. 52.7 ft. scribed S14 T27S R4W CS BT.
34" B.Oak bears S.89°E. 135.4 ft. scribed S23 T27S R4W CS BT.

See Note in File!!!

See Map M 14-42 also!

54

RE-RENEWED SECTION CORNER NO. #141
RE-RENEWED SECTION CORNER NO. 130