

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 27 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91881

Milo E. Godfrey, Deputy  
Vern Tracy and Mike Stone  
January 1963  
C. S. File No. 53/33

Milo E. Godfrey, Deputy Co. Surv.  
Wm. Stoffel, Darby, Stone, Halterman  
October 1963  
C. S. File No. 53/33

1/4 Corner to Sec. 12, T27-4W. & Sec. 7, T27-3W. 75  
Found - I. Pipe with Brass Cap, pulled out of ground by uprooted tree.  
Fir Stump S.37°W. 56.8 ft., partial scribing visible (1917 BT.)  
Fir N.31°E. 45.5 ft., tree uprooted & down, scars buried in mud.  
9" Fir S.55 1/4°E. 9.2 ft., Tree uprooted (1917 BT.)  
& down, scribing visible, (1958 BT.)  
11" Fir S.25 1/2°W. 50.8 ft., tree uprooted & down, scribing visible.  
Reset Brass Cap in Original Position.  
New BT's: 16" D. Fir S.87°E. 34.1 ft. Mkd: 1/4 S7 CS BT.  
10" D. Fir N. 7°W. 38.2 ft. Mkd: 1/4 S12 CS BT.  
Brass Cap set Originally in Cadastral Resurvey of 1958.

Renewed Corner  $\frac{S14}{S23}$  S13 76  
Found - Rock set in 1917 in place, and  
Both Fir Stumps Mkd. in 1917: 32" Fir Stump S.60°W. 16.5 ft. (good scar)  
36" Fir Stump N.51°W. 7.9 ft. (good scar)  
Also found both trees Mkd. by Co. Surveyor's Office, 1959. *Ren. #51*  
20" Cedar N. 3°W. 43.2 ft., scribing still visible. *Fd. O.K. by*  
30" Fir S.86°W. 27.0 ft., scribing still visible. *B. HOLT 1982*  
Alongside Rock at Corner Set I. Pipe with Brass Cap Mkd:  
County Surveyor's Office, 1963 T27S R4W  $\frac{S14}{S23}$  S13 *M 91-37*  
Did not mark new Bearing Trees.

T27-3W 77  
West 1/4 Corner Section 30 only. (E. Line T27-4W.)  
Found - Brass Cap set in 1917.  
18" Fir Stump S.33 3/4°E. 28.4 ft. Cut open & fd. good scribing "T".  
No trace of N. E. Tree.  
New BT's: 14" D. Fir N.12°E. 72.0 ft. Mkd: 1/4 S30 CS BT.  
18" D. Fir S.20°E. 42.3 ft. Mkd: 1/4 S30 CS BT.  
Note - A 27" D. Fir (with aluminum Tag) is 2 feet south of corner.

1/4 Corner to Section 18 only, T27-3W. (E. Line T27-4W) 78  
Found - Brass Cap set in 1917 survey. *Fd. O.K. by*  
5" Cedar N.46°E. 27.7 ft., Alive & in good condition. *B. HOLT MAR. 82*  
6" Cedar S.35 1/2°E. 8.6 ft., Down & broken up. *M 91-37*  
New Tree: 5" Red Cedar S.7°E. 21.2 ft. Mkd: 1/4 S18 CS BT.

Closing Corner Sections 24 and 25. (W. line T27-3W) 79  
Found - Brass Cap set in 1917 survey, still firmly set.  
38" Fir S.31 3/4°W. 31.0 ft. Very plain axe scar visible. Tree alive.  
Dead & Rotting Fir Snag N.65°W. 47.5 ft., shows good scar.  
New BT: 40" D. Fir N.77 1/2°W. 67.8 ft. Mkd: T27S R4W CC S24 CS BT.

Sec. Cor. to Sections 19 and 30 only, T27-3W. (on E. Line T27-4W) 80  
Found - Granite(?) Rock as called for in gov't. notes. 2 notches on S. and  
4 notches on N. sides.  
36" Fir S.6 1/2°E. 28.4 ft. Has been opened previously, good scribing  
visible "T27-3W". Tree alive & in good condition.  
42" Fir N.67°E. 6.0 ft. Good axe scar visible. Did not open.  
Set - Brass Cap alongside Rock Mkd: County Surveyor's T27S R4W  $\frac{S19}{S30}$  R3W  
Office, 1963

T27S 81  
Corner to R4W  $\frac{S36/S31}{S6}$  R3W  
T28S  
Found - Wooden Stake at Corner  
20" Laurel N.22°W. 12.5 ft. scribed S36 T27S R4W CS BT in 1961.  
32" Laurel N.50°E. 13.0 ft. scribed S31 T27S R3W CS BT in 1961  
(See Ren. #62) (Both BT's. alive & in good condition)  
Other two Orig. BT's., no longer showing scribe marks.  
Drive 1/4" Iron Rod in Corner in place of Wooden Stake.

RE-RENEWED CORNER NO. #152