

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 27 S. T. S. R. 4. W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

FD. O.K.  
By: B. Holt  
Mar. 1962  
M 91-37

82

Closing Corner to Sections 13 and 24 only. (W. Line T27-3W)  
Found - Brass Cap set in 1917 Survey.  
42" Fir Stump N.20 $\frac{1}{2}$ °W. 38.9 ft., shows very plain axe scar.  
36" Fir Stump S.77 $\frac{1}{2}$ °W. 27.1 ft., shows very plain axe scar.  
New BT's: 22" In. Cedar N.40°W. 38.3 ft. Mkd: T27S R4W CC S13 CS BT.  
12" Maple S.47°W. 10.4 ft. Mkd: T27S R4W CC S24 CS BT.

83

Section Corner to Secs. 30 & 31, T27-3W. & Secs. 25 & 36, T27-4W.  
Found - Brass Cap set in 1917 in Mound of Rocks.  
5" Hemlock N.4°E. 92.0 ft. (scribed in 1962) Ren. No. 65.  
7" Hemlock S.72°W. 94.3 ft. (scribed in 1962) recorded.  
6" Hemlock N.10°W. 105.6 ft. (scribed in 1962) not recorded.  
Rescribe Dead Cedar Snag, now 43", S.45°E. 16.3 ft., Orig. BT. Mkd:  
"T27S R3W S31 CS BT"

84

North  $\frac{1}{4}$  Corner to Section 36 only.  
Found - 40" Cedar Stump S.35°W. 14.5 ft. Cut open & fd. good scribing.  
Did not find Brass Cap set in 1917, nor trace of S.E. Tree.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963  
S 36  
Rescribe 40" Cedar Stump S.35°W. 14.5 ft. Mkd:  $\frac{1}{4}$  S36 CS" (old "BT" vis.)  
New BT: 31" Hemlock Stump N.49°E. 41.2 ft. Mkd:  $\frac{1}{4}$  S36 CS BT.  
No live trees available - No other stumps available.

85

South  $\frac{1}{4}$  Corner to Section 25 only.  
Found - Fir, uprooted & slid short dist. downhill, N.38°E. 31.0 ft.,  
cut open & found good scribing " $\frac{1}{4}$ B".  
7" Yew N.67°W. 11.2 ft. Found old blaze, but face had rotted  
before being covered by overgrowth. No scribing on rotted face.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963  
T27S R4W  $\frac{1}{4}$  S 25  
Blaze & Rescribe: 7" Yew N.67°W. 11.2 ft. Mkd:  $\frac{1}{4}$  S25 CS BT.  
21" Hemlock N.16°W. 70.2 ft. Mkd:  $\frac{1}{4}$  S25 CS BT.  
Note - Corner is under a log approximately 30" diam.

86

Corner to Sections S26 | S24  
S25  
Found - Pipe with Brass Cap set in 1917 survey.  
12" Fir N.61 $\frac{1}{2}$ °E. 10.6 ft., now splintered snag, badly burned  
old face. No scribing left.  
20" Fir S.40 $\frac{1}{2}$ °E. 25.1 ft., now uprooted & dead.  
New BT's: 4" Madrone S.76°E. 21.5 ft. Mkd: S25 CS BT.  
25" In. Cedar N.63°E. 153.6 ft. Mkd: T27S R4W S24 CS BT.

87

East  $\frac{1}{4}$  Corner to Sections 26 only.  
Found - Rock called for in gov't notes, " $\frac{1}{4}$ " mkd. on W. face.  
Rotten Fir Stump N.45 $\frac{1}{2}$ °W. 32.3 ft., scribing visible on old  
face, " $\frac{1}{4}$  S26 BT".  
Rotten Fir Stump S.68°W. 17.2 ft., partial scribing visible " $\frac{1}{4}$ ".  
Drove -  $\frac{3}{4}$ " Iron Rod alongside Rock at Corner.  
New BT's: 6" Madrone N.55°W. 31.9 ft. Mkd:  $\frac{1}{4}$  S26 CS BT.  
4" Madrone N.86°W. 24.2 ft. Mkd:  $\frac{1}{4}$  S26 CS BT.

88

East  $\frac{1}{4}$  Corner to Section 14 only.  
Found -  $\frac{3}{4}$ " Reinforcing Rod driven nearly flush with ground. (Ren. #32)  
27" Bl. Oak S.77°W. 83.8 ft., shows scars. Alive & in good cond.  
9" B.Oak N.41°W. 49.4 ft. is burned & dead, scribing visible.  
New BT: 11" Bl. Oak N.61°W. 194.8 ft. Mkd:  $\frac{1}{4}$  S14 CS BT.

FD. O.K.  
By: B. Holt  
Mar. 1962  
M 91-37

Milo E. Godfrey, Deputy County Surveyor  
Wm. Stoffel - Stone, Darby & Halterman  
October 1963  
C. S. File No. 53/33