

Douglas County Surveyor's Record of
Government Corners Renewed

T. 27 S. T. S. R. 4 W. R. W. W. M.

KONE-CHAPMAN CO., EUGENE, ORE. 21881

Milo E. Godfrey, Deputy County Surveyor
Wm. Stoffel and Mike Stone
October 1963
C. S. File No. 53/33

West $\frac{1}{4}$ Corner to Section 25.

Found - Iron Pipe with Brass Cap, pulled out of ground by uprooted tree.
41" Fir (N.83 $\frac{1}{2}$ °E) 47.5 ft., shows good scar - true bearing N.77°E.
Fir S.17 $\frac{1}{2}$ °E. 30.4 ft., uprooted & dead. Old axe scar visible.
Reset - Gov't. Brass Cap in ground at True Corner Position.
New BT: 17" D.Fir S. 7° E. 39.4 ft. Mkd: " $\frac{1}{4}$ S25 CS BT".

89

Section Corner to Sections 25 - 26 - 35 - 36.

Found - Iron Pipe & Brass Cap set in 1917 survey.
32" Hemlock N.40°W. 15.8 ft. Has been opened previously, good scrbing.
25" Doug. Fir S.78 $\frac{1}{2}$ °W. (not S.58 $\frac{1}{2}$ °W) 24.4 ft., shows good axe scar.
50" Cedar S.66°E. 35.0 ft., shows good scar.
No trace of N. E. BT.
New BT: 6" Red Cedar N.57°E. 58.5 ft. Mkd: T27S R4W S25 CS BT.

90

$\frac{1}{4}$ Section Corner to Section 13 and 24.

Found - Iron Pipe with Brass Cap set in 1917 survey.
28" Red Cedar S.70°W. 30.4 ft., good scribing visible on previously
opened blaze " $\frac{1}{4}$ S24 BT", in good condition.
Rotten remnants only of Hemlock stump N.50°W. 23.8 ft., no marks.
New BT: 14" Red Cedar N.78 $\frac{1}{2}$ °E. 22.7 ft. Mkd: $\frac{1}{4}$ S13 CS BT.

FD. OK. by: 1982
B. Holt MAR. 91-37

91

Section Corner to Sections 11 - 12 - 13 - 14.

Found - Iron Pipe with Brass Cap set in 1917 in E. & W. Fence Line.
Stump hole only N.47°E. 82 links.
Stump Hole only N.81°W. 14 lks.
No trace of Fir BT. to S. E.
Did not find Mound of Ston.
New BT's: 17" W.Oak S.5 $\frac{1}{2}$ °W. 231.4 ft. Mkd: T27S R4W S14 CS BT.
12" W.Oak N.83°W. 100.0 ft. Mkd: T27S R4W S11 CS BT.
Power Pole (with transformer) Mkd: "Copco E10111" bears N.4 $\frac{1}{2}$ °E. 194.7 ft.

FD. 11/90 M111-24

92

$\frac{1}{4}$ Section Corner to Section 12 and Section 13.

Found - Iron Pipe with Brass Cap set in 1917 survey.
18" Fir S.16 $\frac{1}{2}$ °E. 19.8 ft., shows scar, tree alive & in good cond.
33" Dead Fir N.56°E. 35.6 ft., shows very plain axe scar.
New BT: 6" D.Fir N.1 $\frac{1}{2}$ °E. 54.1 ft. Mkd: $\frac{1}{4}$ S12 CS BT.

FD. O.K. by
B. Holt MAR. 1982
M 91-37

93

Township Corner

	T26S		
R4W	S 36	S 31	R3W
	S 1	S 6	
	T27S		

Found - I. P. with Brass Cap set by Richardson in 1947, (See Cor. No. 68 -57)
35" W.Oak N.15 $\frac{1}{2}$ °W. 222.8 ft., shows good scar. Tree alive & In good
10" W.Oak S.81°W. 195.8 ft., now dead snag, all scribing visible.
Stump of 36" Fir S. 6° E. 543.8 ft., bark scribing visible.
New BT's: 12" D.Fir S.28°E. 444.6 ft. Mkd: T27S R3W S6 CS BT.
26" W.Oak S.76°W. 175.7 ft. Mkd: T27S R4W S1 CS BT. This tree
was marked as BT. in 1917 survey, scar previously opened
& old face rotted away., new scribing above old face.
Note - Corner is approx. 6" north of E. & W. Fence Line & 200 ft. East
of Buckhorn Road.

RE-RENEWED CORNER NO. #144
(See #27 INT. 24)

94

Sec. Cor. to Secs. 12 & 13, T27-4W. & Secs. 7 & 18, T27-3W.

Found - I. Pipe with Brass Cap set in 1917, in mound of large rocks.
44" Fir N.17°E. 11.2 ft., shows very plain axe scar, tree alive.
48" Fir S.58°W. 28.4 ft., shows very plain axe scar, tree alive.
Fir Stump S.16 $\frac{1}{2}$ °E. 40.3 ft., scar visible.
23" Fir N.54°W. 29.5 ft. (record dist. 30.4 ft.) scar not visible.
Reblaze & Scribe this tree (in wood) "T27S R4W S12 CS BT".
New BT: 10" D.Fir S.41°E. 34.0 ft. Mkd: T27S R3W S18 CS BT.

FD. OK
10/31/89
DC50
C.S. 64/3

FD. OK. by:
B. Holt - MAR. 82
M 91-37

95