

Douglas County Surveyor's Record of
Government Corners Renewed

T. 27 S. T. S. R. 4 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

96

Section Corner to Sections 27 - 28 - 33 - 34.
Found - County Surveyor's Brass Cap set in 1959. (See Cor. No. 42)
All 3 BT's. mkd. in 1959 are still alive & in good cond.
12" Yew N.42°W. 18.3 ft.
12" Cedar S.54°W. 8.5 ft.
15" Cedar S.12°E. 33.4 ft.
The 12" Fir S.88½°E. 69.2 ft., is uprooted & down.
New BT: 4" Yew N.11°E. 23.4 ft. Mkd: "S27 CS BT".
Note - Corner is approx. 6 ft. North of E. & W. Fence Line.

97

Sec. Cor. to Secs. 1 & 12, T27-4W. & Secs. 6 & 7, T27-3W.
Found - G. L. O. Brass Cap at Corner set in 1958. #145
12" Fir S.50°E. 93.7 ft. (slope dist.), scribing visible, in
not completely healed blaze, Tree Alive & in good condition.
10" I. Cedar N.50°W. 11.2 ft., blaze healed over. Tree alive.
13" Fir N.68½°E. 84.5 ft. is standing but dead, good scar.
No trace of White Oak to S. W. which was mkd. in 1958.
32" Fir Stump, 1917 BT, N.60°E. 62.0 ft., scribe mks. visible.
New BT's: 11" W.Oak S.28½°E. 68.7 ft. Mkd: T27S R3W S7 CS BT.
9" Doug. Fir N.45½°E. 163.2 ft. Mkd: T27S R3W S6 CS BT.
No trees near to S. W.

See Also:
Ren. # 26

RE-RENEWED
RE-RENEWED

98

Section Corner to Secs. 31 and 32 only.
(on N. Line T28S R4W).
Found - Iron Wagon boxing set by Frear in 1921. (See Corner # 5)
27" E. Cedar S.28°E. 11.2 ft., shows plain axe scar. Tree
alive & in good condition.
24" Cedar S.82°W. 28.3 ft., is uprooted & dead, shows very
plain axe scar. This tree marked by Frear.
New BT's: 10" I. Cedar N.76°E. 57.5 ft. Mkd: T27S R4W S32 CS BT.
10" I. Cedar N.38°W. 85.6 ft. Mkd: T27S R4W S31 CS BT.
(Scribed high to get over fence wires).

Milo E. Godfrey, Deputy Co. Surveyor
Wm. Stoffel and Mike Stone
October and November, 1963
C. S. File No. 53/33

99

Section Corner to Sections 22 - 23 - 26 - 27.
Found - Rock Mound at Corner, no marks found on any of them.
9" I. Cedar N.66°W. 20.4 ft., scribing visible on not compltly.
healed scar. (See Ren. Cor. No. 41)
9" I. Cedar S.13°E. 10.0 ft., scribing visible on scar.
24" D. Fir S.60°W. 56.6 ft., scar pitched over, scribing visible.
(All 3 of these trees are alive & in good condition.)
12" Fir N.68°E. 11.6 ft. is broken off 6 ft. above ground,
all scribing visible.
Black Oak S.47½°E. 19.8 ft., still alive & standing, but in
poor condition.
Set - Brass Cap (in place of rock) Mkd: County Surveyor's Office, 1963
T. 27 S. R 4 W. S22 | S23
(pile rocks around cap) S27 | S26
New BT: 6" I. Cedar N.71°E. 37.4 ft. Mkd: T27S R4W S23 CS BT.
Note - Corner lies 3 feet N. of E. & W. Fence Line.

100

¼ Section Corner to Sections 27 and 26.
Found - Old, rotted Pine Stump, used for fence corner post, S. 2° W.,
23.8 ft., cut open & fd. old axe marks at top of old rotted
face, no scribing found.
48" Old Fir Stump N.88°E. 6.6 ft., very old axe mks. vis. on
bark which is flaking badly. No scribing fd. in stump, but knowing
of Flint's preference for bark scrbng., I believe bark scribed
this tree. Fd. limb or knot which had been broken or chopped off
at approx. time of Flint's survey.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T27S R4W ¼ S27/S26
New BT's: 24" E.Cedar N.72°W. 103.5 ft. Mkd: ¼ S27 CS BT.
9" D.Fir S.22°W. 84.2 ft. Mkd: ¼ S27 CS BT.
No good trees available East of Line.
A fence cor., Fences S. & W., bears S. 24 ft., A Rock outcrop(12x15x7')
high on S. side bears S.77°W. 34 ft.(S.E. Cor. Tied)
Corner lies approximately 100 ft. South of top of ridge.