

Douglas County Surveyor's Record of
Government Corners Renewed

T. 27 S. T. S. R. 5 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

135

$\frac{1}{4}$ Corner to Section 23 and 24.
Found - County Surveyor's Brass Cap set by BBI in 1953, Ren. #71.
16", now 19" B.Oak, N.81°W. 95.0 ft., shows good scars.
12", now 14" B.Oak S.25°E. 13.0 ft., shows good scars.
As Road is to be widened, I removed said corner and set
Witness Corner, as follows:
Set - Brass Cap for Wit. Cor. Remkd: County Surveyor's Office W.C. 35' South to
T 27 S R 5 W
 $\frac{1}{4}$ S 23 | S 24
1969

New BT's 20" S. Pine N. 17° W. 29.9 ft. mkd: W.C. $\frac{1}{4}$ S23 CS BT.
12" B.Oak S.27°E. 16.9 ft. mkd: W.C. $\frac{1}{4}$ S24 CS BT.

This corner lies in N - S fence line.

12/19/69 - 20" Pine, now stump, N. 17°W. 29.9 ft.

New BT: 8" Triple B.Oak S.84°W. 31.3 ft. mkd: " $\frac{1}{4}$ S23 CSBT".

FO. OK 4/19/78 EXCEPT 8" OAK BRL S. 88°W - CO. SURVEYOR C.S. 59/46

Renew $\frac{1}{4}$ Cor. Sec. 4 and 3.

Found-Orig. 8", now 16" Oak, S.81 $\frac{1}{2}$ °W. 60.7 ft. Down, only axe mks.
found, badly burned.

No trace of orig. SE. BT. We find Boyer's 1944 BT. See Ren. #47.

12", now 16" Fir, N.80°E. 13.9 ft. (Rec.139.9')-alive-prev.
opened & shows " $\frac{1}{4}$ S3 Cs" scribe. Ring count 26 years.

Ridge top to South would fit call dist. of 95 lks., good from
this location. If we use Boyer's record dist., ridge would
be approx. 4 chs. South.

Set- Brass cap mkd: County Surveyor's T27S R5W
Office 1970 $\frac{1}{4}$ S 4 | S 3

Note- Brass cap lies 2 ft. East of N-S fence.

New BT's-9"D.Fir S.38°E. 19.9 ft. mkd: $\frac{1}{4}$ S3 CS BT.

18" B.Oak S.19°W. 54.4 ft. mkd: $\frac{1}{4}$ S4 CS BT.

Rescribe: Boyer's 16"D.Fir N.80°E 13.9 ft. mkd: $\frac{1}{4}$ S3 CS BT.

2/11/70

Renew Sec. cor. of 7,8,18, and 17.

Found-3/4"x16" Iron Bar, in place, as called for in Ren.#55.

Ren.#55 BT, 22", now 26" B.Oak, N.23°W. 102.4 ft. alive, prev.
opened, faint scribe mks. on decayed blaze, good lower scar.

Orig. 11", now 20" W.Oak, N.64 $\frac{1}{2}$ °E. 40.9 ft., alive-prev.
opened, nearly rehealed.

Orig. 16", now 24" Y.Oak, N.13 $\frac{1}{2}$ °W. 102.3 ft. now only burned
stump 6" high.

Orig. 18", now 34" W.Oak, S.53°E. 62 ft., alive-prev. opened,
blaze decayed.

Orig. 14", now 22" W.Oak, S.40 $\frac{1}{2}$ °W. 88.4 ft., alive-prev.
opened, blaze healed.

Cedar Post scribed "CS SEC COR" at cor. pt.

Set- Brass cap mkd: County Surveyor's T 27 S R 5 W #170
(Reset I.Bar alongside) Office S 7 | S 8
1970 S 18 | S 17

New BT's-15"W.Oak N.44°E. 50.8 ft. mkd: T27S R5W S8 CS BT.

20" Forked W.Oak S.4°E. 34.8 ft. mkd: T27S R5W S17 CS BT.

12" W.Oak S.37°W. 36.1 ft. mkd: T27S R5W S18 CS BT.

26" B.Oak N.23°W. 102.4 ft. Rescribe: T27S R5W S7 CS BT.

Note- This cor. lies on steep Easterly slope approx. 125 ft. E. of
ridge top, sloping Southerly.

2/13/70

Section Corner to Sections 29 - 30 - 31 - 32.

Found - 3/4" Iron Pipe, 18" Long, at corner, See Ren. #29.

16", now 19" W.Oak, S.76 $\frac{1}{2}$ °W. 77.2 ft., shows good scar.

12", now 16" W.Oak, N.40 $\frac{1}{2}$ °W. 57.3 ft., shows good scar.

24", now 26" W.Oak S.5 $\frac{1}{2}$ °E. 71.5 ft., shows good scar.

16", now 19" W.Oak N.17°E. 98.4 ft., shows good scar.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 27 S R 5 W
Office S 30 | S 29
1970 S 31 | S 32

All Bearing Trees O. K. & Tagged.

This corner lies at fence corner, fence running N. & W.

7/13/70

John M. Powell & Crew
Feb. 7, 1969
C.S. File No. 53/38

Vernon R. Tracy
Jack Heritage & V. Perron
C.S. File No. 53/38

John M. Powell
W. Penley & J. Heritage
C.S. File No. 53/38

RE-RENEWED, SEE CORNER NO. #165

RE-RENEWED, SEE CORNER NO. #170

FO 5/21/84
R. Thompson
M 92-58

MARCH 71