

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 27 S. T. S. R. 5 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

96

Sec. Cor. to Secs. 35 & 36, T26-5W. & Secs. 1 & 2, T27-5W.

Found -  $\frac{3}{4}$ " I. Rod at approx. Corner Location.

All 3 Orig. BT's. found, bearings & distances according to gov't. notes; as follows:

20" Bl. Oak, now 52", S.  $83\frac{1}{2}^{\circ}$  W. 109 lks.; opened prev., center rotted.

12" Bl. Oak, now 34", N.  $62^{\circ}$  W. 74 lks., shows good scar.

10" Bl. Oak, now 26", N.  $7\frac{1}{2}^{\circ}$  W. 157 lks., shows very good scar.

Bearings fit very closely, but distances vary from 1.5 ft. to 8 ft. from record distances. Since it is impossible to find any one point which will fit distances given, I decide to accept rod found as corner.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964

S35	S36	T26S	
S 2	S 1	T27S	R5W

New BT's: 12" Bl. Oak N.  $11^{\circ}$  E. 10.3 ft. Mkd: T26S R5W S36 CS BT.

10" Bl. Oak S.  $84^{\circ}$  E. 21.6 ft. Mkd: T27S R5W S1 CS BT.

9" Bl. Oak S.  $56^{\circ}$  W. 24.3 ft. Mkd: T27S R5W S 2 CS BT.

Old BT. 26" Bl. Oak N.  $8^{\circ}$  W. 102.1 ft. still in good condition, not rescribed.

Fence Corner - Fences North & East, bears South 19.5 feet.

Milo E. Godfrey, Deputy  
 Wm. Stoffel - Mike Stone  
 Mike Darby - March 31, 1964  
 C.S. File 49/125

97

Sec. Cor. to Secs. 4 & 5, T27-5W. & Secs. 32 & 33, T26-5W.

Found - White Oak Stump S.  $30^{\circ}$  W. 7.3 ft., good reverse scribing visible.

22" Bl. Oak N.  $26^{\circ}$  W. 6.6 ft., scar plainly visible. Did not open. Tree dying.

27" Bl. Oak N.  $10^{\circ}$  E. 8.6 ft., both scars plainly vis. Did not open.

Stump Hole & decayed remnants of Oak Stump S.  $58^{\circ}$  E. 25.1 ft.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964

T26S	S32	S33	
T27S	S 5	S 4	R5W

Rescribe-27" Bl. Oak N.  $10^{\circ}$  E. 8.6 ft. Mkd: T26S R5W S33 CS BT.

New BT's: 24" Madrone (Main Trunk in clump of Five) N.  $76^{\circ}$  W. 67.5 ft.

Mkd: T26S R5W S32 CS BT.

15" Madrone S.  $59^{\circ}$  E. 14.7 ft. Mkd: T27S R5W S4 CS BT.

9" White Oak S.  $45^{\circ}$  W. 129.0 ft. Mkd: T27S R5W S5 CS BT.

Milo E. Godfrey, Deputy Co. Surveyor  
 Wm. Stoffel - M. Stone - M. Darby  
 April 1964  
 C. S. File No. 49/125

98

SEC. COR. to Secs. 4 & 3; T27-5W. & Secs. 33 & 34, T26-5W.

Found - 17" White Oak S.  $62\frac{1}{2}^{\circ}$  E. 98.3 ft. Opened & fd. good scribing.

Shows good upper scar.

26" Bl. Oak S.  $50^{\circ}$  W. 49.5 ft., prev. opened & center rotted away.

Dead & Down Bl. Oak N.  $72\frac{1}{2}^{\circ}$  W. (not N.  $27\frac{1}{2}^{\circ}$  W) 14.5 ft., previously opened and center rotted out.

Did not find N. E. Tree - in Cat. Road.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964

T26S	S33	S34	
T27S	S 4	S 3	R5W

New BT's: 8" White Oak N.  $13^{\circ}$  W. 25.0 ft. Mkd: T26S R5W S33 CS BT.

6" White Oak N.  $20^{\circ}$  E. 20.5 ft. Mkd: S34 CS BT.

9" White Oak S.  $58^{\circ}$  E. 11.6 ft. Mkd: T27S R5W S3 CS BT.

5" White Oak S.  $60^{\circ}$  W. 18.3 ft. Mkd: S 4 CS BT.

Note - Corner lies in N. & S. Fence Line.

99

S. S. E. Corner D. L. C. No. 39.

Found - Iron Rod 175.0 from D. L. C. Corner, See Map File M 5 - 47.

(I find this distance to be 175.4 ft.)

Also PK Nail over DLC Corner,

Move West 0.4 ft. to Correct Distance of 175.0 and

Set -  $\frac{3}{4}$ " Iron Rod West 20.0 ft. from Reference Point.

22" W. Oak N.  $8^{\circ}$  W. 29.4 ft. scribed S.E. DLC #39 CS BT.

18" Cedar S.  $30^{\circ}$  E. 55.5 ft. smkd. with P. K. Nail.

Note - Move this corner point West 0.4 ft., because of solid

Iron Rod & information of  $\frac{3}{4}$ " Iron Pipe at DLC Corner

being badly bent at the time PK Nail was set for corner.

John N. Powell  
 Frank Jones & J. Brady  
 March 1, 1966  
 C. S. File No.  
 No. 53/38