

Douglas County Surveyor's Record of
Government Corners Renewed

T 27 T. S. R 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91881

C O N T - - -

(Sec. Cor., 16,17,20,21)

189

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
March 1, 1990
C.S. 64/6

- 20" now 28" dia. W. Oak with a previously opened blaze, no scribing visible, bears S.60½°W., 169.0 ft. (Rec. S.63°W., 169.0 ft.) Orig. BT.
- 5" now 6" dia. W. Oak with a fully healed double blaze bears S.66°E., 42.4 ft. (agrees with rec.) Ren. No. 78
- 6" now 7" dia. W. Oak with a fully healed double blaze bears N.39°E., 50.0 ft. (agrees with rec.) Ren. No. 78
- 10" now 10" dia. W. Oak with a fully healed double blaze bears S.69°W., 121.9 ft. (Rec. S.69°W., 122.8 ft. Ren. No. 78.

Corner lies at intersection of East and South running ridge on North side near top.

SW Corner DLC #56

190

Found - 2 3/8" dia. DCSO brass cap on a 1¼" O.D. iron pipe flush with ground. Ren. #33

28" now 37" dia. W. Oak, no blazes visible bears N.56°E., 113.8 f (Rec. N.57°E., 112.0 ft. dist. was a face measurement). Ren. 33

4" X chiseled in the top of the easterly curb of W. Umpqua St. 1.5 ft. north of the south end of the curb, bears N.29½°E., 53.4 ft. (agrees with rec.) Ren. #149

4" X chiseled on top of the westerly curb of W. Umpqua St. 1.5 ft. north of the south end of the curb, bears N.11½°W., 39.1 ft. (agrees w/rec.) Ren. No. 149

New Accessory:

25" dia. manhole cover, near center of intersection of W. Military Road and W. Umpqua St. center of manhole cover bears N.43°E., 15.4 ft.

Corner lies along south edge of southerly ditch to Military Rd. near the intersection of Military Rd. and Umpqua St.

2/22/90

191

1/4 Corner for Sections 22 and 27

Found - A 2" O.D. iron pipe protruding 4" above ground. (Source unknown).

A yellow BLM corner location tag is found on intersecting fence line fence post. Tag is from Ren. #93 dated 1/61 indicates corner is "here". Tagged fence post is east, 0.9 ft. from I.P.

10" now 20" dia. B. Oak, we open near ground, no blazes or scribing found. (note: tree is forked south, fork may be a limb that grew over blaze. A larger Oak approx. 28" dia. is found on line between I.P. and previously described BT, this tree is approx. 14 ft. from I.P., may not have been blazed because of fence wire grown into trunk). BT bears N.4½°W., 17.6 ft. (agrees well with record) Ren. No. 93

Set - Position of 2" I.P. is perpetuated because many surveys are tied to it. There is not a clear chain of record showing the I.P. as being at the original or calculated position of ¼ c

New Accessories:

8" dia. W. Oak, double blazed and scribed "1/4 S22 CS BT" bears N.76°E., 50.4 ft.

3" dia. I. Cedar in open field. No other trees in field, not blazed or scribed, bears S.52½°W., 155.1 ft.

Power Pole # Copco B8168, bears S.78°E., 10.8 ft.

Iron pipe lies at intersection of an east and north running fences. Open field to the southwest.

3/6/90

192

Section Corner for Secs. 22, 23, 26 and 27

Found - A 1" I.D. iron pipe protruding 2" above ground. Ren. #31

20" now shattered and rotted Oak stump no blazes or scribing seen, bears N.44 3/4°E., 103.6 ft. Orig. BT (agrees w/rec.) Orig. SE BT is gone.

8" now 13" dia. W. oak with a previously opened unhealed blaze with scribing visible "BT" (blaze is 4 ft. above ground) bears N.46°W., 89.8 ft. Orig. BT (agrees with record)

7" now 11" dia. root crown of a rotted Oak (flush with ground) No blazes or scribing visible bears S.75 3/4°W., 50.1 ft. (Rec. S.75 3/4°W., 51.5 ft. is a slope dist.) Orig. BT.

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Linda Rigutto
March 6, 1990
C.S. 64/6

Douglas County
Surveyors Office
Randall Smith
Stephen J. Flause
Mar. 9, 1990
C.S. 64/6