

Douglas County Surveyor's Record of
Government Corners Renewed

27 T. S. 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

69

Section Corner to Secs. 18 & 19, T27S R6W and Secs. 13 & 24, T27S R7W.
Found - Orig. 17", now 26" down Oak N.10 $\frac{3}{4}$ °W. 88.4 ft. We open
& find good reverse scribing "S13".

Find now 24" Oak, face down, that checks bearing &
distance for Orig. S. W. BT.

No other BT's. found.

Note - Section Corner falls in Cattle guard. I set Witness
Corner 5 feet West.

Set Brass Cap at Wit. Cor. Mkd: County Surveyor's Office, 1960
Mkd. W. C.

5 feet East to

S13	S18
S24	S19

 R6W T27S

New BT's: 7" W.Oak bears N.23°W. 40.9 ft. scribed WC S13 CS T27S R7W BT
18" R.Fir bears S.62°W. 46.5 ft. scribed WC S24 T27S R7W CS BT.
11" W.Oak bears S.48 $\frac{1}{2}$ °E. 62.3 ft. scribed WC S19 T27S R6W CS BT.
11" W.Oak bears N. 4 $\frac{1}{2}$ °E. 32.3 ft. scribed WC S18 T27S R6W CS BT.

James W. Byron
Milo Godfrey
Clete Putnam
Nov. 31, 1960
C.S. File 49/79

70

Sec. Cor. Secs. 7 & 18, T27-6W and Secs. 12 & 13, T27-7W.

Found - Orig. 11", now 20" B.Oak S.60 $\frac{1}{2}$ °W. 20.5 ft. We open & find
good scribing "S 1".

Orig. 13", now 18" B.Oak N.35°W. 29.7 ft. Shows good
scar. I do not open.

No trace of other Orig. BT's. found.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

S12	S 7
R7WS13	S18 R6W

 T27S

New BT's: 20" B.Oak bears S.63°W. 28.1 ft. scribed S13 T27S R7W CS BT.
20" B.Oak bears S.55°E.115.3 ft. scribed S18 T27S R6W CS BT.
20" B.Oak bears N.62°E. 16.3 ft. scribed S 7 T27S R6W CS BT.
18" B.Oak bears N.32°W. 29.7 ft. scribed S12 T27S R7W CS BT.

RENEWED SEE CORNER NO. #168

James W. Byron, Deputy County Surveyor
Milo Godfrey
Clete Putnam
December 1960
C. S. File No. 49/79

71

Sec. Corner Secs. 19 & 30, T27-6W and Secs. 24 & 25, T27-7W.

Found - B. Oak, now 25", S.16°E. 58.7 ft. Cut open & fd. good
reverse scribing "R" & portions of others.

W. Oak, instead of B.Oak, now 35", N.46 $\frac{1}{2}$ °W. 50.2 ft. This
tree had been opened previously and was hollow.

Rotted Remnants of N. E. & S. W. BT's. Too far gone to
find any trace of scribing.

Set Brass Cap Mkd: County Surveyor's

S24	S19
R7W S25	S30 R6W

 T27S

New BT's: 16" B.Oak S.56 $\frac{1}{2}$ °W.64.8 ft. mkd, T27S R7W S25 CS BT.
11" B.Oak N.24°W. 62.3 ft. mkd: T27S R7W S24 CS BT.
14" W.Oak N.39°E. 65.6 ft. mkd: T27SR6W S19 CS BT.
15" W.Oak S.51°E. 79.7 ft. Mkd: T27S R6W S30 CS BT.

This Corner is in fence corner with Fences E. W. & N. from corner.

72

$\frac{1}{2}$ Section Corner to Sec. 7, T27S R6W. & Sec. 12 T27S R7W.

Found - Scribed Oak Stake.

B. Oak, now 36", S.40 $\frac{1}{2}$ °E. 13.5 ft. Chopped scar open &
found good scribing.

A Stump Hole & a down Oak Tree bears N.33 $\frac{1}{2}$ °W. 15.5 ft.
Tree evidently died shortly after being marked &
all marks have rotted off.

Set Brass Cap at Corner alongside scribed stake Mkd:

County Surveyor's Office, 1960 T27S $\frac{1}{2}$ R7W S12/S 7 R6W

New BT's: 11" I. Cedar N.84°E. 32.1 ft. Mkd: $\frac{1}{2}$ S 7 CS BT.
20" B.Oak N.24°W.123.3 ft. Mkd: $\frac{1}{2}$ S12 CS BT.


Corner falls in fence corner-Fences N. S. & E. from corner.

FD. 82. 2 BTs
6/84 R. W. W. M.
1990-57

73

$\frac{1}{2}$ Corner to Sections 19 and 20.

Found - Brigg's 24", now 36" B.Oak N.46°E. 17.2 ft. We open
& find good scribing "CS". SW. BT. not found.

Fence Corner Thus: 

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961
 $\frac{1}{4}$ S19/S20 T27S R6W

New BT's: 15" R.Fir bears N.85°W. 17.5 ft. scribed $\frac{1}{4}$ S19 CS BT.
36" B.Oak bears N.46°E. 17.2 ft. scribed $\frac{1}{4}$ S20 CS BT.

RD. #35