


Douglas County Surveyor's Record of  
Government Corners Renewed

27 T. S. 6 R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 Section Corner to Sections 31 and 32. 85  
 Found - Orig. 18", now down 22" Oak East 2.6 ft. We open & find  
 good scribing "BT".  
 Orig. 12", now 30" B.O. N.38°W. 20.5 ft., shows good scar. I do not open. Fa. O.K.  
by  
Baughman  
April, 1984  
SEE C.S. 58/288  
 Note - I also find 3/4" Iron Pipe at Corner & under N. S. Fence.  
 Set Brass Cap alongside Corner I. P. & Mkd: County Surveyor's  
 Office, 1961 1/4 S31/S32 T27S R6W.  
 New BT's: 7" W.Oak bears N.28°E. 62.6 ft. scribed 1/4 S32 CS BT.  
 24" B.Oak bears N.37°W. 20.0 ft. scribed 1/4 S31 CS BT. (O.B.T.)

Closing Corner to Section 33 and 34. 86  
 Found - 20" Ash, now 30" N.76 1/2°E. 198.0 ft., shows good scribing  
 on old face "R2". (See Vol. 2 PG 8) REN #38  
 N. W. BT. not found.  
 Fence Thus   
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961 C.C. S33/S34 T27S R6W  
 New BT: 54" Forked W.Oak S.63°E. 307.5 ft. scribed,  
 above wire fence, CC S34 -- S34 CS BT. T28S

1/4 Section Corner to Sections 27 and 26. 87  
 Found - Both Orig. BT's.: Orig. 14", now 22" B.Oak N.29°E. 31.0 ft.,  
 Shows scar. I do not open.  
 Orig. 7", now 20" B.Oak N.38 3/4°W. 20.5 ft., shows good scribing.  
 Note - Corner in N. S. Fence Line.  
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961  
 1/4 S27/S26 T27S R6W  
 New BT's: 11" W.Oak bears S.81°E. 25.8 ft. scribed 1/4 S26 CS BT.  
 11" B.Oak bears N.87°W. 30.6 ft. scribed 1/4 S27 CS BT.

1/4 Section Corner to Sections 32 and 33. 88  
 Found - Both Orig. BT's.: Orig. 18", now 40" B.Oak N.49°E. 35.0 ft.,  
 Shows scar. I do not open.  
 Orig. 9", now down Oak, partly rotted. We find good reverse  
 scribing "S".  
 Note - Corner 10' West of Wire Fence.  
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961  
 1/4 S32/S33 T27S R6W.  
 New BT's: 12" W.Oak N.15°E. 20.5 ft. scribed 1/4 S33 CS BT.  
 10" W.Oak N.58°W. 32.9 ft. scribed 1/4 S33 CS BT.

1/4 Section Corner to Sections 28 and 27. 89  
 Found - 12" B.Oak, now 22", N.54°W. 56.8 ft. Cut open & found  
 good scribing "1/4 S". Tree alive & Standing.  
 No trace of N. E. BT. Brush Pile surrounds location.  
 Set Brass Cap Mkd: County Surveyor's Office, 1961  
 1/4 S28/S27 T27S R6W.  
 New BT's: 20" E. Cedar S.21°E. 28.7 ft. Mkd: 1/4 S27 CS BT.  
 12" W.Oak N.48°W. 21.4 ft. Mkd: 1/4 S28 CS BT.

S. E. Corner to D. L. C. No. 50. (Witness Corner) 90  
 Found - 10", now 14" B.Oak, recorded by B.B.I., 1931. We open &  
 find good scribing. REN #15  
 East Laurel BT. not found.  
 Note - This Corner in Roadway. Wit. Corner Set 50' West of True Corner.  
 Set Brass Cap at Witness Corner Mkd: County Surveyor's Office, 1961  
 Wit. Cor. 50' E. to S.E.  
 D.L.C. 50 T27S R6W.  
 New BT's: 9" W.Oak bears S.79°W. 19.7 ft. scribed WC DLC SE 50 CS BT.  
 8" B.Oak bears N.10 1/2°W. 30.0 ft. scribed WC DLC SE 50 CS BT.

Feb. 10, 1970 -- Found 1961 C.S. Brass Cap in place & Mkd. new BT:  
 12" B.Oak N. 22° W. 35.2 ft. mkd: "W.C. S.E. DLC 50 CS BT".  
 This cor. lies 10' W. of top of cut bank on W. side of Melrose Rd. about  
 150 ft. South of Rocky Point Curve.

James W. Byron, Deputy County Surveyor  
 Milo Godfrey  
 Clete Putnam  
 January 13, 1961  
 C. S. File No. 49/79