

Douglas County Surveyor's Record of  
Government Corners Renewed

27 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

101

Section Corner to Secs. 24 & 25, T27-7W & Secs. 19 & 30, T27-6W.  
Found - B. Oak, now 25", S.16°E. 58.7 ft. Cut open & fd. good  
reverse scribing "R" & portions of others.

W. Oak, instead of B.Oak, now 35", N.46½°W. 50.2 ft.  
This tree had been opened previously & was hollow.  
Rotted remnants of N.E. & S.W. BT's., too far gone  
to find any trace of scribing

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

T27S	S24	S19
R7W	S25	S30 R6W

New BT's: 16" B.Oak S.56½°W. 64.8 ft. mkd: T27S R7W S25 CS BT.  
11" B.Oak N.24° W. 62.3 ft. Mkd: T27S R7W S24 CS BT.  
14" W.Oak N.39°E. 65.6 ft. Mkd: T27S R6W S19 CS BT.  
15" W.Oak S.51°E. 79.7 ft. Mkd: T27S R6W S30 CS BT.

This corner is in fence corner with fences E.-W.-N. from corner.

102

¼ Section Corner to Sec. 12 T27-7W. & Sec. 7 T27-6W.  
Found - Scribed Oak Stake.

36" B.Oak S.40½°E. 13.5 ft. chopped scar open & fd.  
good scribing. *REN.#38*

A stump hole & a downed Oak Tree bears N.33½°W. 15.5 ft.  
Tree evidently died shortly after being mkd. &  
all marks have rotted off.

Set Brass Cap at Corner alongside Scribed Stake Mkd:  
County Surveyor's Office, 1960

T27S	R7W	S12/S7	R6W
------	-----	--------	-----

New BT's: 11" I. Cedar N.84°E. 32.1 ft. mkd. ¼ S7 CS BT.  
20" B.Oak N.24°W. 123.3 ft. mkd: ¼ S12 CS BT.

Corner falls in fence corner, fences N. S. & E. from corner.

103

¼ Section Corner to Sections 11 and 12.  
Found - Both BT's. as recorded by Stewart. We open N. W. BT.

& find good scribing. 2" A. P. set by Stewart  
not found. *REN.#19*

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

¼	S11/S12	T27S	R7W
---	---------	------	-----

I rescribe N. W. BT., now 22" W. Oak ¼ S11 CS BT.

104

Sec. Cor. Secs. 12 & 13, T27-7W & Sec. 18 & 77, T27-6W.

Found - Orig. 11", now 20" B.Oak S.60½°W. 20.5 ft. We open  
& find good scribing "S L".

Orig. 13", now 18" B.Oak N.35°W. 29.7 ft. shows  
good scar. I do not open.

No trace of other Original BT's. found.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

T27S	S12	S17
R7W	S13	S18 R6W

New BT's: 20" B.Oak bears S.63°W. 28.1 ft. scribed S13 T27S R7W CS BT.  
20" B.Oak bears S.55°E. 115.3 ft. scribed S18 T27S R6W CS BT.  
20" B.Oak bears N.62°E. 16.3 ft. scribed S17 T27S R6W CS BT.  
18" B.Oak bears N.32°W. 29.7 ft. scribed S12 T27S R7W CS BT.

105

Section Corner to Sections 4, 5, 8, and 9.

Found - Orig. 15", now 30" dead Cedar, partly burned S.55°W. 9.2 ft.,  
shows scars.

Orig. 24", now 32", partly rotted Fir Stump S.65°E. 60.7 ft.  
We open & find good scribing "BT".

Stump of Orig. N.E. BT., Orig. N.W. BT. gone.

16"x8"x16" Corner Stone with + on top at 4 way fence inter. *REN.#50B*

Corner Stone is good. We do not set Brass Cap.

New BT: 6" Laurel bears N.86°W. 37.6 ft. scribed S5 CS BT.

No trees near.

James W. Byron, Deputy County Surveyor  
Milo Godfrey  
Clete Putnam  
December 1960  
C. S. File No. 49/79

**RE-RENEWED, SEE CORNER NO. 180**

**RE-RENEWED, SEE CORNER NO. 194**

**RE-RENEWED, SEE CORNER NO. 164**