

Douglas County Surveyor's Record of
Government Corners Renewed

T 27

T. S.

R 7

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97401

C O N T - -

199

Larry Monrean
Deputy, Doug.
Co. Surveyors
Office
R. Smith
S. Flause
May 2, 1985
C. S. 62/28

(1/4 Cor. Secs. 22 & 27)

Found - Garrett BT, a 8" W. oak with well healed double blaze bears
S. 84° E., 38.9 ft.

Garrett BT, 8" now 11" pine with well healed double blaze bears
N. 54 1/2° W., 48.3 ft. (Rec. 49 ft. checks center of tree
at breast height.)

According to Garrett, the bearing and distance to the apparant BT as well
as the NW cor. Section 27 checks well with record. The aerial photo of the
area shows this location to agree with straight line between controlling
section corners. Construction of the E-W roadway is some evidence of
agreement with position for usage purposes. There are few large oak trees
in this area which would tend to lesson the likelyhood of finding this
evidence by coincidence. Considering the above, I believe this is currently
the best evidence of the original corner. To perpetuate this point:

WE SET - a 1" x 30" iron pipe with brass cap 13" into the ground and
build a mound of stone around measuring 3' x 4' x 17" high.
Cap marked: Douglas County Surveyor T 27 S 1/4 S22 S27
R 7 W 1985

New BTs - 11" D. fir double blazed and scribed "1/4 S22 CS BT" bears
N. 11° W., 20.1 ft.

10" D. fir double blazed and scribed "1/4 S27 CS BT" bears
S. 25° W., 52.4 ft.

5/2/85

Ronald Geisler
For: Champion
International Corp.
M 90 - 79
Nov. 1985-Jan. 1986

Section corner for Sec. 31; and Sec. 36 of T.28-8 only.

Found - 1961 County Brass cap. Ren. No. 135
Scribe marks on a fir stump which has been destroyed and
dragged out of position.

New BTs - 4" fir bears N.46°E., 34.4 ft. scribed X BT.
8" fir bears N.78°W., 47.9 ft. scribed T27S R8W S36 BT.

200

Section corner for Sec. 1 and Sec. 6 of T.28-7 1/2 (So. bdy of T.27-7)

Found - 1924 GLO 3 1/2" brass cap on a 3" I.P. Ren. No. 144
23" rotted fir stump, 3 ft. tall, bears S.12°W., 30.3 ft.
(Rec. 31.0 ft.) No scribing. (1924)

25" rotted fir stump bears S.29°E., 34.3 ft. No scribing. (1924)

New BTs - 8" fir bears S.6 1/2°E., 136.0 ft. scribed T28S R7 1/2W S6 BT.
8" fir bears S.31°W., 198.3 ft. scribed T28S R8W S1 BT.

201

1/4 Corner for Sections 21 and 22

Set - 2" x 30" alum. pipe with 2" alum. cap mkd. "T27S R7W W.M. 1/4
S21/S22 R.L.S. 2305 1988" Corner 3 ft. W. of N-S fence.

BTs set - 8" W. oak bears S.13°W., 171.0 ft. scribed "1/4S21BT".
7" D. fir bears N.49°E., 25.1 ft. scribed "1/4S22BT".

202

Mark Ramp
L.S. #2305
For: Ernie Knigge
and Dan Jones
April, 1989
M 107 - 79
C.S. 63/94

Center 1/4 Corner for Section 22

Set - 5/8" x 30" iron rod with plastic cap marked "R.L.S. 2305".

BTs set - 24" D. fir bears S.32°W., 121.4 ft. scribed "C 1/4 S22BT"
13" D. fir bears S.70°E., 101.2 ft. scribed "C1/4S22BT"

203

Section Corner for Secs. 22, 21, 27 and 28

Found - 1 1/2" I.P. with a 2 1/2" brass cap. 1954 Co. Surveyor. Ren. #94
18" W. Oak bears N.44°E., 146.5 ft. healed blaze.
(NW Fir and SW Oak taken out by road.)

Set BTs - 6" D. fir bears S.24°E., 9.5 ft. scribed "S27 BT"
6" W. Oak bears N.67°W., 84.4 ft. scribed "T27SR7WS21BT"
No BTs available in S28.

204

4/89

FD OK
2/91 M111-79