

Douglas County Surveyor's Record of
Government Corners Renewed

27

T. S.

7

R. W. W. M.

51

N.E. corner D. L. C. 43.
Set 1 inch iron pipe with brass cap
marked D. L. C. 43. N. E. Cor-Co. Surveyors office, D.L.C. 43 CS BT.
A B. O. 18 inches diam. S.49°W., 56.7 feet, NE Cl 43 CS BT.
A B. O. 13 inches diam. S.36°W., 55.3 feet, NE Cl 43 CS BT. 136

Ben B. Irving
Ray Irving
Ralph Irving
July 10, 1953
File No. 45/86

52

Section corner to secs. 15, 14, 22, and 23.
Found 1 inch bolt at corner and one original BT stump only left -
12 inch B. O., S.30°W., 81 lks. - Some scribes visible.
Set a 1 inch iron pipe with brass cap mkd. County Surveyor's Office
T27S, R7W., $\frac{15}{22}$ / $\frac{14}{23}$ 155

We blazed and scribed the following:
10 inch R. Fir, N85°E., 31.0 feet - S 14 CS BT.
10 inch R. Fir, S.24°E., 33.3 feet - S 23 CS BT.
8 inch R. Fir, N.42°W., 25.0 feet - S 15 CS BT.
10 inch R. Fir, S.72°30'W., 46.6 feet - S 22 CS BT.

53

$\frac{1}{4}$ sec. corner to secs. 15, and 22.
Set 1 inch iron pipe with brass cap mkd. T27S, R7W County Surveyor's
Office 1954. Sec. 15, Sec. 22.
This corner was set at midpoint between section corners to secs. 15, 14,
22, and 23 and secs. 16, 15, 21, and 22.
Blazed and scribed the following: 154
10 inch R. Fir, S.47°W., 20.9 feet - Mkd $\frac{1}{4}$ S 22, CS BT.
12 inch Laurel, N. 3°W., 29.8 feet - mkd $\frac{1}{4}$ S 15, CS BT.

Ben B. Irving, County Surveyor
Jim Byron
Ray Irving
John Fee
March-April, 1954
File 45/262

54

Section corner to secs. 15, 16, 21, and 22.
Corner renewed from stump of orig. BT - 20 inch W. O. S.39°E., 33 lks. dist.
Also we foun old rotted stumps that check for size, bearings and distances
for NE and SW BTs: 30 inch W. O. N.77°E., 109 lks.
20 inch W. O. S.27°W., 332 lks.
Set a 1 inch by 36 inch iron pipe with brass cap mkd 15, 16, 21, and 22,
T27S, R7W., 1954, County Surveyor's Office - Set cap 4 inches under road
surface.
Blazed and scribed the following: 161
14 inch B. O., S.39°15'W., 50.0 feet, S21 CS BT.
10 inch B. O., N.17 $\frac{1}{2}$ °W., 85.8 feet S 16, CS BT. 9/18/68 - FOUND O.K.
16 inch B. O., N.30°E., 80.5 feet, S 15, CS BT. V.R.T.

55

Section corner to secs. 21, 22, 27, and 28.
Found original BT - 10 inch W. O., S.84°W., 126 lks. scribed T27S, R7W
S 28, - Good condition - all other BTs gone.
Set 1 inch iron pipe with brass cap mkd County Surveyor's Office 1954
21, 22, 27, 28., T27S, R7W. 94
Blazed and scribed the following trees:
14 inch red fir, S.27 $\frac{1}{2}$ °E., 27.4 feet - mkd S 27 CS BT.
18 inch red Fir, N.37 $\frac{1}{2}$ °W., 45.7 feet - mkd S 22 CS BT.
10 inch red Fir, N.24 $\frac{1}{2}$ °W., 59.0 feet - mkd S 21 CS BT.

56

$\frac{1}{4}$ corner to secs. 27 and 28:
Found original BT 20 inch B. O., S.32°E., 63 lks. in good condition. Also
found leaning snag with possible old blaze. No scribes visible. Checks
for bearing and distance - a yellow tag near this snag states that Jack
Chapman found scribes on snag in 1945.
Set 1 inch iron pipe with brass cap mkd County Surveyor's Office, 1954.
27/28, T27S, R7W. 192
Blazed and scribed the following trees:
10 inch Red Fir, S.34°E., 62.0 feet mkd $\frac{1}{4}$ sec. 28 CS BT.
10 inch Red Fir, S.17°W., 20.6 feet mkd $\frac{1}{4}$ S 28 CS BT.

57

$\frac{1}{4}$ corner to secs. 15 and 16.
Found 30 inch B. O., N.0°15'E., 714 lks-scribes visable S $\frac{1}{4}$ also found
stump B. O. N.1°W., 717 lks.
Set $\frac{5}{8}$ inch iron rod at corner.
Blazed and scribed the following trees:
16 inch W. O., N.47 $\frac{1}{2}$ °E., 462.6 feet mkd $\frac{1}{4}$ S 15 CS BT.
16 inch B. O., N.22 $\frac{1}{4}$ °W., 372.4 feet mkd $\frac{1}{4}$ S 16 CS BT. 170