

Douglas County Surveyor's Record of
Government Corners Renewed

27

T. S.

7

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

James W. Byron, Dep.
County Surveyor
Ray Irving
John Fee
Feb. 3, 1955.
C. S. File No. 46/90

Section corner to secs. 28, 29, 32 and 33.
Found: Brass Cap at f. corner and stump of 14 inch R. Fir
N.12°E., 15 lks. Also stump of 14 inch R. Fir, S.56°W., 16
lks., scribing visible. All other BTs gone.

Blazed and scribed four trees:

14 inch B. Oak, N.1°E., 7.6 feet, T 27 S, R 7 W., S 28 CS BT.
14 inch R. Fir, N.61½°W., 70.5 feet, T27S, R 7 W., S 29 CS BT.
10 inch R. Fir, S.38½°E., 25.7 feet, T 27 S, R 7 W., S 33 CS BT.
8 inch R. Fir, S.28°W., 66.0 feet, T 27 S, R 7 W., S 32 CS BT.

58

James W. Byron
M. Godfrey
S. Bilow
Dec. 20, 1957
C.S. File No. 49/50

Section Corner Common to Sections 29, 30, 31, & 32.

Found: 4"X 4" Sq. & scribed stake with mound of rocks, REN.#30
Also both BTs. scribed by Eppstein, 1929. Check record dist. &
bearing except N.32°E. BT. should be N.37°E. 55.7 ft.
I open this BT. & find good scribing.

Wire Fence Corner bears N.45°W. 10 ft.

Set Brass Cap at corner & alongsides scribed stake, marked S30|S29 T27S
County Surveyor's Office, 1957 S31|S32 R7W

New BTs: 18" R.Fir bears N.14°E. 19.9 ft. scribed T27S R7W S29 CS BT.
24" Laurel bears N.21°W. 23.0 ft. scribed T27S R7W S30 CS BT.
10" R.Fir Bears S.44°E. 110.9 ft. scribed T27S R7W S32 CS BT.

59

~~THIS CORNER REMOVED JUNE 17, 1960 - M 18-80~~

~~Section Corner to Sections 31 & 32. SEE WIT. COR. #79~~

~~Found - Scribed Power Pole S.31½°W. record S.34°00'W. 223.6 ft. REN.#29~~

~~15" W. Oak S.4°E. 197.2 ft. shows good scar. I do not open.
Set Brass Cap at Corner marked T27S R7W S31/S32 ¼ County Surveyor's
Office, 1957.~~

~~Tie to new Power Pole - RF 1 S.83½°W. 137.0 ft.~~

~~1
1
A~~

Dec. 23, 1957

60

¼ Section Corner to Sections 30 & 31.

Found - Both BT's. as recorded by Eppstein, 1930, See C.S. File No. 14/59

BT's alive & in good condition. I open each BT & find good REN.#23
scribing & both check for distance, but I find the
S.47°15'W. BT. should be S.52°W. & S.89°E. BT. should
be S.84°E.

Set Brass Cap at Corner marked: ¼ S30 T27S R7W County Surveyor's
Office, 1958 S31

New BT's: 14" Cedar bears S.46°W. 41.3 ft. scribed ¼ S31 CS BT.
Rescribe S.84°E. 135.0 ft. now 20" W.O. ¼ S31 CS BT.

Note: See Sketch in file for exact location of corner.

61

Section Corner to Sections 30 & 31, R7W, & Sections 25 & 36, R8W.

Found - All Four BT'S as recorded, 1930 Renewal.#26

The N.E., S.E., & S.W. BT's now stumps, show good scars.
I open N.E. BT., shows good scribing.

The 20" Laurel now 24" Snag N.82°W. 4.0 ft., record N.56°W. 4.0 ft.
Has open face with good scribing. All BT's check bearings
& distances, Except Laurel for bearing.

Set Brass Cap at Corner mkd.: County Surveyor's Office, 1958 S25|S30
T27S. R8W S36|S31 R7W.

New BT's: 50" R.Fir bears N.81°W. 23.3 ft. scribed S25 T27S R8W CS BT.
58" Cedar bears N.24½°E. 351.0 ft. scribed S30 T27S R7W CS BT.

62

¼ Section Corner to Section 31, R7W, & Section 36, R8W.

Found - Both BT's. as recorded, 1930 Renewal, check bearing & distance.

The S.E. BT., now down. REN.No.24

The N.W. BT., alive & in good condition, I do not open, good scar.
I open S. E. BT. & find good scribing "CS ½S"

Set Brass Cap at Corner Marked: County Surveyor's Office, 1958 ¼ S36/S31
T27S R R8W R7W.

New BT: 9" Cedar N.66°E. 39.8 ft. scribed ¼ S31 CS BT.

63

James W. Byron, Deputy County Surveyor
M. Godfrey
S. Bilow
April 23, 1958
C. S. File No. 49/79

(See Also Vol. 2 Pg. 142 H.S. Brown Survey)