

Douglas County Surveyor's Record of  
Government Corners Renewed

27 T. S. 7 R. W. W. M.

Witness Corner to  $\frac{1}{4}$  Corner S31/S32.

Set Brass Cap Mkd: Wit. Cor., 150 ft. South to  $\frac{1}{4}$  Corner  
S31/S32 T27S R7W

(See Ren #s 29 & 60)

County Surveyor's Office, 1960

79

James W. Byron, Deputy  
M. Godfrey - C. Putnam  
Per Benneville Power  
June 10, 1960  
C.S. File 52/28  
Map File M 18 - 80

No BT's.

Witness Corner South of  $\frac{1}{4}$  Cor. to Sections 31 and 32.

Set Brass Cap Mkd: Wit. Cor. 355 ft. North to  $\frac{1}{4}$  S31/S32 T27S R7W  
County Surveyor's Office, 1960.

79A

Scribed: 6" B. Oak N.87°W. 5.4 ft. Wit. Cor.  $\frac{1}{4}$  S31 CS BT.  
4" W. Oak S. 4°E. 15.6 ft. W. C.  $\frac{1}{4}$  S32 CS BT.

Property Line North 1.3 feet.

Section Corner to Sections 16 - 17 - 20 - 21.

Found - Orig. 36", now 46" W. Oak Snag N.45°E. 215.8 ft. I open  
& find good reverse scribing "BT".

Orig. 18", now 40" B. Oak Snag S.51°E. 208.6 ft. I do  
not open.

Orig. 18", now down Oak & mostly rotted S.53°W. 180.2 ft.  
No trace of Orig. N. W. BT.

Also find  $1\frac{1}{4}$ " Iron Pipe, top broken, at corner. (Ren #14)

Set Brass Cap at Corner Mkd: County Surveyor's Office S17 | S16 T27S  
Office, 1960 S20 | S21 R 7W

New BT's; 6" R. Fir bears N.41°W. 31.0 ft. scribed S17 CS BT.  
8" R. Fir bears S.51°W. 51.5 ft. scribed S20 T27S R7W CS BT.  
21" W. Oak bears S.64°E. 22.5 ft. scribed S21 T27S R7W CS BT.  
6" R. Fir bears N.81°E. 22.4 ft. scribed S16 CS BT.

80

James W. Byron, Deputy  
Milo Godfrey  
Clete Putnam  
June 20, 1960  
C.S. File No. 49/79

Section Corner to Sections 9, 10, 15 and 16.

Found - Orig. 12", now 18" Oak Snag N.32°W. 112.9 ft. I open  
& find good scribing "BT".

Orig. 15", now 24" W. Oak N.20°E. 55.4 ft., shows scar.  
I do not open.

No trace of S. E. or S. W. BT's. found.

Set Brass Cap at Corner Mkd: County Surveyor's S 9 | S10  
Office, 1960 S16 | S15 T27S R7W

Note - Corner Located Thus:

New BT's: Rescribe W. Oak, now 24" N.20°E. 55.4 ft. S10 T27SR7W CS BT.  
21" R. Fir bears N.54°W. 82.6 ft. scribed S 9 T27SR7W CS BT.  
5" W. Oak bears S.24°W. 62.8 ft. scribed S16 CS BT.  
15" R. Fir bears S.61°E. 125.5 ft. scribed S15 T27SR7W CS BT.  
9/18/68 - FOUND O.K. V.R.T.

81

James W. Byron, Deputy  
For C. L. Brown  
Wit: Milo Godfrey  
Clete Putnam  
August 19, 1960  
C.S. File No. 52/41

$\frac{1}{4}$  Section Corner to Sections 10 and 15.

Found - Orig. 24", now 34" W. Oak S.32°E. 84.5 ft. I open & find  
good scribing "ST".

Orig. 16", now 24" W. Oak N. 6°E. 38.9 ft., shows scar,  
I do not open.

Do not find Rock Set by Theil, 1884. (Ren #50) #195

Note - Corner located Thus.

Set Brass Cap at Wit. Cor. Mkd: County Surveyor's Office, 1960

Wit. Cor. 30' South to  $\frac{1}{4}$  Cor. S 10 T27S R7W

New BT's:

Rescribe Orig. W. Oak, now 24" N.20°E. 10.0 ft. W.C.  $\frac{1}{4}$  S10 CS BT.  
12" B. Oak S. 2 $\frac{1}{2}$ °E. 58.0 ft. scribed S.C.  $\frac{1}{4}$  S15 CS BT.

82

Map File M 19-42

Section Corner to Sections 3, 4, 9 and 10.

Found - Orig. 36", now 40", down Oak S.83°E. 56.8 ft., shows good  
reverse scribing "S10". Orig. 12", now 16" rotted Stump,  
good reverse scribing "BT" S.65°W. 155.8 ft. No trace of  
NE BT. found. Found Oak Stump Hole that checks for Orig. N.W. sec.  
BT. Find 12"x8"x Stone at corner with + chisled on top. (Ren #50) \* \* \*

Note - Corner Stone is good Monument. Do not set Brass Cap

New BT's: 9" Laurel bears N.50°W. 17.5 ft. scribed S4 T27S R7W CS BT.  
10" Cedar bears N.63°E. 19.2 ft. scribed S3 T27S R7W CS BT.  
6" R. Fir bears S.27 $\frac{1}{2}$ °W. 42.5 ft. scribed S 9 T27S R7W CS BT.  
21" Cedar bears S.55°E. 25.2 ft. scribed S10 T27S R7W CS BT.

83

James W. Byron, Deputy  
Milo Godfrey  
Clete Putnam  
August 1960  
C. S. File 49/79