

Douglas County Surveyor's Record of
Government Corners Renewed

27

T. S.

7

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE., 21881

James W. Eyrton, Deputy County Surveyor
Milo Godfrey
Clete Putnam
August 19, 1960
C. S. File No. 52/41 M 19 - 42

$\frac{1}{4}$ Section Corner to Sections 10 and 11. 84
Found - Orig. 36", now 42" Oak, mostly rotted Stump, N.2°W. 171.6 ft.,
shows good reverse scribing "BT" on old face section.
Shell of old Oak Stump that checks bearing & distance for
Orig. S. E. BT.

Note - Corner is in old Logging Road.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960
 $\frac{1}{4}$ S10/S11 T27S R7W.

New BT's: 11" B.Oak bears S.76°W. 11.3 ft. scribed $\frac{1}{4}$ S10 CS BT.
7" W.Oak bears N. 6°E. 41.8 ft. scribed $\frac{1}{4}$ S11 CS BT.

$\frac{1}{4}$ Section Corner to Sections 9 and 10. 85
Found - Both Orig. BT's. Each now down & mostly rotted, but each
has parts of old faces showing good reverse scribe marks.
check record size, species, bearing & distance.

Note - Corner 2 feet West of N. S. Fence.
Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1960
 $\frac{1}{4}$ S 9/S10 T27S R7W

New BT's: 19" R. Fir bears S.33°W. 23.5 ft. scribed $\frac{1}{4}$ S 9 CS BT.
10" R. Fir bears S.39°E. 38.4 ft. scribed $\frac{1}{4}$ S10 CS BT.

*Fd OK 1986
PER M100-18*

Section Corner to Sections 10, 11, 14 and 15. 86
Found - Orig. 24", now 36" Oak Stump. I open & find good reverse
scribing "BT" S.18°E. 192.1 ft.

Orig. 12" Ash, now 30", shows old axe marks, center rotted,
checks record distance & bearing, recorded N.63°E. 6 I
find should be N.61°E.

Orig. S. W. BT. not found.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960
 $\frac{S10}{S15} | \frac{S11}{S14}$ T27S R7W

New BT's: 8" W.Oak bears N.86°E. 179.0 ft. scribed S11 T27S R7W CSBT.
12" W.Oak bears S.46 $\frac{1}{2}$ °E. 147.6 ft. scribed S14 T27S R7W CS BT.
8" R.Fir bears S. 2 $\frac{1}{2}$ °W. 299.5 ft. scribed S15 T27SR7W CS BT.

Note - No Trees near to N. W.

RE-REVIEW SEE CORNER NO. 186

$\frac{1}{4}$ Section Corner to Sections 11 and 14. 87
Found - W. Oak Tree, now 44", N.58°E. 56.1 ft., showing scar.
Opened & found good scribing "4S" about 6" inside wood.
No trace found of S. E. BT.

At Corner Set Iron Pipe with Brass Cap Mkd: "County Surveyor's Office,
1960 T27S R7W $\frac{1}{4}$ $\frac{S11}{S14}$ "

Blaze & Scribe New Trees: 9" D. Fir N.8°E. 26.6 ft. Mkd. $\frac{1}{4}$ S11 CS BT".
18" D. Fir S.35°E. 17.6 ft. mkd. $\frac{1}{4}$ S14 CS BT".

Section Corner common to Sections 11 - 12 - 14 - 13. 88
Found - Orig. 30", now down & rotted Oak, N.84°W. 669.9 ft. No
scribing found.

Orig. 9", now down & mostly rotted Oak, S. 21°W. 139.9 ft.
We find good scribe marks(reverse) "T Ø"

Orig. 15", now 30" Oak Snag S. 7°E. 190.7 ft. Old face
rotted, shows old axe work.

Note - This corner was renewed about 50 years ago. I find, now
18" white Oak bears S. 2°E. 134.2 ft. We open & find good
scribe marks. Renewal not of record.

Set Brass Cap at Corner Mkd: County Surveyor's $\frac{S11}{S14} | \frac{S12}{S13}$ T27S R7W
Office, 1960

New BT's: 20" W.Oak bears N.22°E. 40.5 ft. scribed T27S R7W S12 CS BT.
7" W.Oak bears N.49°W. 32.0 ft. scribed T27S R7W S11 CS BT.
10" W.Oak bears S.33°W. 97.6 ft. scribed T27S R7W S14 CS BT.
18" R.Fir bears S.23 $\frac{1}{2}$ °E. 96.5 ft. scribed T27S R7W S13 CS BT.

James W. Eyrton, Deputy
Milo Godfrey
Clete Putnam
Sept. & Oct. 1960
C. S. File No. 49/79