

Douglas County Surveyor's Record of
Government Corners Renewed

27 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 Section Corner to Sections 22 and 23. 89
Found - Orig. 12", now 18", down & mostly rotted, Oak, S.45°E.
34.3 ft. We find good reverse scribing on old face. "BT"
Mound of Stone at Corner.
Orig. S.W. BT. gone
Set Brass Cap in Mound of Stones Mkd: County Surveyor's Office, 1960
1/4 S22/S23 T27S R7W
New BT's: 18" Pine bears N.44°E. 46.0 ft. scribed 1/4 S23 CS BT.
6" W.Oak bears N.83°W. 42.0 ft. scribed 1/4 S22 CS BT.

RE-RENEWED, SEE CORNER NO. #191

Section Corner to Sections 22 - 23 - 26 - 27. 90
Found - Orig. 10", now 16" Oak Snag N.20°E. 27.7 ft. We open
& find good reverse scribing "23R".
Orig. 12", now 24", down Oak, checks bearing & dist.
for N. W. BT.
Orig. S.W. BT. gone. Orig. S.E. BT. gone.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960
S22/S23 T27S
S27/S26 R7W
New BT's: 9" Cedar bears N.65°E. 11.7 ft. scribed S23 T27S R7W CS BT.
14" Pine bears S.25°W. 6.3 ft. scribed S27 T27S R7W CS BT.
10" Cedar bears S.76°E. 27.5 ft. scbd S26 T27S R7W CS BT.
14" R.Fir bears N.13°W. 35.0 ft. scribed S22 T27S R7W CS BT.

1/4 Corner to Sections 15 and 14. 91
Found - Orig. 10", now 16" E.O. N.78°W. 7.3 ft. We open &
find good reverse scribing "BT".
Orig. 18", now down stump section, S.25°E. 58.1 ft.
We find good reverse scribing "B".
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960
1/4 S15/S14 T27S R7W
New BT's: 10" R.Fir bears S.45°W. 18.0 ft. scribed 1/4 S15 CS BT.
7" R.Fir bears N.68 1/2°E. 21.9 ft. scribed 1/4 S14 CS BT.

FD OK 5/64
R. Quinn
M 96-55

1/4 Corner to Sections 33 and 34. 92
Found - Brass Cap, set in 1924, in good condition.
Orig. Oak, approx. 30", N.76°W. 25.7 ft. Still
standing but center completely rotted away.
20" B.Oak N.26°W. 40.3 ft. is uprooted & down.
No trace found of N. E. BT. (1924)
24" D. Fir N.42°W. 50.0 ft. with recent scribing showing
in still open blaze.
Blaze & Scribe: 16" Madrone N.77°E. 34.0 ft. Mkd: "1/4 S34 CS BT".

Section Corner to Sections 27 - 28 - 33 - 34. 93
Found - Brass Cap set in 1924 Survey.
Stump of 8" Fir S.27°E. 13.9 ft. scribe marks visible
in open scar.
Stump of 12" Fir S.29°W. 7.9 ft., showing scar.
Rotted remnants of old Oak BT's. to N.W. & N.E. found.,
too far gone for any possibility of scribing to be fd.
Blazed & Scribed new BT's: 15" Fir S.65 1/2°W. 13.7 ft. Mkd:
"T27S R7W S33 CS BT"
6" Fir N.79°W. 25.6 ft. Mkd: "S28 CS BT".
8" Fir S.16 1/2°E. 50.4 ft. Mkd: "T27S R7W S34 CS BT".
8" Fir N.57°E. 63.5 ft. Mkd: "T27S R7W S27 CS BT".

Section Corner to Sections 21 - 22 - 27 - 28. 94
Found - Brass Cap at Corner. REN # 55
Note - N.W. & N.E. BT's. now stumps only.
New BT's: 16" W. Oak N.44°E. 116.5 ft. scribed S22 T27S R7W CS BT.
12" R.Fir N.70°W. 11.6 ft. scribed S21 T27S R7W CS BT.
5" W. Oak S.47°W. 20.0 ft. scribed S28 CS BT.

RE-RENEWED, SEE CORNER NO. #204

James W. Byron, Deputy County Surveyor
Milo Godfrey
Clete Putnam
November 1960

C. S. File No. 49/79

Nov. 16,
1960
C.S.
File
No.
49/79