

Douglas County Surveyor's Record of  
Government Corners Renewed

27 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

James W. Byron, Deputy  
Milo Godfrey  
Clete Putnam  
Nov. 21, 1960  
C. S. File No. 49/79

Section Corner to Sections 13 - 14 - 23 - 24. 95  
Found - Oak Tree, down & rotted, N.75°W. 66.7 ft. Good reverse scribing "BT".  
Oak Tree, down in creek, N.57°E. 9.9 ft. Good reverse scribing "BT".  
Rotted Oak Stump in place, S.35°E. 15.2 ft., No scribing Fd.  
Rotted Oak Stump, in place, S.20°W. 30.4 ft. No scribing fd.  
Position for Corner falls in Creek & directly in N. & S. Fence Line.  
Set Wit. Corner - Iron Pipe with Brass Cap Mkd: 10' North to Corner.  
County Surveyor's Office, 1960 

S14	S13
S23	S24

 T27S R7W  
New BT's: 10" P. Pine S.60°W. 31.0 ft. Mkd. T27S R7W WC S23 CS BT.  
9" W. Oak N.23°W. 51.4 ft. Mkd: T27S R7W WC S14 CS BT.  
6" W. Oak N.37°E. 33.2 ft. Mkd: T27S WC S13 CS BT.  
7" D. Fir S.60°E. 7.7 ft. Mkd: T27SR7W WC S24 CS BT.

Approximate  $\frac{1}{4}$  Corner to Sections 23 and 26. 96  
Set Oak Post - Mound of Rock from which:  
W. Oak 10" diam. N.53°15'E. 26.4 ft.  
W. Oak 30" diam. S.37°30'E. 44 ft.  
Approximate  $\frac{1}{4}$  Corner - Refer to C. S. File No. 4/37 for further information  
Dec. 29, 1922 - By J. W. Cole.

Section Corner to Sections 23, 24, 25 and 26. 97  
Found - Orig. 12", now 26" Oak S.75°E. 81.8 ft. We open & find good scribing "S".  
Stump Hole that checks for Orig. N. E. BT.  
Find  $\frac{3}{8}$ " I. R. with Y strap on top at Corner. SEE REN.#16  
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960 

S23	S24
S26	S25

 T27S R7W  
New BT's: 9" B.Oak bears N.40°E. 22.4 ft. scribed S24 T27S R7W CS BT.  
15" B.Oak bears S. 6°E. 34.2 ft. scribed S25 T27S R7W CS BT.  
6" B.Oak bears S.58°W. 9.0 ft. scribed S26 T27S R7W CS BT.  
No trees near to N. W.

$\frac{1}{4}$  Section Corner to Sections 13 and 24. 98  
Found - Orig. 12", now 20" Oak Stump N.87°E. 396.7 ft., center rotted but shows good reverse scribing "BT". REN.#7  
Also find large Oak down in creek that checks close for Orig. S. E. BT.  
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960 

S13
S24

 T27S R7W  
New BT's: 6" W.Oak bears N.36°W. 308.2 ft. scribed  $\frac{1}{4}$  S13 CS BT.  
24" W.Oak bears S.89 $\frac{1}{2}$ °E. 381.2 ft. scribed  $\frac{1}{4}$  S24 CS BT. #183

$\frac{1}{4}$  Section Corner to Sections 23 and 24. 99  
Found - Iron Rod Set by Cole, REN.#11 & 12  
16" B.Oak N.25°E. 42.2 ft. Cut open & find good scribe "BT".  
17" B.Oak S.60°W. (instead of S.60°E. as recorded by Cole) 12.5 ft., showing good scars. Did not open this tree.  
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960 T27S R7W  $\frac{1}{4}$  S23/S24 Set alongside Cole's rod.  
New BT's: 7" W.Oak N.84°E. 17.6 ft. mkd:  $\frac{1}{4}$  S24 CS BT  
Found remnants of rotted Oak showing old axe marks N.25°E. 9 ft.  
Corner falls in fence corner fences N.S. & W. from corner.

Section Corner to Secs. 13 & 24, T27-7W. & Secs. 18 & 19, T27-6W. 100  
Found - Orig. 17", now 26", down Oak N.10 $\frac{1}{2}$ °W. 88.4 ft. We open & find good reverse scribing "S13". Also find, now 24" Oak, down(face down) that checks bear. & dist. for Orig. S.W. BT. No other BT's. fd.  
Note - Section Cor. falls in cattle guard. I set Wit. Cor. 5 ft. West.  
Set Brass Cap at With. Cor. Mkd: County Surveyor's Office, 1960 

S13	S18
R7W S24	S19 R6W

 T27S  
New BT's: 7" W.Oak bears N.23°W. 40.9 ft. scribed WC S13 CS T27S R7W BT  
18" R.Fir bears S.62°W. 46.5 ft. scribed WC S24 T27S R7W CS BT.  
11" W.Oak bears S.48 $\frac{1}{2}$ °E. 62.3 ft. " WC S19 T27S R6W. CS BT  
11" W.Oak bears N.4 $\frac{1}{2}$ °E. 32.2 ft. " WC S18 T27S R6W CS BT.

James W. Byron, Deputy County Surveyor  
Milo Godfrey  
Clete Putnam  
December 1, 1960  
C. S. File No. 49/79