

Douglas County Surveyor's Record of
Government Corners Renewed

27 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

Gene E. Johnson
March 15, 1955.
C. S. File No. 42/194.

South Closing corner to secs. 35 and 36.
Location of corner determined from testimony of Arthur M Mathews (See
C. S. File No. 42/194).
At corner point set $\frac{3}{4}$ inch iron rod with stake alongside,
from which:
No bearing trees available.
Drove climbers rock nail in cliff face, S.46°00'E., 16.0 feet dist.
(Rock nail has circular head with 1 inch diameter steel ring attached.)

RENEWED CORNER NO. #13

James W. Byron, Deputy Co. Surveyor
M. Godfrey
J. Fee
July 18, 1957
C.S. File No. 49/5

South $\frac{1}{4}$ corner to section 36.
Location determined from O. B. T.:
12 inch Oak (now 14 inches), N.73°E., 6.0 lks., very rotten-scribe
visible.
At corner point set $\frac{3}{4}$ inch iron rod,
from which: (new B.T.s)
14 inch Oak bears N.82°00'W., 90.0 feet dist. scribed $\frac{1}{4}$ S 36 B T RE 356L.
12 inch Oak bears N.11°15'E., 67.0 feet dist. scribed $\frac{1}{4}$ S 36 B.T. RE 356L.

RENEWED CORNER NO. 11

James W. Byron
M. Godfrey
J. Fee
July 17, 1957
C.S. File No. 49/5

Section Corner 25, 30, 31, & 36.
Found-Original BT 36 inch Fir now 52 inch N 33°30'E 21.1 ft. Found "BT"
bark scribed & parts of other scribe marks. Found original 24 inch
Cedar now 32 inch N 20°W 27.1 feet. Shows old face-rotted-no scribing
found. Also found base of stump of 12 inch Hemlock S28°30'E 27.7 feet.
S. W. original BT not found in roadway.
Note -This corner was renewed about 45 years ago but not of record in our
office. May be recorded in Coos County. I find 18 inch Cedar (Open Face
scribed T 27S, R 8W S31 BT. Bears S 80°E 16.5 feet. I add scribing
to this BT DCS BT.
Set- Brass cap at corner marked D. County Surveyor's Office, 1957
Coos Co. $\frac{25}{36}$ | $\frac{30}{31}$ T 27S Douglas Co. NO. 15
New Bearing Trees: 32 in. Cedar N 20°W 27.1 ft. scribed T27S, R9W, S 25, DCS BT.
52 in. Cedar stump S33°W 52.8 ft. scribed T27S, R9W, S36DCS BT.
Rescribed renewed cedar (See note above S80°E 16.5 feet.
Rescribed 52 inch Fir N 33 $\frac{1}{2}$ °E 21.1 ft. T27S, R8W, S30,
DCS BT (Bark Scribed)

Renew Section Corner $\frac{31}{6}$ | $\frac{32}{6}$ T27S R 8W. T28S
Found-Original N 5°W 26.4 feet 30 inch Fir Snag, good bark scribing,
Also find Fir stump 35 inch, bark gone, bears N 75°E 33.0 feet.
Record 30 inch Fir N 54°E 33.0.
Position of Corner determined by the one remaining BT from which:
A real old 3"x3"x36" Ewood Stake bears S 38 $\frac{1}{2}$ °E 15.0 ft., no scribing on
stake.
Set Brass Cap at Corner Marked: $\frac{31}{6}$ | $\frac{32}{6}$ T27S, R8W
From Which: $\frac{31}{6}$ T28S, R8W. County Surveyors, 1957.
6 inch Ewood bears N 49°E 9.0 feet, scribed T27S, R8W, S 32 CS BT.
8 inch Hemlock bears N 73°W 59.0 ft, scribed T27s, R8W, S 31 CS BT.
24 inch Hemlock bears S 2 $\frac{1}{2}$ °W 45.0 ft, scribed T28S, R8W, S 6 CS BT.

James W. Byron, Deputy
M. Godfrey
S. Hilow
April 23, 1958
C. S. File 49/79

Section Corner to Secs. 25 & 36, T27S, R8W, & Secs. 30 & 31, T27S, R7W.
Found - All 4 BT's. as recorded, 1930 renewal.
The N.E., S. E. & S. W. BT's. now stumps show good scars.
I open N. E. BT., shows good scribing.
The 20" Laurel now 24" Snag N.82°W. 4.0 ft. record N.56°W. 4.0 ft.,
has open face with good scribing.
All BT's. check bearings & distances, except Laurel for bearing.
Set Brass Cap at Corner Mkd.: $\frac{S25}{R8W}$ | $\frac{S30}{S31}$ T27S County Surveyor's Office,
R7W 1958
New BT's.: 50" R. Fir bears N.81°W. 23.3 ft. scribed S25 T27S R8W CS BT.
58" Cedar bears N.24 $\frac{1}{2}$ °E. 351.0 ft. scribed S30 T27S R7W CS BT.

$\frac{1}{4}$ Section Corner to Section 36, T27S R8W, & Section 31, T27S R7W.
Found - Both BT's. as recorded, 1930 renewal. Check bearing & si