

Douglas County Surveyor's Record of
Government Corners Renewed

27 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

6
 $\frac{1}{2}$ Section Corner to Section 36, T27S, R8W, & Section 31, T27S, R7W.
 Found - Both BT's. as recorded, 1930 renewal. Check bearing & distance.
 The S. E. BT., now down.
 The N. W. BT. alive & in good condition, I do not open, good scar.
 I open S. E. BT. & find good scribing "CS $\frac{1}{2}$ "S".
 Set Brass Cap at Corner marked: $\frac{1}{2}$ S36/S31 T27S, County Surveyor's
 R8W R7W Office, 1958
 New BT.: 9" Cedar N.66°E. 39.8 ft. scribed $\frac{1}{2}$ S31 CS BT.

James W. Byron, Dep.
 M. Godfrey
 S. Blilow
 April 23, 1958
 C.S. File No. 49/79

7
 Section Corner to Sections 2, 3, 10 and 11.
 Found - Orig. 40", now 48" Fir N.43°E. 29.7 ft., previously
 opened, shows good scribing "2 S".
 Orig. 4", now 36" Cedar S.33°W. 74.6 ft., shows good
 scars. I do not open.
 Orig. 40", now 44" Fir Snag, shows good scar, S.66°E. 55.4 ft.
 Orig. 40", now 48" Fir N.39°W. 79.2 ft., shows good scars.
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

James W. Byron, Deputy
 Milo Godfrey
 C. Putnam
 August 14, 1959
 C. S. File No. 49/79

8

S 3	S 2	
S10	S11	T27S R8W

 New BT's: 7" R. Fir bears S.71 $\frac{1}{2}$ °E. 36.3 ft. scribed S11 T27S R8W CS BT.
 9" R. Fir bears N.36 $\frac{1}{2}$ °W. 34.4 ft. scribed S 3 T27S R8W CSBT,
 Oct. 1970 - Found O.K. J.M.P. CS 54/119

Section Corner to Sections 1, 2, 11 and 12.
 Found - Orig. 18", now 36" Cedar N.19°E. 44.2 ft., shows good
 scars, I do not open.
 Orig. 8" Yew, now 10" Ewe Stump, partly burned, shows
 good scribing "8 W" S.36°W. 8.6 ft.
 No trace of Original N. W. or S. E. BT's.
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

8

S 2	S 1	
S11	S12	T27S R8W

 New BT's: 8" Hemlock bears S.54°E. 12.4 ft. scribed S12 T27S R8W CS BT.
 10" Hemlock bears S.45°W. 3.0 ft. scribed S11 T27S R8W CS BT.
 8" Hemlock bears N.39°W. 16.0 ft. scribed S 2 T27S R8W CS BT.
 Original N. E. BT. is O. K.

9
 Sec. Cor. Secs. 24 & 25, T27-8W. & Secs. 19 & 30, T27-7W.
 Found - Orig. 40", now 60" Fir S.71°E. 19.8 ft., shows good bark
 scribing.

Orig. 18", now 28" W. Fir N.31°W. 22.4 ft. We open &
 find good scribing "2".
 Other Orig. BT's. not found.
 Set Brass Cap at Corner Mkd: County Surveyor's R8W S24 | S19 R7W
 Office, 1960 S25 | S30 T27S
 New BT's: 18" R. Fir S.19°W. 26.7 ft. scribed S25 T27S R8W CS BT.
 8" W. Fir S. 4°E. 29.9 ft. scribed S30 T27S R7W CS BT.
 12" W. Fir N.79°E. 29.0 ft. scribed S19 T27S R7W CS BT.
 28" W. Fir N.26°W. 20.6 ft. scribed S24 T27S R8W CS BT.

James W. Byron
 Milo Godfrey
 Cleve Putnam
 December 21, 1960
 C. S. File No. 49/79

10
 Closing Corner Sections 33 and 34.
 Found - Cedar Stake at Corner, down, badly decayed, scribe visible.

24" Fir N.34°E. 37.6 ft., cat face
 22" Fir N.61°W. 26.4 ft. cat face, badly burned.
 Set - Steel Tube with Survey Cap at Corner
 Scribed: 22" Fir N.1°E. 28.2 ft.
 25" Fir N.70°W. 31.4 ft.

Note - This corner lays about 35 ft. North of E-W ridge in
 old growth Fir stand and falls about 100 ft. North of
 the North line of Section 4, T.28S., R.8W.

G. Robert Lecklider
 Wilt Dale McFarland
 January 1961
 C. S. File No. 51/162

RE-RENEWED CORNER NO. 20