

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 27 $\frac{1}{2}$  S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Vernon "Ray" Tracy  
V. Perron - C. S. File No. 54/113

Closing Corner Sections 32 & 33, T27 $\frac{1}{2}$  - R8W.  
Found - 1961 Cadastral Brass Cap, out of position & buried.  
RESET BRASS CAP at corner point from 1961 BT's., as follows:  
Orig. 16", now 17" Hemlock, alive, S. 34° E. 38.3 ft., scribe visible on unhealed blaze.  
Orig. 16", now 16" Cedar, dead, S. 43 $\frac{1}{2}$ ° W. 85.1 ft., scribe visible on unhealed blaze.  
New BT: 10" Hemlock S. 85° W. 22.1 ft. mkd: "T27 $\frac{1}{2}$ S R8W S32 CC CS BT".  
This corner falls in west tract of cat. skid trail & 91 ft. N. and 95 ft. E. of Wilson Creek, course N.W.

5/14/70

1

Standard Corner for Sections 32 & 33, T27-8W.  
Found - 1961 Cadastral Brass Cap was pushed over and buried.  
RESET BRASS CAP at corner point.  
Found - County Surveyor BT. as recorded in Ren. #16, T. 27-8W.  
36" Cedar, Alive, N. 2° E. 39.9 ft., scribe visible on unhealed blaze, "T27SR8W S33 SC BT" (We add "CS") All other BT's. Destroyed.  
New BT: 7" Hemlock N. 17° W. 31.4 ft. mkd: "T27S R8W S32 SC CS BT".  
This corner lies on top of cut bank on westerly side of the Burnt Mt. access road, approx. 60 ft. west of centerline.

5/14/70

2

Standard Corner for Sections 33 and 34.  
Found - 1961 Cadastral Brass Cap, properly set & mkd. with Lecklider's pipe and cap alongside. (Ren. #10, T27-8W)  
Orig. 22", alive, Fir, N. 36° E. 37.6 ft., tagged, chopped open & scribe vis.  
1961 10", now 12" Hemlock, alive, N. 29 $\frac{1}{2}$ ° W. 10.6 ft., scribe visible on partially healed blaze.  
All other Bearing Trees are turned out stumps.  
New BT: 10" Hemlock N. 34° E. 23.6 ft. mkd: "T27S R8W S34 SC CS BT".  
This corner lies 50 ft. west of top of ridge, course S.W. & N.E.

5/18/70

3

Standard  $\frac{1}{4}$  Corner to Section 33 only, T27-8W.  
Found - 1961 Cadastral Brass Cap, out of place, approx. 2.0 ft. and buried 2 ft. deep.  
Orig. 38" Fir, alive, N. 54° E. 24.4 ft. Rescribe visible on unhealed blaze.  
1961 10", now 12" Hemlock, alive, N. 50 $\frac{1}{2}$ ° W. 39.6 ft., scribe visible on nearly healed blaze.  
No trace other bearing trees called for due to logging.  
RESET CADASTRAL BRASS CAP at corner point.  
New BT: 9" Hemlock N. 39° E. 13.5 ft. mkd: " $\frac{1}{4}$  S33 SC CS BT".

5/18/70

4

$\frac{1}{4}$  Corner South Side Section 33, T27 $\frac{1}{2}$ -8W.  
Found - 1961 Cadastral Brass Cap, properly marked and set.  
9" Chinquapin, alive, N. 27° W. 11.9 ft., bark scribed " $\frac{1}{4}$  S33 BT" low & bark scribe "BT" 5.0' high. (Recorded as Oak)  
We Rescribe in wood " $\frac{1}{4}$  S33 CS BT".  
No trace N.E. BT due to cat skid trail.  
New BT: 8" Hemlock N. 68° E. 75.4 ft. mkd: " $\frac{1}{4}$  S33 CS BT".  
This corner lies on top of spur, sloping west & the standard  $\frac{1}{4}$  corner of Section 4, T28-8W. bears S. 89 $\frac{1}{2}$ ° W. 27.1 ft.

5/18/70

5

Standard  $\frac{1}{4}$  Corner to Section 4 only, T28-8W.  
Found - 1961 Cad. Brass Cap, properly set and marked.  
Orig. 25" Fir, alive, S. 25° E. 13.2 ft., Rescribe visible on unhealed blaze.  
10" Hemlock, N. 67° W. 13.2 ft., blazes nearly healed. We tag. (Boyer's BT)  
6" Hemlock, broken off 15' high, dying, S. 38° W. 23.1 ft., scribe visible.  
New BT: 7" Hemlock S. 44° W. 20.8 ft. mkd: " $\frac{1}{4}$  S 4 SC CS BT".  
This corner lies on top of spur, sloping west. The  $\frac{1}{4}$  cor. of Sec. 33, T27S R8W bears N. 89 $\frac{1}{2}$ ° E. 27.1 ft.

5/18/70

6