Douglas County Surveyor's Record of Government Corners Renewed

T 28 T. S. R 1 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21981

29

1/4 Corner to Sec.10 and 11
Found 15 x 14 x 10 inch basalt stone set firmly,10" Deep " 1/4" marked on west face
A Hemlock, 10(now 11)inches dia. leaning badly, bears S85°E,8.9 ft.(rec.7.9 ft). Tree scribed " 1/4 S 11 BT"
A Hemlock windfall 10" dia. approximate standing position S29°W,15.2 ft. tree is rotted,has good blaze.
Renewal: Set brass cap at 1/4 corner stamped:
COUNTY SURVEYORS OFFICE 1975 — T 28 S R 1W | 1/4 S 10 | S11
A' Hemlock, 14" Dia. bears S13 1/2°E,17.7 ft. scribed "1/4 S11 CS BT"
A Hemlock, 11" dia. bears N62°W.,12.2 feet. scribed "1/4 S10 CS BT
12/1/75

L.E. MOnrean
P.L.E
J.H.C.
CS 57/39
12/1/75

1/2c

30

Section corner for Secs. 1 and 12 only, T28-2.
Found - 1923 GLO brass cap properly stamped.
From which:
A 36" now 45" Fir, bears S.45°W., 16.0 ft. Tree is alive with well healed blaze.
A 36" now 42" Fir, bears N.78°W., 7.4 ft. Tree is alive with well healed blaze.
Corner OK. Did Not Renew. Corner lies approx. 200 ft. south of T28-1 West 1/4 Corner Sec. 7. Also lies 10 ft. south of Rd. #274.
8/2/76

M. Lenora Ladig, Doug. Co. Surveyors Office
Jim Cook
Karen Cheney
Aug. 2-3, 1976
C.S. 59/18

31

West 1/4 Corner for Sec. 7 only.
Found - A 15" x 12" x 8" Basalt stone with "1/4" on West face.
A 12" now 21" Hemlock snag bears N.35°E., 22.4 ft. with "1/4 S7 BT" in cut open blaze.
A 18" now 27" Hemlock bears West 13.2 ft. with well healed blaze. Tree is alive.
An unrecorded 16" Fir, bears S.60°E., 19.1 ft. Tree is alive with visible scribe marks in healing blaze.
Set - At true corner point: A 1" x 36" I. Pipe with brass cap stamped:
"Douglas Co. Surveyor" 1976 — T28S | R2W | S.7 1/4 | R1W
Placed orig. stone East of cap.
Compass dec. 20° East. Note: Cor. lies approx. 200 ft. North of T28S R2W Sec. Cor. for 1 and 12. Also Approx. 190 ft. North of White post on Rd. #274.
8/3/76

32

1/4 Corner for Sec. 18 only. West side
Found - A 12"x9"x5" Stone, (rec. 10"x6"x4") with "1/4 18" mkd. on east face. (See second resurvey and retracement)
A 16" now 20" Hemlock bears N.13°E., 37.6 ft. Alive and well. Shows healed blaze.
Other trees are gone.
Set - A 1" x 30" I. Pipe with brass cap stamped:
DOUGLAS COUNTY SURVEYOR 1976 — T 28 S R 1 W | S 18 | 1/4
Replaced Stone on South side of brass cap.
New BT - A 5" Yewwood, bears N.54°E., 10.2 ft. mkd. "1/4 S 18 CS BT".
9/21/76

A. Victor Cangie
Mike Tompkins
Do. Co. Surveyors
Sept. 21, 1976
C.S. 59/24

33

Section Corner for Secs. 12 and 13 only, T.28-2.
Found - Orig. 1923 SW BT, 60" now 64" D. Fir alive and well healed.
The 1923 corner monument and NW BT have been lost due to logging activity.
At the true corner location as determined by the record measurements from the original SW bearing tree:
We set - A 1"x30" I. Pipe 28" in the ground with brass cap attached:
Douglas Co. Surveyor 1976 — T 28 S | R 2 S | S 12 / S 13 | S 18 | R 1 W
From which: The orig SW BT bears S.34°W., 34.3 ft.
New BT - A 16" G. Fir, bears N.10°E., 34.2 ft. scribed "T28S R1W S18 CS BT" on a double blaze.
9/21/76

Gary Langlitz
Karen Cheney
Do. Co. Surveyors
Sept. 21, 1976
C.S. 59/24