

Douglas County Surveyor's Record of
Government Corners Renewed

T 28 T. S. R 2 R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 97401

112

Ronald A. Quimby LS.
#1654 - BHW, Eng.
For: U.S. Forest Serv.
April 1980
C.S. 58/229

1/4 Corner for Sections 7 and 18.
Found - Alum. cap on iron pipe as renewed by Thomas Schrum Jr. in 1962.
18" Hemlock, N.68°W., 55.8 ft. with visible scribe. Ren. #19
No original evidence left.
New BT's - A 12" Hemlock, S.7°W., 12.5 ft. scribed 1/4 S18 BT.
A 8" Hemlock N.34°E., 14.5 ft. scribed 1/4 S7 BT.
Placed brass washers in BT faces.

4/80

113

East 1/4 Corner for Sec. 12 only, T.28-3
Found - 1 1/2" I.P. with 1962 County Brass cap. (no record).
Found 4" x 4" wood post
18" Cedar snag, N.71°W., 27.11 ft. visible scribes. See #26 A
9" Hemlock, S.61°W., 9.3 ft. good marks.
New BT - 11" Cedar, S.24°E., 8.1 ft. "E 1/4 S12 BT"
Brass washer RLS #1005 in BT face.
Set Fiberglass post and sign N.45°W., 2.0 ft.

3/80

114

Section corner for Secs. 7 and 18 only. (west side)
Found - 1" I.P. with alum. cap marked U.S.P.C. Prop. cor. T28S R2W
S12 R3W R2W 7C 18C RE 4287. Ren. #27
26" stump, N.32°W., 26.1 ft.
40" D. Fir S.60°E., 29.0 ft.
24" stump, N.82°W., 56.1 ft.
Corner bears 4.76 ft. west of line.
New BT - 12" Maple, N.49°E., 51.8 ft. "T28S R2W S7 CC BT" . Brass washer
RLS 1654 in BT face.

3/80

115

1/4 Corner for Sec. 13 only, T28-3
Set - 2 1/2" Iron pipe with brass cap marked RLS 1654 T28S R3W 1/4 S13
T28S R2W 1980
New BT's - 7" Hemlock N.40°W., 10.0 ft. "E 1/4 S13 BT" #149
9" Madrone, S.85°E., 7.2 ft. "E 1/4 S13 BT"
Brass washers in BT faces, RLS 1005,

116

Section corner for Secs. 18 and 19 only,
Set - 2 1/2" iron pipe with brass cap marked RLS 1654 T28S R3W S13,
S18C S19C T28S R2W 1980
New BT - 7" Hemlock N.35°W., 16.4 ft. "S19 CC T28S R2W BT". Brass washer
RLS 1654 in BT face.
Set Fiberglass post and signs 6.0 ft. south
Found - stone 1.94 ft. west of line - set brass cap at location of stone -
buried stone alongside See Ren. #16
13" Hemlock bears S.43°E., 5.0 ft. from stone - good face.
20" D. Fir bears N.25°E., 23.0 ft. from stone - visible scribes.

3/80

117

Township corner for Secs. 6 and ; Sec. 31, T.27-2; Sec. 36, T.27-3
Sec. 1, T.28-3.
Found - 1" iron pipe with brass cap (1962 County) Ren. #9
11" D. Fir, N.14°W., 19.7 ft. good scar
14" Madrone snag, S.3°E., 17.0 ft. visible scribes #143
22" Cedar, S.27°W., 72.8 ft. visible scribes.
New BT - 7" D. Fir N.27°E., 35.3 ft. "T27S R2W S 31BT"
Set fiberglass post 3.0 ft. south. BT has brass washer RLS 1005 in face.

118

Angle Point Section 6 and Sec. 31 of T.27-2.
Found - 1" iron pipe with alum. cap (1968 U.S. Plywood) Ren. #59
12" D. Fir, N.2°W., 33.3 ft.
12" Fir, S.65°E., 11.1 ft.
New BT - 14" Cedar S.14°W., 10.0 ft. marked "A.P. S6 BT". Brass washer RLS
#1005 in face.
Set fiberglass post and sign 2.0 ft. north.
New BT - 6" Fir S.66°W., 34.5 ft. "AP S6 BT". Brass washer RLS #1654 in face

3/80

Ronald A. Quimby RLS #1654
BHW, Engineering
For: U.S. Forest Service
March 1980
M 83 - 19

Ronald Quimby
BHW, Engineering
For: U.S. Forest Ser.
March 1980
M 79 - 37