

Douglas County Surveyor's Record of
Government Corners Renewed

T 28 T. S. R 2 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97501

119

Center 1/4 Corner for Section 6
Set - 2 1/2" iron pipe with brass cap marked T28S R2W C 1/4 S6 RLS 1005
1980.
New BT's-13" Hemlock, N.7°W., 53.6 ft. "C 1/4 S6 BT"
26" D. Fir, S.70°E., 78.8 ft. "C 1/4 S6 BT"
Brass washer RLS 1005 in both BT faces.
Set post and sign 4.0 ft. north and east.
Found - Alum. cap on 1" iron pipe, N.3°44'53"W., 1.93 ft. Ren. #62
72" D. Fir bears N.32°W., 37.2 ft. visible scribes
34" D. Fir bears S.81°W., 42.5 ft. visible scribes.
- - - - - 3/80

1/4 Corner for Secs. 6 and 5.
At proportionate location:
Set - 2 1/2" Iron pipe with brass cap marked T28S R2W 1/4 S6 S5 RLS 1654
1980.
New BT's-14" Fir, S.35°W., 25.2 ft. "1/4 S6 BT"
10" Madrone, S.64°E., 26.0 ft. "1/4 S5 BT"
Brass washers RLS 1005 in both BT faces.
Set post 5.0 ft. east.
Shrum's corner location bears N.33°40'29"W., 31.51 ft. as computed from
southeast BT - 10" Fir. Ren. #61
- - - - - 3/80

1/4 Corner for Section 1 only, T.28-3
Found - 1962 County surveyors brass cap on 1 1/4" iron pipe. Ren. #10
12" Cedar stump, S.60°E., 120.2 ft.
Fiberglass post and signs 4.0 ft. north and south.
New BT's- 10" Pine, S.10°E., 25.8 ft. "1/4 S1 BT"
9" Cedar, S.76°E., 15.5 ft. "1/4 S1 BT"
No trees in Section 1. Brass washers in BT faces RLS 1005.

1/4 corner for Secs. 6 and 7
Found - Alum. cap on 1" iron pipe. Ren. #22
13" Cedar, N.56°E., 33.5 ft. visible scribes
14" D. Fir, S.5°E., 20.3 ft. visible scribes (down)
New BT - 20" Cedar, S.6°E., 98.0 ft. "1/4 S7 BT". brass washer RLS 1654
in BT face.
Set fiberglass post and signs 4.0 ft. west and south.
- - - - - 3/80

Section corner for Sections 1 and 12 only, T.28-3
Found - 1" iron pipe with alum. cap. Ren. #25
14" Hemlock stump, S.16°W., 18.5 ft.
16" D. Fir stump, S.84°W., 16.6 ft. visible scribes.
New BT's - 14" Pine, N.86°W., 184.0 ft. "S1 T28S R3W BT"
8" Hemlock N.56°W., 152.0 ft. "S1 T28S R3W BT"
Brass washers RLS 1005 in BT faces. Set fiberglass post and signs 4.0 ft.
north.
- - - - - 3/80

Angle Point between Sec. 2; and Sec. 34, T.27-2W. See Ren. #54
Fd. - Aluminum cap on 3/4" Iron Rod (unrecorded) mkd. "USPC Prop Cor
T27S R2W S34, Ap T28S R2W S2 RE#4287."
10" Yew bears N.14°E., 18.0 ft. with visible scribe.
20" Hemlock stump bears N.77°E., 40.1 ft. with visible scribe.
Original 24" Fir down stump bears North 6.0 ft. uproot.
12" W. Fir snag bears S.81°E., 53.4 ft. with visible scribe.
New BT - 8" Fir bears South 66.0 ft. scribed "AP S2 BT", with brass washer
mkd. RLS 1654 set in BT face.
Set post and sign 3.0 ft. East of corner.
- - - - - 6/80

Closing Corner to Secs. 34 and 35, T.27S. R.2W.
Fd. - Unrecorded aluminum cap on 3/4" iron rod mkd. "USPC PROP COR T27S
S34, S35; T28S R2W S2 RE #4287"
16" Fir stump bears N.50°W., 22.7 ft. (unrecorded).
15" Cedar snag bears S.76°E., 6.6 ft. (unrecorded).
Original 30" Cedar stump bears N.45°E., 7.3 ft. shows bottom of face

CONTINUED NEXT PAGE

Ronald A. Quimby LS. 1654
BHW, Engineering
For: U.S. Forest Service
March 1980
M 79- 37

Ronald A. Quimby LS#1654
Romanso E. Ware LS#1005
For: U.S. Forest Service
May 1980
M 79 - 45