

Douglas County Surveyor's Record of  
Government Corners Renewed

T 28 T. S. R 2 R. W. W. M.

KONE-CHAPMAN CO., EUGENE, ORE. 97401

142

Leonard Herzstein  
U.S.F.S - Deputy  
Dougl. Co. Surveyors  
Office  
Witness: Jim Landrum  
Nov. 18, 1981  
C.S. 61/29

1/4 Corner for Secs. 19 and 30.  
CONDITION REPORT ONLY  
Found - 1 1/2" Diam. I.P. firmly set projecting 14" above ground with  
brass cap, properly mkd., set by Shaner in 1968. Ren. #44  
I add 2 ft. diam. mound of stone with I.P. now projecting 10".  
12" yewood, bears S.34°W., 24.5 ft. with scribe marks "1/4 S30  
T28 S R2W BT" visible on partly healed blaze. Ren. #44  
44" D. Fir stump, bears N.7°W., 18.0 ft. with no marks visible. #44  
A 8" hemlock bears N.84°W., 77.7 ft. with scribe marks "1/4 S19 BT"  
and brass washer stamped "RLS 835" visible on partly healed  
double blaze. (Not of record, 1977, Donald Stone RLS #835)  
Note - Corner is 75 ft. west of USFS Rd. #2817 and about 180 ft. north  
of standing timber.

11/18/81

Township Corner for Sec.6 (T28-2); Sec. 1 (T28-3); Sec. 31 (T27-2);  
and Sec. 36 (T27-3). Renewal # 117 (28-2) 143

Found - A 1962 County Surveyor brass cap on an iron post, and the following  
accessories;  
BT's - 27" Fir stump, bears N.40°E., 46.9 ft. (Rec. N.43°E., 46.2 ft.)  
Scribing partly visible. (Original)  
44" Fir stump, bears N.52°W., 29.9 ft. (Rec. N.55°W., 30.4 ft.)  
No scribing visible. (Original)  
Badly decayed stump, bears S.25°W., 27.7 ft. (Orig.)  
11" broken-top Fir, bears N.10°W., 19.7 ft. Closed face. (1962)  
22" Cedar, bears S.27°W., 71.6 ft. (Rec.72.0 ft.) Closed face.  
(1962)  
16" Madrone snag, 17 ft. tall, bears S.06°E., 17.0 ft.  
(Rec. S.03°E) Scribing visible. (1962)  
9" down and uprooted fir bears N.87°E., 50.0 ft. No scribing  
found. (1962)  
10" Fir, bears N.27°E., 35.1 ft. (Rec. 35.3 ft.) Closed face.  
(1980)  
Set - 5" Fir, bears S.79°E., 5.9 ft. dist., Scribed: X BT.

Section Corner for Secs. 24&25, T28-3, and 19 &30 T28-2.

Found - A 1" iron pipe with 2 1/2" brass cap ext. 14" above ground and  
mkd."T28S R3W 

S24	S19
S25	S30

 R2W, 1962 SEE REN #106 144  
BT's - A 18" Chinquapin Oak, bears S14 1/2°W, 102.5 ft. vis. scribe.  
40" Hemlock stump, bears S14°E, 23.4 ft. vis. scribe.  
36" D. fir stump, bears S29°W, 19.7 ft. blaze healed.  
36" D. fir stump, bears N50W, 15.8 ft. vis. scribe.  
Set - A 8" Chinquapin Oak, S52°E, 45.0 ft. scribed "S30 T28S R2W BT"  
5" Hemlock, bears N85°E, 43.3 ft., scribed "X" "BT".  
A brass washer stamped "RLS 1035" was nailed flush with the  
lower portion of the blazes.

1/4 Corner for Sections 14 and 23

Found - 1923 GLO 2 1/2" disk on a 1" O.D. IP protruding 12" above ground and  
leaning 8" west of plumb.  
22" now 22" dia. 14" high rotted fir stump with a fully healed  
lower blaze, blaze opened and illegible scribing found, bears  
N.20°E., 29.7 ft. (agrees with record) Original BT.  
10" now 13" dia. down hemlock with a fully healed blaze, bears  
S.20°W., 18.5 ft. to center of remaining root crown. Orig. BT.  
8" Hemlock now an 8" dia. fallen southwesterly and broken, dead  
hemlock with a partially ehaled single blaze with scribing "1/4  
S23 CS BT visible, Has stump hole bearing S.67°W., 9.8 ft.  
(Agrees with record) Ren. No. 46  
A 10" D. fir now measuring 9" DBH and now a dead 35 ft. tall snag  
with the scribing "1/4 S14 CS BT visible on a partially healed  
single blaze bears N. 23°W., 6.7 ft. (as per rec.) to center of  
trunk above blaze and N.16 1/2°W., 6.7 ft. to center of root  
crown. Ren. No. 46  
Set - Monument is straightened to plumb position and is now firmly set  
protruding 10" above ground.  
New BTs - 6" DBH Hemlock double blazed and scribed "1/4 S23 CS BT bears  
S.71 1/2°W., 88.5 ft.  
6" DBH Hemlock double blazed and scribed "1/4 S23 CS BT bears  
S.06°W., 113.4 ft.

145

Ronald G. Geisler, Champion International  
June, 1985 thru August, 1985  
M 90 - 71

Gerald Nygren LS 1035  
C.S. 63/29  
March 1988

Doug. Co. Surveyor  
Office  
R. W. Smith  
S. J. Flause  
Sept. 6, 1988  
C. S. 62/55