

Douglas County Surveyor's Record of
Government Corners Renewed

T. 28 S. T. S. R. 2 W. R. R. W. W. M.

ROSE-CHAPMAN CO., EUGENE, ORE. 21881

James W. Byron and Milo E. Godfrey, Deputy County Surveyors
John Powell Ray Tracy
Wm. Stoffell Mike Stone
August and September 1962
C. S. Files No. 49/28 Also C.S. File No. 52/126

Thomas E. Shrum, Jr.
For U. S. Flywood Corp.
June 1962
Map File M 25 - 7

Renew Corner to Sections 13 and 24 only, T28-³W.
Found - All BT's. as recorded. N.W. BT. shows good scribing.
Set - Brass Cap at Cor. Mkd: County Surveyor's S13
Office, 1962 R3W S24 R2W T28W
Rescribe Orig. 24", now 28", Hemlock S.25°W. 9.9 ft. S24 T28S R2W CS BT.

15

FD. OR 3/4
BHW ENG.
M83-19

Renew Closing Corner to Sections 18 and 19 T28-2W. #116
Found - Stone at Cor. & Both BT's. as recorded. N.W. BT. shows good scribing.
DO NOT SET BRASS CAP AT CORNER.
New BT: 9" R. Fir bears S.43°E. 5.0 ft. scribed S19 CC T28S R2W CS BT.

16

Closing Corner to Sections 31 and 32; T27-2W.
Found - 1 1/2" Iron Pipe in Mound of Rock at Corner.
Rotten Fir Snag N.29 1/2°E. 6.6 ft. good scribing on piece of rotten
fir wood lying at base of snag, "T27S R2W S32 BT".
D. Fir, alive & standing, now 28"; N.21°W. 56.1 ft., shows good axe
scar in small opening previously made. Fd. good scribing "B".
DO NOT SET BRASS CAP AT CORNER.
New BT's: 10" D. Fir N.12°W. 14.7 ft. Mkd: T27S R2W S31 CS BT.
6" Madrone N.78°E. 21.4 ft. Mkd: T27S R2W S32 CS BT.
Corner lies on top of rocky ridge sloping south.

17

C.S. 49/28

Closing Corner to Sections 6 and 5, T28-2W.
Found - Fir, now 42", bark scribing visible. (Orig. must have been 40")
instead of 4") - S.45°W. 6.0 ft. from face.
Fir, now 48", S.34°E. (not S.57°E. 53.5 ft. (face) Bark scribing visible.
(Orig. must have been 30", instead of 3")
Set - Brass Cap at Corner Mkd: County Surveyor's T28S R2W C.G.
Office, 1962
Orig. BT's: 42" D. Fir bears S.45°W. 7.2 ft. to center of tree.
48" D. Fir bears S.34°E. 55.5 ft. to center of tree.

18

S 6/S 5

55

C.S. 49/28

1/4 Corner to Sections 7 and 18.
Found - Hemlock 17" S.23°W. 8.8 feet
Set - 2 1/2" Aluminum Cap & one BT:
16" Hemlock N. 68 1/4° W. 55.8 feet

19

Section Corner to Sections 7 - 8 - 17 - 18.
Found - 10" Hemlock N.80 1/2°W. 14.6 ft.
23" Cedar N.17°E. 15.5 ft.
8" Maple S.41°W. 19.8 ft.
7" Yew S.48 1/2°E. 14.8 ft.

20

1/4 Corner to Sections 7 and 8.
Found - Fir Snag 17" diam. S.74 1/2°W. 17.4 ft.
Madrone 13" diam. S.79°E. 18.1 ft.
Set - 17" Cedar N.50 1/2°E. 53.0 ft.
24" Cedar S.53 1/2°W. 27.0 ft.
2 1/2" Aluminum Cap

21

1/4 Corner to Sections 6 and 7.
Found - 15" Madrone N.37 1/2°W. 21.8 ft.
9" Fir S.54°E. 14 ft.
Set - 2 1/2" Aluminum Cap & 2 BT's: 15" Fir S.51°E. 28.2 ft.
11" Cedar N.56°E. 33.5 ft.

22

Center 1/4 For Section 7.
Set - 29" Fir S.46°E. 23.2 ft. 29" Fir N.52°W. 27.1 ft.
2 1/2" Aluminum Cap.

23