

Douglas County Surveyor's Record of  
Government Corners Renewed

28

T. S.

2

R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 21881

John M. Powell  
J. Heritage  
G. Commons  
C.S. 56/25  
March, 1973

Section Corner for Sec. 31, T28-2 and Sec. 36, T28-3 only. 79  
Found - 6" D. Fir, now 8", N.59°W., 21.7 ft. Shows good scar.  
40" Cedar, now stump, S.83°E., 11.9 ft.  
7" Laurel, now 8", N.25°E., 25.9 ft.  
Also truck axle at sec. cor. See Ren. No. 34 in T28-3.  
New BT - 24" D. Fir, S.35°W., 78.6 ft. Scribed T29S R2W S6 CS BT.

3/14/73

Jack Heritage  
G. Commons  
June 6, 1973  
C.S. 56/25

1/4 Corner, Sections 15 and 22. 80  
Found - 36" now 39" Hemlock, snag w/ open face scribe visible  
"1/4 S22 BT.  
24" now 28" Hemlock, alive w/open face scribe visible  
"1/4 S15 BT.  
Set - 1" I. Pipe with brass cap mkd. County Surveyors T 28 S R 2 W  
Office 1/4 S 15  
1973 S 22  
New BT - 10" Yew, S.22°E., 17.6 ft. mkd. "1/4 S22 CS BT.

6/6/73

V. R. Tracy  
J. Heritage  
C.S. 56/34  
7/6/73

Section corner for Secs. 15, 22 and 23 only. 81  
Found - Old squared post with fragmentary scribe mks. tipped over  
over and badly decayed.  
20" now 26" Fir, S.69°W., 19.1 ft. alive, good condition & tagged.  
10" now 11" fir, N.39°W., 10.6 ft. dead, scribe mks. visible on  
unhealed blaze.  
Set - 1" I. P. and brass cap mkd. County Surveyors T 28 S R 2 W  
Office S 15 S23  
1973 S 22  
New BT - 14" D. Fir, N.51 1/2°W., 24.4 ft. mkd. "T28S R2W S15 CS BT"  
Note - This cor. lies 58.7 ft. S.0°14'W., of sec. cor. of  
S15 S23 which is a 1923 GLO brass cap and BT's in good cond.

7/6/73

M. Lenora Ladig, Doug. Co. Surveyors Office  
Jim Cook  
Karen Cheney  
Aug. 2-3, 1976  
C.S. 59/18

Section Corner for Secs. 1 and 12 only. 82  
Found - 1923 GLO Brass cap properly stamped.  
From which:  
A 36" now 45" Fir, bears S.45°W., 16.0 ft. Tree is alive with  
well healed blaze.  
A 36" now 42" Fir, bears N.78°W., 7.4 ft. Tree is alive with well  
healed blaze.  
Corner OK. Did Not Renew. Corner lies approx. 200 ft. South of T28-1 West  
1/4 Cor. Sec.7. Also lies 10 ft. South of Rd. #274.

8/2/76

West 1/4 Cor. for Sec. 7 only T28-1. 83  
Found - A 15" x 12" x 8" Basalt stone with "1/4" on West face.  
A 12" now 21" Hemlock snag bears N.35°E., 22.4 ft. with "1/4 S7  
BT" in cut open blaze.  
A 18" now 27" Hemlock bears West 13.2 ft. with well healed blaze.  
Tree is alive.  
An unrecorded 16" Fir, bears S.60°E., 19.1 ft. Tree is alive with  
visible scribe marks in healing blaze.  
Set - At true corner point: A 1" x 36" I. P. with Brass cap stamped:  
"Douglas Co. Surveyor" T28S  
1976 R2W S 7 1/4  
R 1 W

Placed orig. stone East of cap.  
Note: Cor. lies approx. 200 ft. North of T28S R2W Sec. Cor. for 1 and 12.  
Also approx. 190 ft. North of White post on Rd. #274.

8/3/76

A. Victor Cangie  
Mike Tompkins  
Doug. Co. Surveyors  
Sept. 21, 1976  
C.S. 59/24

1/4 Corner for Sec. 18 only, T28-1 84  
Found - A 12"x9"x5" Stone, (Rec. 10"x6"x4") with "1/4 18" mkd. on east  
face. (See second resurvey and retracement)  
A 16" now 20" Hemlock bears N.13°E., 37.6 ft. Alive & well. Shows  
healed blaze.  
Other trees are gone.  
Set - A 1" x 30" I. Pipe with brass cap stamped:  
DOUGDAS COUNTY SURVEYOR T 28 S R 1 W  
1976 S 18  
1/4  
Replaced stone on south side of brass cap.  
New BT - A 5" Yewwood, bears N.54°E., 10.2 ft. mkd. "1/4 S 18 CS BT".

9/21/76