

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 28 T. S. R 2 R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

90

Section Corner for Secs. 16, 15, 21 and 22.

Found - Stone 24" x 20" x 16" set firmly in the ground marked with three grooves on the east face and three grooves on the south face.

Orig. 7" now 13" Chinquapin Oak (?) snag bears N.21°E., 21.5 ft. scribing visible on partly healed blaze "T28S R2W S15 BT" (Record N.21°E., 19.8 ft.)

Orig. 6" now 22" Hemlock bears N.6°W. 55.9 ft. has a healed blaze. (Rec. N.6°W., 55.44 ft.)

Orig. 48" now 72" D. Fir bears S.72°W., 37.1 ft. Has a healed blaze. (Rec. 35.64 ft.)

Orig. 60" now 65" D. Fir snag bears S.26°E., to center of tree and S.41°E., to center of healed blaze, 3.3 ft. to center of tree. (Rec. S.26°E., 3.3 ft.)

Set - Moving corner stone aside, I set in its place a 2 1/2" brass cap on a 1" iron pipe stamped: County Surveyors Office

T 28 S
S 16 S 15
S 21 S 22
R 2 W
1977

I turned the corner stone over and placed it alongside the brass cap. New BT's-A 11" Yew bears N.60°E., 42.2 ft. scribed "T28S R2W S15 CS BT" on a double blaze.

A 8" Chinquapin Oak bears S.64°E., 43.4 ft. scribed "T28S R2W S22 CS BT" on a double blaze.

Placed county BT signs on all bearing trees.

9/16/77

91

Section Corner for Secs. 17, 16, 20 and 21.

Found - 3" x 7" x 16" stone lying on ground surface with 3 distinct notches on one edge.

A 21" D. Fir (orig. 8" bears N.54°E., 62.04 ft. Has a healed blaze.

A 14" D. Fir (orig. 8" Hemlock) bears N.46°30'W., 29.7 ft. Has a healed blaze.

A 17" D. Fir (Orig. 10") bears S.22°30'W., (Rec. S.17°45'W.) 13.86 ft. Has a healed blaze.

A 20" D. Fir (orig. 14") bears S.44°E., 1.98 ft. Has a healed scar

All are alive and well. Placed County BT signs on all four trees.

Set - 2 1/2" Brass cap stamped County Surveyors Office

T 28 S R 2 W
S 17 S 16
S 20 S 21
1977

No new accessories. Corner lies on a steep SE slope.

9/2/77

92

West 1/4 Corner for Sec. 6 only, T.29-1.

Found - 2 1/2" Brass cap on a 1" I.R. set firmly in the ground with brass cap flush to surface material (duff). This is the W 1/4 corner for Sec. 6 only, T29-1. I add "T29S R1W" to brass cap on East side of stamping 1/4 S6.

A 30" Cedar, bears S.74°E., 12.9 ft. (Rec. 13.2 ft.) Has a healed blaze.

A 18" Hemlock bears N.77°E., 27.3 ft. (Rec. 27.06 ft.) Has a healed blaze.

Condition Report Only. Did not Re-monument.

Placed County BT signs on both trees.

3/16/78

93

SE corner for Section 36 only.

Found - 3 1/2" Brass cap on a 3" I.P. set solidly in ground stamped U.S. General Land Office Survey T28S R2W S36 T29S R1W S6 1922

A 10" Orig. 5" D. Fir with a healed blaze bears N.70°W., Rec. N.73°W.), 2.64 ft. to face & 2.9 ft. to center of tree.

A 24" Orig. 18" Cedar bears N.10°W-, 45.54 ft. Has a healed scar.

Condition report only. Did not re-monument.

Placed County BT signs on both trees.

3/16/78

Dennis Gaylord, U.S.F.S.
Deputy, Douglas County Surveyors Office
Witness: Travis Worthen
Sept. 1977
C.S. 59/40

Dennis Gaylor, U.S.F.S.
Deputy Doug. Co. Surveyors Office
Witness: Randal Lopez
March 16, 1978
C.S. 59/46