

Douglas County Surveyor's Record of  
Government Corners Renewed

T 28 T. S. R 2 R.W.W.M.

HOKE-CHAPMAN CO., EUGENE, ORE. 91881

98

Dennis Gaylord  
U.S.F.S.  
Deputy, Doug. Co.  
Surveyors Office  
Randal Lopez  
March 1978  
C.S. 59/46

1/4 Corner for Sec. 35 only. (South)  
Found - 1923 GLO brass cap on a 1" I.P. stamped U.S. General Land Office  
Survey 1/4 S35 1923. I ADD "T28S R2W" to brass cap above  
the 1/4 S35.  
A 16" D. Fir bears N.23°W., 1.98 ft. has a healed blaze.  
A 17" D. Fir bears N.89°E., 13.8 ft. (Rec. 13.2 ft.) Has a  
healed blaze.  
Placed County BT signs on both Bt's  
No new monument or accessories.

3/23/78

99

1/4 Corner for Sec. 34 only.  
Found - Orig. Corner stone, 12"x12"x18", marked "1/4". Stone is loose  
and lying at top of road cut, directly up-slope from where  
I have determined the true corner point to be.  
A 30" Fir stump bears N.36°30'W., 53.46 ft. (Rec. N.81°30'W.,  
53.46 ft.) Scribing visible on partly healed blaze which  
does face corner, "1/4 S34 BT".  
Stump hole bears N.35°E., 21.12 ft. (Rec. N.36°E., 21.12 ft.)  
Corner for 3 and 2 only, T29-2 bears East 258.01 ft. (Rec.  
S.89°58'E., 253.44 ft.)  
Set - Corner falls in ditch line of road, so I SET a 5/8" x 24" Iron  
Rod at corner point. (F.S. Road #274).  
New BT's-A 11" D. Fir bears N.45°30'E., 14.0 ft. scribed "1/4 S34 CS  
BT" on a double blaze.  
A 12" D. Fir bears N.9°W., 12.5 ft. scribed "1/4 S34 CS BT"  
on a double blaze.  
I bury the orig. corner stone between the new BT's. 4" of the  
stone is above ground & the "1/4" is facing North. The  
Stone bears N.19°E., 12.1 ft.  
A 2 1/2" Brass cap on a 1" I.P. bears East 70.0 ft. from cornr  
point stamped: County Surveyor's Office T28S R2W 1/4 S34

1978

West  
70.0'

4/6/78

100

Section corner for Secs. 34 and 35 only, South boundary.  
Found - Orig. Corner stone, 16"x14"x5" set firmly in the ground  
Stone is marked with 2 grooves on the east edge and 4 grooves  
on the west edge.  
A 32" D. Fir bears N.75°E., 23.76 ft. (Rec. N.73°45'E.,)  
Has a healed scar.  
A 6" Chinquapin is down. Stump bears N.50°W., 21.4 ft. (rec.  
N.49°30'W., 21.78 ft.) Scribing visible on Chinquapin log,  
"T28S R2W S34 BT". Placed BT signs on both trees.  
Set - Moving the corner stone aside, I SET in its place a 2 1/2" Brass  
cap on a 1" I.P. stamped County Surveyor's Office T28S R2W  
1978 S34 S35

I bury corner stone alongside iron pipe.

New BT's-A 17" D. Fir bears N.5°W., 44.4 ft. scribed "T28S R2W S34  
CS BT" on a double blaze. Placed a County BT sign on Fir.

4/13/78

101

1/4 Corner for Sec. 2 only, T29-2. (North)  
Found - 2 1/2" Brass cap stamped U.S. General Land Office Survey 1/4 S2 1917  
is solidly set & brass cap is 12" above ground. I ADD  
"T29S R2W" to brass cap below the "S2".  
A 15" D. Fir bears S.73°30'W., 17.16 ft. (Rec. S.74°W.)  
Has a healed scar.  
A 8" Chinquapin is down. Stump bears S.57°30'E., 17.0 ft.  
(Rec. S.59°E., 16.5 ft.) Scribing visible on down log  
"1/4".  
Placed BT signs on Fir and Chinquapin log.

No new monument set.

New BT - A 16" D. Fir bears S.35°E., 28.7 ft. scribed "1/4 S2 CS BT"  
on a double blaze.

Placed a County BT sign on Fir.

4/13/78

Dennis Gaylor, U.S.F.S.  
Deputy, Doug. Co. Surveyors Office  
Witness, Randal Lopez  
April, 1978  
C.S. 59/46