

Douglas County Surveyor's Record of
Government Corners Renewed

28

T.J.S.

3

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

Section Corner to Sections 7, 8, 17, & 18.

Found - Original 30 inch now 34 inch rotted Fir stump S.58°W., 9.2 feet, shows good face. I do not open.

Original 14 inch now 22 inch Cedar alive, open face, scribed "T.28S, R.3 W., S 8 BT", N.37°E., 29.0 feet.

Original 20 inch now 30 inch Fir stump which I do not open S.65°E., 23.8 feet. All check for bearings & distances. Original N. W. BT not found.

Note- Iron Peg reported as found by Forest Appraisal at this corner not found today.

Set Brass Cap at corner marked County Surveyor's Office, 1957. $\frac{S 7}{S 18} | \frac{S 8}{S 17}$ T.28S, R.3W.

New Bearing Trees: 22 inch Cedar N.37°E., 29.5 feet scribed T.28S, R.3W, S8 CS BT.

14 inch Maple S16°W.42.2 ft. scribed T.28S, R.3W, S 18 CS BT.

18 inch Cedar N.39½°W.64.9 ft. scribed T.28S, R.3W, S 7 CS BT.

22 inch Cedar S.40½°E.82.0ft. scribed T.28S, R.8W, S 17 CS BT.

Oct. 4, 1957

¼ Section Corner between 9 & 16.

Found - Both original BTs & broken stone at corner marked ¼ on East Face.

Original 48 inch now 48 inch R.Fir S.48°E., 25.1 feet shows scribing on loose bark "¼ S BT".

Set Brass Cap at corner marked ¼ $\frac{S 9}{S 16}$ T.28S., R.3W., County Surveyor's Office, 1957

New Bearing Trees: 10 inch Ewood bears S.48°E., 76.5 feet scribed

¼ S.16 CS BT.

14 inch Cedar bears N.70½°E., 11.5 feet scribed

¼ S.9 CS BT.

Oct. 7, 1957

¼ Section Corner between 7 & 18.

Found - Both original BTs. The 7 inch now 14 inch Cedar N.20°W., 25.7 feet. Has open face scribed "¼S".

The 12 inch now 18 inch Cedar S.61°E., 27.7 feet. Shows good faces.

I do not open. Both check for Bearings & distances.

Set Brass Cap at Corner Marked ¼ $\frac{S 7}{S 18}$ T.28S., R.3W. County Surveyor's Office, 1957

New Bearing Trees: The original S.E. BT is alive and in good condition.

I do not scribe new BT in Section 18.

14 inch Cedar N.30½°W. 50.0 ft. scribed ¼ S 7, CS BT.

Note-I find 3"X3" scribed Cedar stake S.27°W., 3.1 ft. from corner; seems to be old.

Oct. 8, 1957

Section Corner to Section 8, 9, 16, & 17.

Found - Original 30 inch Cedar now 36 inch. Open face scribed "T.28S, R.3W, S. 8 BT" N.37°W., 42.9 feet.

Original 5 inch Hemlock now 10 inch. Open face scribed "R.3W., S.9" N.63°E., 29.7 feet.

I also find Cedar stump that checks size, bearing & distance for original S.E. BT. broken off near ground. No scribing found.

Set Brass Cap at corner marked T.28S, R.3W. $\frac{S 8}{S 17} | \frac{S 9}{S 16}$ County Surveyor's Office, 1957.

New Bearing Trees: 18 inch Hemlock bears S.5°E., 13.6 feet scribed,

S. 16, T.28S, R.3W., CS BT.

13 inch Hemlock bears S.82½°W., 44.4 feet scribed,

S. 17, T.28S, R.3W., CS BT.

36 inch Cedar(orig) N.38°W., 44.2 feet. I rescribe,

S. 8, T.28S, R.3W., CS BT.

The N.E. original BT is in good contition. I find the bearing & distance should be N.65°W., 29.7 feet.

Oct. 7, 1957

¼ Section Corner to Sec. 18, T28S R3W, & Sec. 13 T28S R4W.

No evidence of orig. corner. Found J.R. Markham's Corner and Remove 1" I.P. set by Markham for ¼ Corner & remeasure(bearings & distances) to BTs. Rescribe S.E. BT. R4W R3W

Set Brass Cap midway between Sec. Corners on Line mkt: $\frac{S 13}{S 17} | \frac{S 18}{S 16}$ T28S County Surveyor's Office, 1955

New BTs: 22" Maple N.35°53'W. 105.82 ft. scribed ¼ S BT.

12" R.Fir S.82°15'E. 163.7 ft. scribed ¼ S18 CS BT.

7

#132

RE-OPENED CORNER NO.

James W. Byron, Deputy County Surveyor
M. Godfrey
S. Blaw
For Office Records
C. S. File No. 49/22
October, 1957

8

9

#133

RE-OPENED CORNER NO.

112

11

RE-OPENED CORNER NO.

James W. Byron
For B.D. Randall
Sept. 23, 1955
CS File No. 47/31
M 8 - 9

28