

Douglas County Surveyor's Record of
Government Corners Renewed

T. 28 S. T. S. R. 3 W. R. W. W. M.

KOIKE-GHAPMAN CO., EUGENE, ORE. 21881

128

Center $\frac{1}{4}$ Corner Section 30.
Set - $\frac{5}{8}$ " Iron Rod
Bearing Trees: 20" Madrone bears N.25°E. 17.2 ft., marked.
24" Madrone bears S.10°W. 53.4 ft., marked.

129

$\frac{1}{4}$ Corner to Sections 19 and 30.
Set - 1" x 30" Iron Pipe with Brass Cap.
Found - 17" Douglas Fir bears N.49°E. 13.9 ft. rescribed at this time.
20" Douglas Fir bears S.18°W. 9.2 ft., rescribed.

130

$\frac{1}{4}$ Corner to Sections 31 and 30. (Witness Corner)
Set by proportionate measurement.
Set Wit. Corner bears N.89°16'16"W. 126.0 ft. from which bears:
16" White Fir S. 5° W. 5.3 ft.
8" White Fir N.70°W. 4.3 ft.
Set - 1" x 30" Iron Pipe with Brass Cap
Marked 14" Alder bears S. 20° W. 32.0 feet.

131

Section Corner for Sec. 36, T28-3 and Sec. 31, T28-2 only
Found - 6" D. Fir, now 8", N.59°W., 21.7 ft. Shows good scar.
40" Cedar, now stump, S.83°E., 11.9 ft.
7" Laurel, now 8", N.25°E., 25.9 ft.
Also truck axle at sec. oor. Ren. No. 34
New BT - 24" D. Fir, S.35°W., 78.6 ft. Scribed T29S R2W S6 CS BT.

132

Section Corner for Secs. 7, 8, 18 and 17.
Found - 1957 County Surveyors brass cap, properly marked, and firmly set.
From which: Ren. #7
An orig. bearing tree, a 14" now 24" Red Cedar, bears N.37°E., 29.0 ft with portions of orig. scribing and 1957 rescribing visible on unhealed blazes.
An O.B.T., a 20" Fir, now a 30" stump, bears S.65°E., 23.8 ft. no marks visible.
An O.B.T., a 30" Fir, now a 34" stump, bears S.58°W., 9.2 ft. good scar visible.
The orig. NW bearing tree is gone.
The SE and SW bearing trees marked in 1957 have been destroyed.
The NW bearing tree marked in 1957, an 18" Cedar, now a 20" stump, bears N.39 1/2°W., 64.9 ft.
New BT's A 12" D. Fir, bears S.7°E., 5.4 ft. scribed "T28S R3W S17 CS BT".
A 10" D. Fir, bears S.37 1/2°W., 10.4 ft. scribed "T28S R3W S18 CS BT".
A 7" Grand Fir, bears N.82 1/2°W., 12.4 ft. scribed T28S R3W S7 CS BT.
Note - This corner is located approx. 75 ft. north of north Myrtle County Rd
Compass declination setting: 20° east.

133

$\frac{1}{4}$ Corner for Secs. 7 and 18.
Found - 1957 County Surveyors brass cap properly marked. Ren. #9
From which:
An orig. bearing tree, a 12" now 18" Incense Cedar, bears S.61°E., 27.7 ft. alive and well healed.
The orig. NW bearing tree has been destroyed.
A 14" Cedar marked by the County Surveyor in 1957, now a 20" stump, bears N.30 1/4°W., 50.0 ft. with scribing "BT" visible.
New BT - A 14" Red Cedar bears S.57°W., 18.8 ft. scribed "1/4 S18 CS BT".
Note - This corner is located approx. 100 ft. east of BLM Rd. #28-4-132.
Compass declination setting: 20° east.

134

Section corner for Secs. 5 & 6 only, T.29-3
Set - $1\frac{1}{2}$ " x 34" Iron pipe with brass cap
From which:
A 6" Madrone bears S.53°W., 26.5 ft. mkd. T29S R3W S6 BT.
A 6" Cedar bears S.70 3/4°E., 37.3 ft. mkd. T29S R3W S5 BT.

Glenn S. Baughman
For Sun Studs
July, 1971
C.S. File M 43 - 19

John M. Powell
J. Heritage
G. Commons
C.S. File 56/25
March, 1973

County Surveyors Office

Gary L. Langlitz
Peter L. Earle
Jan. 23, 1975
C.S. 57/17

FILE OK 11/93
M 119-11

RE-SET THE CORNER NO. 178

FILE OK 11/93
M 119-11
By EDWARDS
M 128-70

Burton W. Holt
For: Sun Studs
April 19, 1976
M 59 - 77

3-72

4/76