

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 28                      T. S.                      R 3                      R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

Victor M. McLind  
RL #934  
For: Umpqua National Forest  
Sept. 1978  
M 70 - 36

Center 1/4 corner for Section 24.  
Set - 2" x 30" Galv. I.P. with a 3" brass cap stamped T28S R3W C 1/4  
S 24 RLS 934 1978.  
From which:  
8" Hemlock bears S.41°15'E., 14.6 ft. I blazed & scribed "C 1/4  
S 24 BT".  
8" Hemlock bears N.44°E., 10.4 ft. I blazed & scribed "C.1/4  
S 24 BT".

**RE-RENEWED, SEE CORNER NO. #159**  
**145**  
1-79                      9/78

East 1/4 Corner for Section 12 only. See Ren. #26 A in T.28-2  
Found - 1 1/2" I.P. with 1962 county brass cap. (no record)  
4" x 4" wood post.  
18" Cedar snag, N.71°W., 27.11 ft. visible scribes  
9" Hemlock, S.61°W., 9.3 ft. good marks  
New BT - 11" Cedar, S.24°E., 8.1 ft. "E 1/4 S12 BT". Brass washer RLS #1005  
in BT face.  
Set fiberglass post and sign N.45°W., 2.0 ft.

**146**

CC corner for Secs. 7 and 18 only of T.28-2.  
Found - 1" iron pipe with alum. cap marked U.S.P.C. prop.cor. T28S S12  
R3W R2W 7c 18c RE 4287. Ren. #116  
26" stump, N.32°W., 26.1 ft.  
40" D. Fir S.60°E., 29.0 ft.  
24" stump, N.82°W., 56.1 ft.  
Corner bears 4.76 ft. west of line.  
New BT - 12" Maple, N.49°E., 51.8 ft. "T28S R2W S7 CC BT". Brass washer  
RLS 1654 in BT face.

3/80  
**147**

1/4 Corner for Sec. 13 only (east side)  
Set - 2 1/2" I.P. with brass cap marked RLS 1654 T28S R3W 1/4 S13  
T28S R2W 1980.  
New BT's- 7" Hemlock, N.40°W., 10.0 ft. "E 1/4 S13 BT"  
9" Madrone, S.85°E., 7.2 ft. "E 1/4 S13 BT"  
Brass washers in BT faces - RLS 1005

**RE-RENEWED, SEE CORNER NO. #165**  
**RE-RENEWED, SEE CORNER NO. #164**

**148**

CC corner for Secs. 18 and 19 only T.28-2.  
Set - 2 1/2" I.P. with brass cap marked RLS 1654 T28S R3W S13 S18C S19C  
T28S R2W 1980.  
New BT - 7" Hemlock, N.35°W., 16.4 ft. "S19 CC T28S R2W BT" - brass washer  
RLS 1654 in BT face.  
Set fiberglass post and signs 6.0 ft. south.  
Found - stone 1.94 ft. west of line - set brass cap at location of stone  
buried stone alongside. See Ren. #78  
13" Hemlock bears S.43°E., 5.0 ft. from stone - good face  
20" D. Fir bears N.25°E., 23.0 ft. from stone - visible scribes

**149**

Township corner for Sec. 1 and Secs. 6 of T.28-2; Sec. 31 of T.27-2  
and Sec. 36 of T.27-3  
Found - 1" iron pipe with 1962 County surveyors brass cap. Ren. #70  
11" D. Fir, N.14°W., 19.7 ft. good scar  
14" Madrone snag, S.3°E., 17.0 ft. visible scribes  
22" Cedar, S.27°W., 72.8 ft. visible scribes.  
New BT - 7" D. Fir, N.27°E., 35.3 ft. "T27S R2W S 31 BT"  
Set fiberglass post 3.0 ft. south BT has brass washer RLS 1005 in face.

**RE-RENEWED, SEE CORNER NO. #156**

3/80  
**150**

1/4 Corner for Sec. 1 only. (East)  
Found - 1962 County Surveyors brass cap on 1 1/4" I.P.. Ren. #70  
12" Cedar stump, S.60°E., 120.2 ft.  
Fiberglass post and signs 4.0 ft. north and south.  
New BT's- 10" Pine, S.10°E., 25.8 ft. "1/4 S1 BT"  
9" Cedar, S.76°E., 15.5 ft. "1/4 S1 BT"  
No trees in section 1. Brass washers in BT faces RLS 1005.

3/80  
**151**

Ronald A. Quimby LS #1654  
BHW, Engineering  
For: U.S. Forest Service  
March 1980  
M 83 - 19

Ronald A. Quimby  
BHW, Engineering  
For: U.S. Forest Serv.  
March 1980  
M 79 - 37