

Douglas County Surveyor's Record of
Government Corners Renewed

T. 28 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Cont. from previous
page

Set Brass Cap at Cor. Mkd: County Surveyor's Office, 1962. East $\frac{1}{4}$ S 1 T28S R3W R2W

New BT's: 15" Fir bears S. 61°W. 31.9 ft. scribed $\frac{1}{4}$ S 1 CS BT.
13" Cedar bears N. 59 $\frac{1}{2}$ °W. 19.3 ft. scribed $\frac{1}{4}$ S 1 CS BT. #151

Renew S36 | S31 T27S
R3W S 1 | S 6 R2W T28S

Found - All Orig. BT's. All are now stumps. N.E. BT. shows good scbng. "3".
Also find Rock Mound at Corner.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962. S36 | S31 T27S R3W S 1 | S 6 R2W T28S

New BT's: 16" Cedar bears S. 27°W. 72.0 ft. scribed S1 T28S R3W CS BT.
17" Laurel bears S. 3°E. 17.0 ft. scribed S6 T28S R2W CS BT.
4" R. Fir bears N. 10°W. 19.8 ft. scribed S36 CS BT.
9" R. Fir bears N. 87°E. 50.1 ft. scribed S31 CS BT T27S R2W.

FOUND O.K. Nov. 1968 VRT.

South $\frac{1}{4}$ Corner Section 36 only, T27-3W. #150 71

Found - Both Orig. BT's. Orig. N.E. BT., now down. Orig. 20", now 38"
R. Fir S. 53°E. 52.1 ft., shows good bark scribing.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962. South $\frac{1}{4}$ S36 T27S R3W.

New BT's: Rescribe O. BT. 38" R. Fir S. 53°E. 54.9 ft. $\frac{1}{4}$ S CS BT.
5" R. Fir bears N. 66°W. 24.4 ft. scribed $\frac{1}{4}$ S36 CS BT.

Note - Corner is at Base of Laurel Stool.

3 Renewed Corners listed directly below are corners renewed by U. S. Plywood, 1961 but not recorded: #114 73

Corner to Section land 12 only, T28-3W.

Found - $\frac{3}{4}$ " Iron Pipe with aluminum cap at Cor. Mkd: U.S.P.C. Prop. Cor. 1961 S1 | S7 T28S R3W S12 | S7 R2W

Orig. 30", now 36", Fir Snag S. 70°E. 30.4 ft., no scribing found.

Orig. 30", now 40" Fir N. 5°W. 38.3 ft., shows good bark scribing.

New BT's: 1961: 7" W. Fir N. 15 $\frac{1}{2}$ °W. 46.9 ft. scribed T28S
12" W. Fir S. 16°W. 18.5 ft. scribed T28S R3W S12 BT.
13" W. Fir S. 84°E. 16.6 ft. scribed T28S R2W S7 BT.

Renewal of Closing Corner for Sections 6 and 7, T28-2W. #113 (found 1962) visit 74

Found - Orig. 16", now 30" Cedar N. 82°E. 31.7 ft., shows good scribing.

Also find Stump Hole for Orig. S.E. BT.

Find $\frac{3}{4}$ " I. Pipe with aluminum cap at corner.

1961 BT's: 25" Cedar S. 29°E. 42.2 ft. scribed T28S R2W S7 BT.

11" W. Fir N. 34°W. 12.4 ft. scribed T28S R3W S1 BT.

7" Fir N. 63°W. 43.0 ft. scribed T28S R2W S6 BT.

Renewal of Closing Corner for Sections 7 and 18, T28S-R2W. #116 75

Found - Aluminum cap on Pipe at corner set by U. S. Plywood, 1962

We also find both Orig. BT's. in good condition, show scars.

New BT: 21" Fir bears N. 32°W. 26.1 ft. scribed S12 T28S R3W CC BT.

Corner to Sections 12 and 13 only, T28-3W.

Found - All Orig. BT's., except S.E. BT. Orig. 10", now 30" Cedar N. 50°W. 6.0 ft., shows scar. I do not open. #116 76

Orig. 8", now 14" Fir N. 50°E. 2.0 ft., opened to old face, scribing destroyed, see record of 1910 survey.

Orig. 10", now 30" Cedar shows scar.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1962 S12 | R3W S13 | R2W T28S

New BT: 8" R. Fir bears S. 37°W. 34.4 ft. scribed S13 T28S R3W CS BT.

James W. Byron, Deputy County Surveyor
John Powell and Wm. Stoffel
August and September 1962
C. S. File No. 52/126

FD OK 3/88
BHW ENG.
1182-19