

Douglas County Surveyor's Record of
Government Corners Renewed

T. 28 S. T. S. R. 3 W. R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Corner to Sections 22 and 23 only. 92

Found - BT's. & Road at Corner as recorded by Shrum. REN. #22

Except N.E. BT., now stump, shows scribing.

New BT: 18" Hemlock bears S.31°E. 32.1 ft. scribed S23 T28S R3W CS BT.

Section Corner to Sections 3 - 4 - 9 - 10. 93

Found - Orig. 32", now 36" Fir, down, S.30°W. 32.3 ft., shows old bark scribing "S". No other O.BT's. found. We do find, now 15" Hemlock bears N.61°E. 22.0 ft., scribed about 50 yrs ago, about 6" diam. when scribed. Also find 12" Hemlock bears N.43°W. 26.8 ft. scribed about 40 years ago and about 6" diam. when scribed.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962 $\frac{S4}{S9} \frac{S3}{S10}$ T28S R3W

New BT's: 15" Hemlock bears N.61°E. 22.0 ft. scribed T28S R3W S3 CS BT.

6" Hemlock bears S.78°E. 11.7 ft. scribed S10 CS BT.

9" Hemlock bears N.30°W. 29.0 ft. scribed S4 CS BT. T28S R3W

7" Cedar bears S.81°W. 47.5 ft. scribed S9 CS BT.

Jan. '69 - (Set - 5' Metal Fence Post at Cor. by Thomas Shrum, See C.S. File No. 51/254)

$\frac{1}{4}$ Corner to Sections 5 and 4. 94

Found - Stump of Orig. N.E. BT. & Orig. 30", now 36" Fir, previously opened, shows good scribing N.45°W. 17.8 ft.

Also find at Corner, Stone, as recorded.

Note - Log. Road is about 200 ft. East & small stream about 30 ft. South of $\frac{1}{4}$ Corner.

Set - Brass Cap at Cor. & alongside Corner Stone & Mkd: County Surveyor's Office, 1962 $\frac{1}{4}$ S5/S4 T28S R3W.

New BT: 7" Hemlock bears N.18 $\frac{1}{2}$ °E. 64.9 ft. scribed $\frac{1}{4}$ S4 CS BT.

$\frac{1}{4}$ Corner to Sections 10 and 15. 95

Found - Orig. 6", now dead, 10" Cedar N.22°W. 5.9 ft., shows good scribing " $\frac{1}{4}$ ". Orig. S.E. BT., down & out of place.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962 $\frac{1}{4}$ $\frac{S10}{S15}$ T28S R3W

New BT's: 18" Cedar bears N.27°W. 19.2 ft. scribed $\frac{1}{4}$ S10 CS BT.

6" Yewood bears N.31°E. 55.0 ft. scribed $\frac{1}{4}$ S10 CS BT.

No trees near to South.

Corner is at West edge of old logging road.

$\frac{1}{4}$ Corner to Sections 3 and 10. 96

Found - Orig. 14", now 20" R. Fir N.4°E. 35.0 ft., shows good bark scrbing.

Orig. S. W. BT., now down.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962 $\frac{1}{4}$ $\frac{S3}{S10}$ T28S R3W

New BT's: 10" R. Fir bears N.60°W. 43.0 ft. scribed $\frac{1}{4}$ S3 CS BT.

19" Laurel bears S.23°W. 49.6 ft. $\frac{1}{4}$ S10 CS BT.

Note - Log. Road is 65 ft. North of $\frac{1}{4}$ Corner.

$\frac{1}{4}$ Corner to Sections 2 and 11. 97

Found - Orig. 36", now 46" Cedar S.5°E. 66.6 ft. We open & find good scrbing.

Orig. N.E. BT., now down & rotted.

Also find $\frac{3}{4}$ " I. R. at Corner.

New BT's: 10" Hemlock bears S.22°E. 3.0 ft. scribed $\frac{1}{4}$ S11 CS BT.

14" Cedar bears N. W. 8.9 ft. scribed $\frac{1}{4}$ S2 CS BT.

Section Corner to Sections 2 - 1 - 11 - 12 98

Found - Orig. 14", now 27" Fir S.30°E. 25.7 ft., shows good bark scrbing.

No other Orig. BT's. found - Find $\frac{3}{4}$ " I. R. at Corner.

Note - Call to Cavitt Creek to East, checks O.K. 121

New BT's: Rescribe, now 27" R. Fir S.30°E. 28.4 ft. S12 T28S R3W CS BT.

24" W. Fir bears N.13 $\frac{1}{2}$ °E. 11.2 ft. scribed S1 T28S R3W CS BT.

10" W. Fir bears S.21°W. 26.0 ft. scribed S11 T28S R3W CS BT.

8" Yewood bears N.5°W. 28.8 ft. scribed S2 CS BT.

James W. Byron, Deputy County Surveyor
John Powell and Wm. Stoffel
August and September 1962
C. S. File No. 52/126