

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 4 R. W. W. M.

20

SECTION CORNER BETWEEN SECTIONS 12 and 13.
Identified by one O.B.T. properly marked. Original notes call for two firs. Found one Hemlock N.10°W., 20 lks. Set post for corner. New B.T.s as follows.
Yew 10" dia. bears N.83°W., 20.9 ft.
Cedar 15" dia. bears S.69°W., 56.8 ft.

21

SECTION BETWEEN SECTION 13 and 14.
Identified by old Hemlock stump carrying scribe marks and a 36" fir which bears proper scars which I did not chop out. Set Post for corner and marked a Hemlock 10" dia. bears S.54°10'W., 15.9 ft. I remarked O.B.T.
Leaning Fir 36" dia. bears N.35°E., 36.8 ft.

22

SECTION CORNER BETWEEN SECTIONS 22 and 23.
Location identified by Laurel B.T. which on being chopped out showed original scribe marks. Also hole where other recorded B.T. stood. Set 6" x 6" x 48" Yew wood post, scribed $\frac{1}{4}$ S. 23 on E. face, $\frac{1}{4}$ S. 22 on W face, and C.S. on S. face for corner. Marked the following trees
Laurel 16" dia. bears S.88°E., 32 lks. O.B.T.
Fir 32" dia. bears N.10°22'E., 46.5 lks. bark scribed $\frac{1}{4}$ S. 23 C.S.B.T.
Fir 36" dia. bears N.81°20'W., 55.1 lks. scribed $\frac{1}{4}$ S. 22 C.S.B.T.

23

CORNER ON NORTH SIDE OF SECTION 6
I reestablished from original B.T. in section 31. As this tree is small and the marks are partly obliterated I remarked this corner as follows, set a White Oak post 4 x 4 x 36", marked $\frac{1}{4}$ S. S. 6 28 S. 4 " from which
White Oak 6" dia. marked C.S. $\frac{1}{4}$ S. S.6 B.T. bears S.28°W. 68 links
Red Fir 14" dia. marked C.S. $\frac{1}{4}$ S. S.6 B.T. bears N.72°E., 38 links.

24

CORNER BETWEEN SECTIONS 6 and 7.
Set Post for $\frac{1}{4}$ Section Corner 4 x 4 x 36 marked C.S. $\frac{1}{4}$ S.6 S.7 from which
A Red Fir 36" dia. marked C.S. $\frac{1}{4}$ S. S.6 B.T. bears N.50 $\frac{1}{2}$ °E., 21 $\frac{1}{2}$ lks.
A Red Fir 48" dia. marked C.S. $\frac{1}{4}$ S. S.7 B.T. bears S.83°W., 49 lks.

25

CENTER OF SECTION 6
Center post of Section 6 marked C.S. 40.10 chains S.89°20'E. from $\frac{1}{4}$ section post in W. Bdy. of Section 6 from which
A Red Fir 26" dia. marked C.S.B.T. bears N.67°W., 27 lks.
A Red Fir 22" dia. marked C.S.B.T. bears N.72 $\frac{1}{2}$ °E., 33 lks.

26

CORNER BETWEEN 26 and 27.
Set from O.B.T. Laurel S.55°E., 61.6 ft. Set 1 $\frac{1}{2}$ " x 20" I Bar for corner from which the following trees bear
A Fir 12" dia. bears S.55°W., 4.3 ft. marked $\frac{1}{4}$ S.27 C.S.B.T. SEE GOV'T NOTES - BLM BRASS CAP
A Fir 18" dia. bears S.33°30'E., 29.7 ft. marked $\frac{1}{4}$ S.26 C.S.B.T.

27

CORNER BETWEEN 23 and 26.
Set from O.B.T. Fir S.15°E., 33 lks. marks plain. Set Stake for corner from which
A Fir 16" dia. bears S.1°E., 30.4 ft. marked $\frac{1}{4}$ S. C.S.B.T.
A Fir 24" dia. bears N.34°W., 30.8 ft. marked $\frac{1}{4}$ S. C.S.B.T.

Ben. B. Irving D.C.S. Ben B. Irving
May 16-17, 1927
Wit.
R. L. Irving
J.R. Stronss
J. Moore

C. C. Boyer Dep. Co. Sur.
June 18-20, 1913
FOR L. Hatfield
Vol. 2 F1240 Book 35 Pg 3-11
Vol. 2 Pg 175
Vol. 2 Pg 174
Pg. 176

H. L. Eppstein Co. Sur.
Set Apr. May and Aug.
Wit. Bert Lene
Stuer
Frank Cain Vol. 4 Pg. 23
Jack Morris
Thackery

RENEWED CORNER NO. 70
RENEWED CORNER NO. 76
RENEWED CORNER NO. 61
RENEWED CORNER NO. 41

1958 BLM BRASS CAP
SEE GOV'T NOTES