

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 4 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

51
 $\frac{1}{4}$ corner to secs. 27 and 28.
Found - 12 inch Fir (now 30 inches) N.78°E., 11.9 feet. I open and find good scribing. The N.W. BT down. I use N.E. BT to fix position of corner. Set an iron pipe with brass cap at corner point mkd. $\frac{1}{4}$ S 28/27 T28S R4W, County Surveyors Office, 1957.

From which:

16 inch Fir bears S.24°W., 27.9 feet mkd. $\frac{1}{4}$ S 28 CS BT.
6 inch Cedar, bears S.76°E., 41.1 feet mkd. $\frac{1}{4}$ S 27 CS BT.

James W. Byron,
Dep. Co. Surveyor
April-May, 1957.
C. S. File No. 47/180

52
West $\frac{1}{4}$ Section Corner to Section 19. (Twp. Line) Det. by O.B.T.
13" W. O. Stump bears S. 2°E. 389.8 ft. O.B.T.
26" W. O. bears N.15°E. 155.0 ft. Found Scribe. O.B.T.
At Corner Point set 2"X 24" Iron Pipe in Mound of Stone from which:
8" W. O. bears N.10°E. 146.5 ft. dist. mkd. $\frac{1}{4}$ S19 B.T.
6" W. O. bears N.43°E. 51.6 ft. dist. mkd. $\frac{1}{4}$ S19 B.T.
9" W. O. bears N.32°W. 50.0 ft. dist. mkd. $\frac{1}{4}$ S24 B.T.
20'X 20'X 6' High Rock Mound in Saddle of Main Ridge bears N.52°W. 245.0 ft.

Note: The most Southerly B.T. should have been at 343.0 ft. but I find it at 389.8 ft.
There is a difference of 47.0 ft.
Note also that Government on rechainning found South $\frac{1}{2}$ Mile 52.7 ft. long.

John Markham, Jr.
For Stomar Lbr. Co.
Oct. 21, 1957
C. S. File No. 42/316

~~$\frac{1}{4}$ Section Corner to Sections 2 & 1. SHOULD BE IN T 28 S. R. 5 W
By Proportional Measurement.
Set Brass Cap at corner marked $\frac{1}{4}$ S2/S1 T28S. R5W. County Surveyor's Office, 1957
N.W. Corner brick house bears S.40°15'W. 57.4 ft.
N.E. Corner of house bears S.21°E. 47.1 ft.
Found boat spike set by County Road Engineers for road intersection bears N.0°30'W. 31.9 ft.
No suitable trees near for Bearing Trees.~~

Section Corner to Sections 7 & 18, T28S R4W; Sections 12 & 13, T28S R5W.
Found - Wire fence corner, fence to North & fence to East. I find 48" Fir Stump S.33°E. 44.2 ft. (Record distance & bearing). Shows real old axe marks. All other original BTs. gone.
Also find $\frac{1}{2}$ " I. Rod at fence corner.
Note: See File for signed statement by Wm. Melton.
Set Brass Cap at side of $\frac{1}{2}$ " I. Rod marked $\frac{1}{2}$ S12/S7 R4W T28S County Surveyor's Office, 1957.
New BTs: 14" Myrtle bears S.11°W. 46.7 ft. scribed S13 T28S R5W.
6" Fir bears N.84 $\frac{1}{2}$ °W. 138.8 ft. scribed S12 T28S R5W CS BT.

James W. Byron, Dep. County Surveyor
M. Godfrey
S. Blilow
November, 1957
C. S. File No. 49/21

53
54
Section Corner to Sections 6 & 7 T28S, R4W; Sections 1 & 12 T28S, R5W.
Found - Orig. 18" now 30" B.O. S.38°W. 13.2 ft. now down & partly rotted I open & find reverse scribing "BT".
Also find stump holes for N.E. & N.W. orig. BTs.
Fence corner bears S.53°W. 6.0 ft.
Set Brass Cap at corner marked $\frac{1}{4}$ S1/S6 T28S County Surveyor's Office, 1957.
New BTs: 18" B.O. bears S.77°E. 27.1 ft. scribed S7 T28S R4W CS BT.
16" Laurel " N.66 $\frac{1}{2}$ °W. 82.1 ft. scribed S1 T28S R5W CS BT.
18" Laurel " N.13°E. 87.8 ft. scribed S6 T28S R4W CS BT.
No trees near in S. W. Quad.

55
Set Witness Corner for $\frac{1}{4}$ Corner 12 & 7.
No Original BTs. found. Position of $\frac{1}{4}$ Corner fixed by Survey Section 12. $\frac{1}{4}$ Corner falls in small stream.
Set Brass Cap 10.0 ft. North marked Wit. Cor. 10°S. to $\frac{1}{4}$ cor. S12/S7. T28S County Surveyor's Office, 1957
New BTs: 15" Maple bears N.62 $\frac{1}{2}$ °W. 30.5 ft. scribed WC $\frac{1}{4}$ S12 CS BT.
5" W. Oak " S.30° E. 48.0 ft. scribed WC CS BT.