

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 4 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

$\frac{1}{4}$ Section Corner to Sec. 13, T28S R4W, & Sec. 18, T28S R3W. **DUPLICATE**
No evidence of Original Corner. Found J.R. Markham's Corner & remove
1" I. Pipe set by Markham for $\frac{1}{4}$ corner & remeasure (bearings & distances)
to BTs. Rescribe S.E. BT.
Set Brass Cap midway between Section Corners on Line Marked: R4W R3W
County Surveyor's Office, 1955 T28S S13/S18
New BTs: 22" Maple N.35°53'W. 105.82 ft. scribed $\frac{1}{4}$ S BT.
12" R.Fir S.82°15'E. 163.7 ft. scribed $\frac{1}{4}$ S18 CS BT.

James W. Byron
For B.D. Randall
Sept. 23, 1955
C.S. File 47/31
M 8 - 9

$\frac{1}{4}$ Section Corner to Sections 34 & 35. **62**
Found - $\frac{1}{2}$ " Iron Pipe at Corner & Both BT's. as recorded by Stewart, 1922.
24", now 30" Fir N.26 $\frac{1}{2}$ °E. 49.0 ft., has good bark scribing,
 $\frac{1}{4}$ CS BT". Ren.#12
The S. W. BT., now stump only, bark gone, no scribing found.
Set Brass Cap alongside $\frac{1}{2}$ " Iron Pipe Mkd.: $\frac{1}{4}$ S34/S35 T28S R4W County
Surveyor's Office, 1958. *FD 029/8
S. Howell
M 96-40*
New BT's: 22" R.Fir bears S.49°E. 46.4 ft. scribed $\frac{1}{4}$ S35 CS BT.
13" Cedar bears N.35°E. 48.7 ft. scribed $\frac{1}{4}$ S35 CS BT.
Note: No Trees near to West.

James W. Byron
M. Godfrey
S. Bilow
May 15, 1958
C.S. File No. 49/67

Section Corner to Secs. 4 & 5, T28S R4W, & Sec. 32 & 33, T27S R4W. **63**
Found - $\frac{3}{4}$ " Iron Pipe set by Frear. Ren.#1
Part of Base of old Laurel that checks bearing & distance
for Orig. S.W. BT., center burned, no scribing found.
No other Original BT's. found. This area burned last year.
Set Brass Cap alongside of Iron Pipe Mkd: County Surveyor's Office, 1959. **103**

S32	S33	T27S	R4W
S 5	S 4	T28S	

New BT's: 12" Cedar bears S.53 $\frac{1}{2}$ °W. 99.9 ft. scribed S 5 T28S R4W CS BT.
34" R.Fir bears N.79°W. 37.0 ft. scribed S32 T27S R4W CS BT.
8" R.Fir bears S.56 $\frac{1}{2}$ °E. 75.4 ft. scribed S 4 T28S R4W CS BT.
8" Cedar bears N.44 $\frac{1}{2}$ °E. 118.5 ft. scribed S33 T27S R4W CS BT.

James W. Byron, Deputy
Milo Godfrey
S. A. Bilow
Jan. 23, 1959
C.S. File No. 49/130

Section Corner to Sections 5, 6, 7, & 8. **64**
Found - All Four BT's. as scribed by Markham, 1951. Ren.#35
Also find Orig. 15", now 20" Laurel, previously opened,
shows good scribing "S 7 T28S R4W". Markham used this
BT. for the Orig. S.E. BT. I believe it is the Orig.
S.W. BT. Not only is it marked for the S.W. BT., but
faces to N.E.
Find no other Orig. BT's., except I do find, now 40" Laurel
bears (N.40°W) 23.1 ft., record 20" Laurel N.10°W. 23.1 ft.,
center rotted, no scribing found.
Find 60" R.Fir, bark blazed & bark scribed "S S / 9 0" bears
S.80°E. 36.0 ft., real old scribing, no record of
this B.T.
Note - I destroy all scribing by Markham and Set Brass Cap at
True Corner Mkd: County Surveyor's

S 6	S 5	T28S R4W
S 7	S 8	

Office, 1959
Note - Markham's Corner N.84°W. 25 ft.
New BT's: 20" R. Fir bears S.3°E. 14.0 ft. scribed S8 T28S R4W CS BT.
12" R.Fir bears S.17°W. 15.8 ft. scribed S7 T28S R4W CSBT.
56" R.Fir bears N.69°E. 51.8 ft. scribed S5 T28S R4W CS BT.
10" R.Fir bears N. 6°W 22.3 ft. scribed S6 T28S R4W CS BT.

James W. Byron, Deputy
S. A. Bilow
April 20, 1959
C. S. File No. 49/67

Section Corner to Secs. 17-18, T28-4W, & Secs. 12-13, T28-5W. **65**
Found - Brass Cap at Corner and N.W. BT. S.W. BT. gone. D7 Cat
at location of S.W. BT. This area cut up by new
Cat Road. See Ren.#53
New BT: 10" R.Fir bears S.56 $\frac{1}{2}$ °W. 135.7 ft. scribed T28S R5W S13 CS BT. **112**

James W. Byron, Deputy
Milo Godfrey
Glete Putnam
March 7, 1961
C.S. File
No. 49/64

REC. SW
FD 7/19
G. Bingham
M 113-49

RE-RENEWED CORNER NO. 112