

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 4 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

66

$\frac{1}{4}$ Section Corner to Sections 7 and 18.
Found - Both Orig. BT's. Each is bark scribed " $\frac{1}{4}$ " and each checks bearing & distance.
Find $1\frac{1}{4}$ " I. P. at corner and fences thus:

New BT: 7" R. Fir bears S. 42° E. 25.9 ft. scribed $\frac{1}{4}$ S18 CS BT.
Rescribe, now 36" R. Fir N. 65° E. 20.5 ft., $\frac{1}{4}$ S 7 CSBT - Note new scribing low near base of Bearing Tree.

67

S. E. Corner D. L. C. 37.
Found - Orig. 10", now 28" W. Oak N. 15° W. 94.4 ft. We open & find Frear's scribing "T".
We do not find $\frac{3}{4}$ " I. P. set by Frear. REN #4
Note - Fence Corner thus:

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961
S. E. Cor. DLC 37 T28S R4W.
New BT's: 12" W. Oak bears N. 41° W. 76.4 ft. scribed SE DLC 37 CS BT.
10" W. Oak bears N. 65° W. 80.9 ft. scribed SE DLC 37 CS BT.

68

Renewed Closing Corner.
Found - Both Orig. BT's. Orig. 60", now 66" Fir S. 80° E. 19.8 ft., shows good old bark scribing "B 8". Orig. 40", now 44" Fir S. 85° W. (Not S. 65° W) 15.8 ft., shows old bark scribing "S T".
Set - Brass Cap at Corner Mkd: CC S36 | T27S
R4W S1/S6 T28S R3W
New BT's: 15" Cedar bears S. 67° E. 23.8 ft. scribed S6T28S R3W CS BT.
6" R. Fir bears S. 56° W. 33.6 ft. scribed S1 CS BT.
Note - See Sketch in file for location of corners. - e. s. #9/30

69

$\frac{1}{4}$ Corner to Sections 3 and 2.
Found - Orig. 24", now 36" Fir, down, N. 89° W. 13.2 ft. We open & #116 find good scribe marks. Orig. 40", now 40" Fir Stump S. 88° E. 21.8 ft., shows good bark scribing, not old.
Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1961
 $\frac{1}{4}$ S3/S2 T28S R4W
New BT's: 7" Cedar bears S. 76° W. 9.2 ft. scribed $\frac{1}{4}$ S3 CS BT.
10" Cedar bears N. 37° E. 17.6 ft. scribed $\frac{1}{4}$ S2 CS BT.

70

$\frac{1}{4}$ Corner to Sections 12 and 13.
Found - Orig. 16", now 30" Fir Stump N. 80° W. 13.2 ft. Orig. SW BT, now shell of snag. We also find BBI, now 26" Cedar S. 69° W. REN #20 56.8 ft., previously opened, shows good scribing " $\frac{1}{4}$ S13 CS".
We do not find BBI NW BT.
Set - Brass Cap at Corner & at East Edge of 30" Fir Log Mkd: County Surveyor's Office, 1961 $\frac{1}{4}$ S12 T28S R4W
S13
New BT: 12" Ewood bears N. $82\frac{1}{2}^{\circ}$ W. 20.3 ft. scribed $\frac{1}{4}$ S12 CS BT.

71

Renewed Closing Corner.
Found - Both Orig. BT's. Each Tree is in good condition, each shows good scribing and each checks record.
Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1961 CC S6 T28S R3W
R4W S7
No New BT's. Note - Corner is under 30" Log.

James W. Byron, Deputy
Milo Godfrey
July 6, 1961
C. S. File No. 49/67

James W. Byron, Deputy
Milo Godfrey
Clete Putnam
July 21, 1961
C. S. File No. 49/67