

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 5 R. W. W. M.

Ben B. Irving D. C. S. A Boyer
N. E. Richardson
Nov. 20, 1937

J. E. Pinkerton
R. L. Irving
Geo. Piper
July 5, 1939

Ben B. Irving Co. Sur.
Wit. Bowman
Carey
French
Thomas
March 1946 - C.S. File 38/42

Percy Armstrong
Surveyor
Lowell Russell
Witness
August 1947

CORNER SECTIONS BETWEEN 5 and 6.

Found original B.T.s in good shape. Marked B.T. on bark. Drove 3/4" x 36" round Iron Bolt for corner, from which
36" FIR bears S. 65° 30' E., 56 lks. Original B.T.
16" FIR bears S. 1° W., 16 lks. Original B.T.

12

SECTION CORNER BETWEEN SECTIONS 15 and 22.

Location identified from an old stake from which a laurel formally was N. 72° E., 40 lks., now has two large laurels which has stooled out from the original tree and a White Oak 30" dia. bears S. 12° W., 37 lks. with blazes plain. Set a post for the corner from which
An Oak 8" dia. bears S. 45° W., 38.6 ft.
An Oak 9" dia. bears N. 68° E., 77.8 ft.

13

CORNER BETWEEN 17 and 20.

Set corner by double proportional measurement. Set
1 1/2" x 42" Pipe 36" in ground and marked
An Oak 8" dia. N. 30° E., 96.5 ft.
An Oak 54" dia. S. 64° E., 92.2 ft.

14

SECTION CORNER BETWEEN 16, 17, 20 and 21.

Reset from one Original Bearing Tree S. 12° W. 1 lks. Chopped etc. Scribe marks gone but found part of one. Stamp and roots of other B.T.s check original. Set Rock and marked
A Fir 12" dia. bears N. 42 1/2° W., 17.2 ft.
Madronna 6" dia. bears N. 53 1/2° E., 26.5 ft.
A Fir 10" dia. bears S. 74° E., 78.9 ft.
A Fir 7" dia. bears S. 25 1/2° W., 19.6 ft.

15

CORNER BETWEEN 16 and 17

Set corner by proportional measurement. Set in Car Drive Shaft 4 ft. long for corner from which,
Oak 12" S. 2° W., 138.2 ft.
Oak 12" S. 32° E., 61.3 ft.

16

SECTION CORNER BETWEEN 8, 9, 16, and 17.

Renewed corner by double proportional measurement. Set in Iron Pipe. Marked
A 8" Forked Oak N. 86° E., 33.2 ft.
No other trees available in near vicinity.

17

CORNER BETWEEN 9 and 16.

Identified from "Y" Oak N. 52° E., 1 lks. chopped out but scribe marks legible. Original B.T. a White Oak S. 60 1/2° E., 56 lks. in place in good shape and not chopped out but remarked.
New B.T.
An Oak 10" N. 70° E., 29.2 ft. marked 1/2 S. 9 C.S.B.T.
Set in 3/4" x 36" Drill steel with post alongside.

18

CORNER BETWEEN SECTIONS 8 and 9.

Location identified by one O.B.T. a Y. Oak N. 19° W., 161 lks. chopped out and properly scribed. Marked
A 14" Black Oak N. 63° W., 49.6 ft. marked 1/2 S. 8 1/2 T.
A 10" Black Oak S. 77° E., 4.2 ft. marked 1/2 S. 9 1/2 T.

19

COR. BETWEEN 11 & 14.

Find old oak stump S 3° 30' W 25.1 ft., remains of original B. T. with "B. T." remaining in shell. Find only depression in ground and rotted fiber at location for other B. T.
Blaze a 8" W. O. N 10° 00' W 27.6 ft. Blaze South side of fir tree S 89° 59' E 62.2 ft., drive 1 1/2" x 36" pipe to renew corner. Chased away by hornets before bearing trees could be scribed.

20

SEE CORNER NO. 54