

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 5W R. W. W. M.

ROSE-CHAPMAN CO., EUGENE, ORE. 97198

1/4 COR. BET. 28 and 33

I renewed this corner from the original B.T.s which were alive and standing scribe marks were visible on one which I chopped open the other tree was identified by its bearing and scars.
Set an iron plow share and a 4 x 4 x 40 Oak post for corner.

135A

39

161.3

J. W. Cole - DCS
Witnesses - Smick, Stone
Jennings
March, 192M

Sec. Cor. Secs. 35 & 36, T 28 S, R 5 W and Sec. 1 & 2, T 29 S, R 5 W 40

I renewed this corner from two O.B.T.s which were alive and standing with scribe mark chopped out and visible. Other trees gone.
Set Rock 6" x 6" x 14" for corner. Marked new trees as follows.

Fir 10" in dia. bears N 45° E 40 lks.

Fir 10" in dia. bears S 65° E 26 lks.

Fir 8" in dia. bears S 35° W 16 lks.

Fir 10" in dia. bears N 29° W 21 lks.

CORNER NO. 47

Sec. Cor. 21 - 22 - 28 - 27

Renewed from B.T.s in Secs. 21 - 22 - 28. Set 1" I. Pipe and marked one new B.T.

18" Maple on North side of creek which bears from corner
S 9° E 183.5 ft.

1/4 Cor. 21 - 28

Both B.T.'s (orig.) entirely destroyed. Found scribed oak post still in ground at fence corner from which new B.T.s bear

N 40° E 17.5 ft. a 12" W. Oak

S 50 1/2° W 49 ft. a 12" W. Oak

CORNER NO. 64

1/4 SEC. COR. 1 and 12

Set 5/8" x 30" Galv. Bolt 2 ins. out of ground

Did not mark new B.T.s

Orig. 14" Oak (now 36") in excellent condition, did not open blaze.

Orig. 12" Oak (now 30") rotting from previous opening of blaze.

S 37 1/4° E 152 lks.

CORNER NO. 46

1/4 section corner to secs. 13 & 14. Determined by old B.T.s.

A 36" Fir bears N.10W., 22.0', I remarked this O. B. T.

A 15" Cedar bears S.31E., 27.0', I found old scribe.

At corner point set 1" x 66" I.P. with steel plate on top mkd. 1/4 S 13/14.

From which

A 38" La. bears S.70W, 130.0' dist. mkd. 1/4 S 14, T28S, R5W., B.T.

A 26" La. bears N.56W, 50.0' dist. mkd. 1/4 S, B.T.

A 3 way fence corner bears North 130.0' with fences running approx. N-E-W.

Top of ridge bears West, 130.0'.

Most Northerly Northeast corner of D. L. C. No. 41.

Found both B. T.s set by Charlie Roberts in good condition. Stub of one original B. T. found but too badly rotted and burned out-no scribe marks.

Iron rod set by Roberts not found.

Set 1/2 inch x 48 inch iron pipe for corner.

Did not mark any new B. T.s since trees marked by Roberts were still good.

1/4 corner to secs. 1 and 12.

Found 1 inch Galv. iron belt at fence corner. N. E. orig. BT. in good condition. S. E. orig. BT. center rotted, some scribing visible.

Blazed and scribed a 14 inch Red Fir, S.37°E., 50 feet 1/4 S 12 CS BT.

H.L. Epstein D.C.S.
Witnesses - Wolford, Ashcraft
2/21/21

A. Boyer - D.C.S.
Witnesses - Homer Vogt
Frank Stanciliff
Jan. 3, 1949

T. R. Eslinger
Land Surveyor
Feb. 27, 1951

John H. Markham Jr.
For Stomar Lbr. Co.
Sept., 22, 1953
C. S. File 41/192

E. S. Woodford
Nov., 1955.
C. S. File 42/115.

James W. Byren
Mar. 24, 1955
C. S. File No. 46/111

see 49/299
REN # 43

REN # 32

53