

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE., 21881

James W. Byren, Deputy County Surveyor
April - May, 1957.
C. S. File No. 47/180.

Section corner to secs. 35 & 36, T28S, R5W., and secs. 1 & 2, T29S, R5W.
Found - All of Coles ^{REN} BTs. The N. E. BT is a stump only & rotted face
well scribed. All other BTs down & rotted but some scribing visible.
All BTs check for bearing & distance.

Set an iron pipe with brass cap at corner mkd. $\frac{35}{2} | \frac{36}{1} \frac{T28S}{T29S}$ R5W
Surveyor's Office, 1957.

Blaze and scribe:

- 4 inch Laurel, S.82°W., 57.4 feet, mkd. S 2 CS BT.
- 5 1/4 inch R. Fir, S.24°E., 72.2 feet, mkd. S 1 T29S R5W CS BT.
- 4 inch R. Fir, N.18 1/2°W., 22.0 feet mkd. S 35 CS BT.
- 4 inch Laurel, N.46°E., 25.1 feet, mkd. S 36 CS BT.

47
Fd. by:
Wm. Ruppert
Sur. Mar. '53
M 93-68

Township corner to secs. 31, 36, 1 and 6, Tps. 28 & 29, Rgs. 4 & 5 W.
Found 3 original BTs. I open NE BT and find good scribing. The NW
BT gone-stump hole only. I do not open SW or SE BTs-show old blazes and
all check for bearings and distances.

Note: Corner 10 feet west of N-S fence.
Set an iron pipe with brass cap mkd. $\frac{36}{1} | \frac{31}{6} \frac{T28S}{T29S}$ R5W R4W
County Surveyors Office,
1957.

Blaze and scribe new trees:

- 20 inch R. Fir, N.82°W., 10.8 feet, mkd. T28S R5W S36 CS BT.
- 12 inch R. Fir, S.46°W., 54.2 feet, mkd. T29S R5W S1 CS BT.
- 12 inch R. Fir, S.54°E., 50.4 feet, mkd. T29S R4W S6 CS BT.
- Reblaze and rescribe orig. 16 inch B. O. (now 24 inches), N.31°E.,
25.1 feet, mkd. T28S R4W S 31 CS BT.

48
Fd. by:
Wm. Ruppert
Sur. Mar. '53
M 93-68

1/4 Section Corner to Sections 1 & 2. - By Proportional measurement -
Set Brass Cap at corner marked 1/4 S2/S1 T28S. R5W. County Surveyor's
Office, 1957.

- N. W. Corner Brick House bears S.40°15'W. 57.4 ft. F.D.O.K. PER BENTL
- N. E. Corner of House bears S.21°E. 47.1 ft. M109-11 OCT 1989
- Found boat spike set by County Road Engineers for road
intersection bears N.0°30'W. 31.9 ft.
- No suitable trees near for Bearing Trees.

Section Corner to Section 1, 2, 11, & 12.

Set Brass Cap by double proportion measurement marked $\frac{S 2 | S 1}{S11 | S12} \frac{T28S R5W Co.}{Sur. Off., 1957}$

- Scribed an 18" Ash which bears N.14°W. 61.0 ft. S2 T28S R5W CS BT.
- A 6" Well with electric motor & pump bears S.33°E. 86.1 ft.
- S. W. Corner of Brick Chimney bears N.84 1/2°E. 324.4 ft.
- Maple bears S.60 1/2°W. 453.0 ft. scribed S11 T28S R5W CS BT.

Section Corner to Sections 1, & 12, T28S. R5W., Secs. 6 & 7 T28S. R4W.

Found - Orig. 18" now 30" B.O. S.38°W. 13.2 ft. now down & partly rotted.
I open & find reverse scribing "BT". Also find stump holes for
N. E. & N.W. orig. BTs. Fence corner bears S.59°W. 6.0 ft.
Set Brass Cap at corner marked $\frac{S 1 | S 6}{S12 | S 7} \frac{T28S R4W}{R5W}$ County Surveyor's
Office, 1957

- New BTs: 18" B.O. Bears S.77°E. 27.1 ft. scribed S7 T28S R4W CS BT.
- 16" Laurel bears N.66 1/2°W. 82.1 ft. scribed S1 T28S R5W CS BT.
- 18" Laurel bears N.13°E. 87.8 ft. scribed S6 T28S R4W CS BT.
- No trees near in S. W. Quad.

Section Corner to Secs. 12 & 13 R5W. & 7 & 18 R4W.

Found - Wire Fence corner, fence to North & fence to East.
48" Fir Stump S.33°E. 44.2 ft. (record dist. & bearing). Shows
real old axe marks. Set Brass Cap at Side of 1/2" I. Rod.
All other orig. BTs. gone. R5W S12 | S7 R4W T28S County
Find 1/2" Iron Rod at fence corner. S13 | S18 Surveyor's Office
Note: Statement by Wm. Melton in file. 1957.

- New BES: 14" Myrtle bears S.11°W. 46.7 ft. scribed S13 T28S R5W.
- 6" R. Fir bears N.84 1/2°W. 138.8 ft. scribed S12 T28S R5W. CS BT.

James W. Byron, Deputy County Surveyor
M. Godfrey
B. Bilow
For Office Records
November, 1957
C. S. File No. 49/21

RECORDED & INDEXED
NO. 137

69 52