

Douglas County Surveyor's Record of  
Government Corners Renewed

28 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE., 21891

Renew N. E. Corner D.L.C. 41, T28S. R5W.  
Found - Both BTs as renewed 1916.

53

N. W. BT. open shows scribe marks "C".

N. E. BT. shows good face, I do not open. BTs check for bearing & distance & both are alive & in good condition.

I cannot find  $\frac{3}{4}$ " I. Bar set in 1916. <sup>REN #45</sup> I find  $\frac{1}{2}$ " I.P. set by Woodford, 1955, bears North 1.0 ft. from corner. REN #45

Also find badly rotted base & stump of orig. S.W. BT., No scribe marks found. Checks bearing & distance to corner.

Set Brass Cap at corner marked N.E. Corner D.L.C. 41 T28S R5W County Surveyor's Office, 1957.

No New Bearing Trees set.

$\frac{1}{4}$  Section Corner to Sections 11 & 14.

54

Found  $1\frac{1}{4}$ " I. P. Set by Armstrong, 1947. Also I find Both BTs. blazed

by Armstrong: 12" W.O. N.17°W. 27.6 ft. scribed  $\frac{1}{4}$  S11 CS BT. REN #20  
24" Fir East 61.0 ft. scribed  $\frac{1}{4}$  S14 CS BT.

Corner under East West Fence.

Section Corner to Sections 14, 15, 22, & 23.

55

Found - Stone & All BTs. set by B.B.I., 1938. BTs. are stumps only now.

I open S.E. & S.W. BTs. & found good scribing. REN #10

Set Brass Cap alongside of corner stone marked S15/S14 T28S R5W  
County Surveyor's Office, 1957. S22/S23

New BTs: 10" R.Fir N.2 $\frac{1}{2}$ °W. 65.4 ft. scribed S15 T28S R5W CS BT.

14" R.Fir S.45°W. 18.5 ft. scribed S22 T28S R5W CS BT.

10" R.Fir N.40°E. 31.5 ft. scribed S14 T28S R5W CS BT.

16" R.Fir S84°E. 27.6 ft. scribed S23 T28S R5W CS BT.

Set Wit. Corner for  $\frac{1}{4}$  Corner Sec. 12, R5W, & Sec. 7, R4W.

56

No original BTs found.

Position of  $\frac{1}{4}$  Corner fixed by survey Section 12, See C.S. File No. 49/21

$\frac{1}{4}$  Corner falls in small stream.

Set Brass Cap 10.0 ft. North, Marked S12/S7 T28S County Surveyor's Office,  
1957, Wit. Cor. 10' S. to  $\frac{1}{4}$  Corner

New BTs: 15" Maple bears N.62 $\frac{1}{2}$ °W. 30.5 ft. scribed WC  $\frac{1}{4}$  S12 CS BT.

5" W.Oak bears S.30° E. 48.0 ft. scribed WC CS BT.

Section Corner to Sections 11, 12, 14, & 13.

57

No. Original BTs. found - Position of Section Corner determined by

Calls. Survey of Section 12 & Tie to  $\frac{1}{4}$  Corner 11 & 14, See C.S. File 46/111

Set Brass Cap at fence corner & mkd. S11/S12 T28S R5W County Surveyor's  
Office, 1957. S14/S13

New BTs: 14" W.O. bears West 39.6 ft. scribed T28S R5W S14 CS BT.

9" W.O. bears N.40°W. 58.6 ft. " T28S R5W S11 CS BT.

6" Apple bears N.85 $\frac{1}{2}$ °E. 7.7 ft. " T28S R5W S12 CS BT.

16" W.O. bears S.27 $\frac{1}{2}$ °E. 290.4 ft. " T28S R5W S13 CS BT.

FD. OK. 2-28-80

$\frac{1}{4}$  Section Corner to Sections 12 & 13.

58

No Original Bearing Trees Found.

Position of  $\frac{1}{4}$  Corner determined by survey Sec. 12 T28S R5W. See 49/21 file

Set Brass Cap at Corner marked  $\frac{1}{4}$  S12 T28S R5W County Surveyor's  
Office, 1957. S13

New BTs: 18" B.O. bears N.81°W. 171.5 ft. scribed  $\frac{1}{4}$  S12 CS BT.

11" R.Fir bears S.5°E. 43.7 ft. scribed  $\frac{1}{4}$  S13 CS BT.

$\frac{1}{4}$  Section Corner to Section 11 & 12.

59

No original BTs. found.

See C.S. File for method used to determine position of this Corner.

Set Brass Cap at corner marked  $\frac{1}{4}$  S11/S12 T28S R5W Co. Surv. Office, 1957.

New BTs: 12" W.O. bears S.75°W. 162.0 ft. scribed  $\frac{1}{4}$  S11 CS BT.

20" Cherry bears S81 $\frac{1}{2}$ °E. 490.2 ft. scribed  $\frac{1}{4}$  S12 CS BT.

James W. Byron, Deputy County Surveyor  
M. Godfrey  
S. Hilow  
For Office Records  
Nov. 1957  
C. S. File No. 49/21

128