

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97120

(continued)

At Corner Set Iron Pipe with Brass Cap stamped "S20|S21 T28S R5W
County Surveyor's Office, 1958. S29|S28
Bark Scribe 35" Doug. Fir S.81°W. 67.5 ft. "T28S R5W S29 CS BT".
Blaze & Scribe 16" Doug. Fir N.48½°E. 103.9 ft. "T28S R5W S21 CS BT".
Blze & Scribe 13" Doug. Fir S.60°E. 104.4 ft. "T28S R5W S28 CS BT."

Section Corner to Sections 19 & 30, T28S R5W, & Secs. 24 & 25, T28S, T6W. **63**
Found - 3 Orig. BTs. check record bearing & distances. I open orig. N.W.
BT. & find good scribing "S 24 T28".

Other orig. BTs. show old scars. I do not open. The N.E. BT.
now 20". The N. W. BT. now 18". The Laurel S.25°E., now 48".
I also find 14" B. O. S.60°W. 19.5 ft. (Record S.20°W.19.1 ft.)
shows old scar. I believe it is the Orig. S. W. BT.

Set Brass Cap at Corner marked: R6W S24|S19 R5W T28S, County Surveyor's
Office, 1958. S25|S30

New Bearing Trees: 16" B.O. N.40°W. 43.5 ft. scribed S24 T28S R6W CS BT.
Rescribe 48" La. S.25°E. 5.9 ft. scribed S30 T28S R5W CS BT.
Rescribe 14" B. O.S.60°W. 19.5 ft. S25 T28S R6W CS BT.

¼ Section Corner to Section 21 & 28. **64**

Found - Both BT's. as scribed by Boyer, 1949. Open faces, good
scribing. Boyer's bearings & distances do not check. REN.#42
I find thus:

Now 13" W. O. (Record S.50½°W. 49.10 ft.) S.50½°W. 17.5 ft.
Now 13" W. O. (Record N.40°E. 17.5 ft.) N.34½°E. 49.0 ft.

Set Brass Cap at Fence Corner marked: County Surveyor's Office, 1958.
Boyer's BTs. alive & in good condition. I do not scribed N.E. Trees.

James W. Byron, Deputy County Surveyor
M. Godfrey
S. Blilow
Feb., 1958
C. S. File No. 49/64

Fd. OK
4/91-BAKER
M113-32

Section Corner to Sections 15, 16, 21, & 22. **65**

Found - 2" Iron Pipe or Shaft at Corner and under old E.W. fence.
Orig. 10", now 20" W. Oak partly rotted stump N.89½°W. REN.#29
304.9 ft. Good scribing visible "S BT".

No other BT's. found.

Note - Evidence of old Fence to South from Corner Pipe.

I do not Set Brass Cap at Corner.

New BT's: 7" W. O. bears N.63½°E. 46.9 ft. scribed S15 T28S R5W CS BT.
14" W. O. bears N.77° W.119.2 ft. scribed S16 T28S R5W CS BT.
12" R.Fir bears S.81°W. 174.1 ft. scribed S21 T28S R5W CS BT.
No trees near to S. E.

¼ Section Corner to Sections 15 & 22. **66**

Found - Scribed Post out of ground near Corner. REN.#13
Both Original BT's. & BT's as recorded by B.B.I., 1939.
Original 10", now 24" W. Oak shows good scar., I do not
open.

Original 30", now 48" Laurel, center rotted.
B.B.I. 8", now 12" W. Oak down, scribing visible S.45°W. 38.6"
9" W.Oak, now 12" N.68°E. 77.8 ft., shows good scar, I do
not open.

Set Brass Cap at Corner Mkd: ¼ S15 T28S R5W County Surveyor's
Office, 1958 S22

New BT's: 8" R.Fir bears N.49°W. 15.0 ft. scribed ¼ S15 CS BT.
7" W.Oak bears S.30°W. 42.2 ft. scribed ¼ S22 CS BT.

¼ Section Corner to Sections 22 & 23. **67**

Found - 10"x 14"x 20" Stone, marked as recorded. I find stone out
of place, down hill & south of True Corner. This section in
slide area. REN.#9

Now 40" Fir Stump S.60°W. 23.1 ft. shows good bark scribe "22".
Now 30" Laurel N.56°E. 21.1 ft., should be N.50°E. 21.1 ft.

See. B.B.I. renewal. I do not open.

Reset Stone at Corner. (Checks Call to Small Creek)

North South Fence 20 ft. East - Reset Stone to True Position.

NEW BT's: 9" R. Fir bears N.24°E. 18.9 ft. scribed ¼ S23 CS BT.
7" R.Fir bears N.80°W. 54.5 ft. scribed ¼ S22 CS BT.

James W. Byron, Deputy
M. Godfrey
S. Blilow
June 6, 1958
C. S. File No. 49/64

James W. Byron, Deputy
Milo Godfrey
S. A. Blilow
April 7, 1959
C.S. File No. 49/64

Fd. OK D. BENTZ 5/92
1992-0046

Fd. OK D. BENTZ 5/92
1992-0046

Fd. B.C. 8/30
M 110-57