

Douglas County Surveyor's Record of  
Government Corners Renewed

28 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

SEE C. S.  
File  
No. 15/  
28B

N. W. Township Corner of T. 28 S. R. 5W.  
Township Corner between 1 and 6 was set from Old BT's.  
A 3" round Iron Bolt 30" in ground. **SEE CORNER NO. 68**  
New BT's: B.Oak 18" bears S.62°15'E. 152.6 ft.  
B.Oak 14" bears S.86°20'W. 226.6 ft.

11-A

SEE BELOW

N. W. Township Corner to T. 28 S., R. 5 W.  
Found - Both Orig. BT's. as follows:  
14" W.Oak, now 18", nearly dead, S.57½°E. 414.5 ft. Had  
been previously opened - scribe marks (B.T.) plainly visible.  
12" G.Oak, 21" B.Oak Snag, 275.9 ft. Previously opened & face  
rotted, opened tree above old chopping, fd. fragmentary  
but unmistakable reverse scribing. **SEE ALSO 11A ABOVE**  
At Corner Set Iron Pipe with Brass Cap Mkd: County Surveyor's Office, 1961  
T27S  
R6W S1/S6 R5W T28S  
New BT's: 18" W.Oak S.58°E. 209.8 ft. mkd: T28S R5W S 6 CS BT.  
Crocker's S.W. BT, actually N.W. of Crocker's Corner, bears  
S.57½°W. 151.8 ft., shows good scars. Did not rescribe.  
Crocker's Iron Bolt bears S.67½°E. 76 ft. from true corner.

68

**RE-RENEWED, SEE CORNER NO. 154**

Sec. Cor. Secs. 12 & 13, T28-5W. & Secs. 7 & 18, T28-4W.  
Found - Brass Cap at Corner and N. W. BT. **REV 52** S.W. BT. gone. **136**  
at location by S.W. BT. This area cut up by new Cat Road.  
New BT: 10" R.Fir bears S.56½°W. 135.7 ft. scribed T28S R5W S13 CS BT.  
March 7, 1961

69

¼ Section Corner to Sections 17 and 16.  
Found - Drive Shaft Set by Irving in 1945. **REN #16**  
B. Oak, now 18", S. 2°W. **#1** 138.2 ft., shows good scars,  
did not open.  
Other BT. marked by Irving gone, No trace found.  
I blaze & scribe 6" Ash N.83°E. 18.5 ft. Mkd: ¼ S16 CS BT. M. Godfrey  
July 28, 1961

70

Sec. Cor. to Secs. 25 & 36, T28-5 and Secs. 30 & 31, T28-4.  
Found = Orig. 9", now 30" Fir Stump S.70°W. 13.2 ft. We open & find  
good scribing "S3".  
Stump Section that checks record S.E. BT. Orig. N.W. & N.E. BT's.  
not found.  
Set - Brass Cap at Corner Mkd: County Surveyor's  
Office, 1961  
R5W S25 | S30 R4W  
S36 | S31 T28S  
New BT's: 21" R.Fir bears N.37°W. 12.0 ft. scribed S25 T28S R5W CS BT.  
24" R.Fir bears N.17½°E. 49.7 ft. scribed S30 T28S R4W CS BT.  
18" Laurel bears S.17°W. 43.4 ft. scribed S36 T28S R5W CS BT.  
No trees near to S. E.

71

Fd. by Wm. Ruppert  
See Mar. 58  
M 23-68

Sec. Cor. Secs. 24 - 25, T28-5 & Secs. 19 & 30, T28-4.  
Found - Orig. 18", now down & mostly rotted Pine. We find goodscribing  
"19 SR4W" on old section, BT. bears N.88°E. 39.6 ft.  
Orig. S.E. BT. down. No trace of N. W. or S.W. BT's.  
Find 1½" I. P. 2 ft. North of Corner. N.S. Wire Fence is West of Cor.  
Set - Brass Cap at Corner Mkd: County Surveyor's  
Office, 1961  
R5W S24 | S19 R4W  
S25 | S30 T28S  
New BT's: 16" Cedar bears S.24°E. 10.5 ft. scribed S30 T28S R4W CS BT.  
10" Pine bears N.54°E. 6.7 ft. scribed S19 T28S R4W CS BT.  
11" Cedar bears S.14°W. 11.2 ft. scribed S25 T28S R5W CS BT.  
10" Pine bears N.45°W. 22.7 ft. scribed S24 T28S R5W CS BT.

72

72-A

North Line Sec. 6, T28-5W. - Renew South ¼ Cor. Section 31, T27-5W.  
Found - 3" Iron Bolt at corner. N.W. BT. shows good scars. I do not open.  
The N.E. BT., now dead, 18" Fir. We open & find good scribing.  
New BT: 8" W.Oak bears N.38°E. 16.2 ft. scribed S ¼ S31 CS BT.

C. S. File No. 49/64  
November 14, 1961

James W. Byron, Deputy  
Milot Godfrey  
Clete Putnam  
Jan. 24, 1961  
C.S. File No. 49/64

James W. Byron, Deputy  
Dale McFarland  
J. Powell  
August 28, 1961  
C. S. File No. 49/67

FD. OK 12/90  
M 111-23